Official Transcript of Proceedings

NUCLEAR REGULATORY COMMISSION

Title: Advisory Committee on Reactor Safeguards

Plant License Renewal Subcommitee Prairie Island Nuclear Generating Station

Docket Number: (n/a)

Location: Rockville, Maryland

Date: Tuesday, July 7, 2009

Work Order No.: NRC-2945 Pages 1-138

NEAL R. GROSS AND CO., INC. Court Reporters and Transcribers 1323 Rhode Island Avenue, N.W. Washington, D.C. 20005 (202) 234-4433

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION ADVISORY COMMITTEE ON REACTOR SAFEGUARDS SUBCOMMITTEE ON THE PLANT LICENSE RENEWAL FOR THE PRAIRIE ISLAND NUCLEAR GENERATING STATION 8 9 TUESDAY, JULY 7, 2009 10 + + + + + 11 ROCKVILLE, MD 12 The Subcommittee convened in Room T2B3 in the Headquarters of the Nuclear Regulatory Commission, Two 13 White Flint North, 11545 Rockville Pike, Rockville, 14 Maryland, at 8:30 a.m., Harold Ray, Chair, presiding. 15 16 SUBCOMMITTEE MEMBERS PRESENT: 17 HAROLD RAY, Chair MARIO V. BONACA 18 19 SAID ABDEL-KHALIK 20 WILLIAM J. SHACK 21 JOHN D. SIEBER 22 J. SAM ARMIJO 23 DANA A. POWERS 24 OTTO L. MAYNARD 25 JOHN T. STETKAR

NEAL R. GROSS

TOM DOWNING

MATTHEW McCONNELL

3

6

/

O

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

NEAL R. GROSS

TABLE OF CONTENTS

Introductions.....5

Applicant Presentation.....9

NRC Presentation.....85

Subcommittee Discussion.....129

COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

P-R-O-C-E-E-D-I-N-G-S

INTRODUCTIONS

CHAIRMAN RAY: The meeting will now come to order. This is a meeting of the plant license renewal sub-committee. I'm Harold Ray, chairman of the Prairie Island Plant License Renewal Subcommittee.

ACRS members in attendance are Mario Bonaca, William Shack, Sam Armijo, Dana Powers, Otto Maynard, John Stetkar, Jack Sieber, Said Abdel-Khalik, and our consultant, John Barton. I expect that member Mike Ryan will join us during the course of the meeting.

The purpose of this meeting is to review the application for the Prairie Island Plant License Renewal, the Draft Safety Evaluation Report, and associated documents. We will hear presentations from the representatives of the Office of Nuclear Reactor Regulation and the applicant, Northern States Power, a Minnesota corporation.

The sub-committee will gather information, analyze relevant issues and facts, and

NEAL R. GROSS

formulate proposed position and action as appropriate for deliberation by the full committee.

The rules for participation in today's meeting were announced as part of the notice of the meeting, previously published in the Federal Register on June 16, 2009. We have not received any requests from members of the public wishing to make oral statements.

A transcript of the meeting is being kept and will be made available as stated in the Federal Register notice, therefore we request that participants in this meeting use the microphones located throughout the meeting room when addressing the sub-committee. Participants should first identify themselves and speak with sufficient clarity and volume so that they can be readily heard.

Somewhere I overlooked the fact that our designated federal official is Mr. Brown, Christopher Brown.

We will now proceed with the meeting and I'll call on Brian Holian of the Office of Nuclear Reactor Regulation to introduce the presenters.

Brian?

MR. HOLIAN: Thank you. Good morning. My name is Brian Holian. I'm director of the Division of

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

License Renewal. To my right is Dr. Sam Lee, deputy director of the Division of License Renewal, and to his right is Mr. Rick Plasse, the project manager for the Prairie Island review.

We have several other branch chiefs from both technical divisions and license renewal in the audience and we'll hear probably from some of those later during the NRC presentation. We would like to highlight two of the staff or one staff and one contractor that's also with us today.

First is Dr. Stu Sheldon, who is the senior rafter inspector from region 3. You'll be hearing from him on inspection results and he's right here in the first row.

Secondly, we have a contractor here from Oak Ridge. That's Dr. Naus. He helped the staff with a site visit and part of our review on some of the containment structural issues at Prairie Island.

Just a couple other opening items on the Prairie Island review. One, the staff does have three open items that you'll be hearing in part of the presentation today. Progress is being made on all the open items.

One was a scoping issue related to the waste gas decay tank. The second item where the staff

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

still -- was more of a timing issue. We still needed to just review the PWR vessel internals program that they submitted, so that's why that's open.

The third item was some leakage and water seepage from a refueling cavity. That's been an item, I think, yes, the committee has heard from on Indian Point a few months back and is an item we're paying particular attention to on some of the plants that have had some historical leakage.

The only other item I'd like to mention really has two parts, and that's just to note that Prairie Island is a hearing plant. They are on a hearing schedule.

There were originally seven contentions that were admitted. Five of those have been closed. There were four safety contentions and one environmental contention that have been closed through the ASLB process. There's just two contentions remaining and they're both on the environmental side of the house, environmental review.

The last item I'd like to recognize is that on Prairie Island, we did have a unique memorandum of understanding that we established with the Prairie Island Indian community and in

NEAL R. GROSS

particular, to get their input on environmental 2 issues surrounding the plant. So that's been working well and we've been working with Prairie Island, both on the inspection and on the review. With that, I'll turn it over to the site vice-president, Mr. Mike Wadley. 8 CHAIRMAN RAY: Mike, before you begin, I also failed to introduce our consultant to the subcommittee, Mr. John Barton. Please proceed. 10 11 MR. WADLEY: Thank you, Chair. Gene, I was 12 going to lead us through the introductions here. 13 MR. ECKHOLT: Yes. My name is Gene Eckholt. I'm the project manager for the Prairie 14 15 Island License Renewal Project. 16 I want to thank the committee for the 17 opportunity to discuss license renewal at Prairie 18 Island and run through some introductions. 19 At the front table, we've got Mike 20 Wadley, the site vice-president and we've got Steve 21 Skoyen, our engineering program manager. 22 We've also got a number of license 23 renewal project team members and subject matter experts with us today. 24

At the side table are my four engineering

supervisor leads for the project. Phil Lindberg, the programs lead. Scott Marty, the mechanical lead, Richard Pearson, the civil structural lead, and Joe Ruether, the electrical lead.

We also have Scott McCall, the plant system engineering manager and from the projects organization, we have Charlie Bomberger, the vice president of nuclear projects and Ken Albrecht, the general manager of major nuclear projects.

Sticking to the agenda, we'll start with some background information on the plant -- the operating history, brief information on the plant, major improvements. We'll talk some on the license renewal project and the methodology we used in developing the licensure application.

We'll talk briefly about implementation of license renewal at Prairie Island and the status of that. Then we will talk on specific items of technical interest, in particular, the three open items in the SER.

At this point, I'd like to turn it over to Mike Wadley.

APPLICANT PRESENTATION

MR. WADLEY: Thanks, Gene. Chair, committee members, good morning.

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

NSP, Northern States Power - Minnesota is a wholly owned subsidiary of Xcel Energy and is the owner and operator of the Prairie Island Nuclear Generating Plant.

The plant is located on the Mississippi River southeast of Minneapolis and Saint Paul.

Prairie Island is a two-loop Westinghouse pressurized water reactor with a thermal output of 1600 megawatts and a gross electrical production of 575 megawatts electrical.

Pioneer Service and Engineering was the plant's architect engineer. Prairie Island has a dual containment consisting of a steel containment surrounded by a limited leakage concrete shield building separated by a five foot annular space.

The ultimate heat sink for the units is the Mississippi River via our clean water system. The plant's steam cycle cooling is once-through cooling supplemented by forced draft cooling towers, which are used on a seasonal basis to support effluent discharge per metric requirements.

Construction permits were issued in June of 1968 and operating licenses were later. One was issued in August of `73 and unit two in October of 1974. We submitted our license renewal application in

NEAL R. GROSS

April of 2008.

3

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Both units completed their 25th refueling outage in 2008. Both units operate on an 18-20 month cycle. Lifetime capacity factors for the station are 84.2 and 86.5 for units 1 and 2, respectively.

Current cycle capacity factors are 96.6 and 98. Refueling outages are scheduled for unit 1 this fall and next spring, for unit 2.

Some major improvements have taken place at the station since it began operation. In 1983, we constructed a new intake screen house and reconfigured our intake and discharge canals. That allowed us to go to seasonal operation with our cooling towers.

In 1986 and 87, we replaced the reactor vessel and internals as our response to the splitpin issues the industry had experienced.

In 1993, we added two new diesel generators on unit 2 and were able to separate the safety-related electrical systems on unit 1 and unit 2.

At the same time, to improve operational flexibility, one of our three non-safeguards or safety-related cooling water pumps was upgraded to safety related to provide a backup to the two diesel-

NEAL R. GROSS

driven cooling water pumps used in the safety related system.

With that, I'll turn it back to Gene.

MR. ECKHOLT: I want to talk a little bit about the license renewal project, the development of the license renewal application, get into the various phases of the project, and wrap up talking about the commitment that was made in response to license renewal.

The license renewal project team was headed up by four engineering supervisors that are full time NSP employees. They have extensive plant knowledge and experience.

In addition to that -- I mean, they had a lot of plant experience, but they didn't have a lot of background in license renewal, so coming into the project, at the time the project started in 2005, we were part of the Nuclear Management Company.

There were three other active license renewal projects underway in NMC at that time, so we used the experience of the other members of the fleet to help train our folks. We utilized their processes extensively and used that to beef up our knowledge and program going into the project.

We also utilized a number of contract

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

support staff members that all had significant license renewal experience, both within NMC and at other plants.

Plant staff, plant subject matter experts were also very actively involved in the project. They reviewed a number of the LRA input documents during the development of the LRA.

They also were very actively involved in support of the license renewal audits and the region 3 inspection in January.

We also remained engaged with the industry, mainly through the NEI license renewal taskforce and the associated working groups.

We also observed audits at a number of plants, NRC audits at a number of plants and participated in the peer reviews of other plants' LRA's as we were developing ours.

Again, our project started in 2005, which is about the time that NEI 95-10 was brought to Rev 6, so our project's process and procedures were based on Rev 6 of NEI 95-10. The processes we used were consistent with the guidance of that NEI document.

The boundary drawings that we provided highlighted components for all the scoping criteria.

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

One other thing to note is that the switchyard 2 scoping boundary in the Prairie Island LRA does include breakers at the transmission system voltage. MR. BARTON: Question on your scoping, please. I noticed you have site lighting as listed as in scope for license renewal. It's the 8 first application I've seen with site light. What's different about your site lighting? MR. ECKHOLT: Joe, maybe you'd like to 10 touch on that. 11 MR. RUETHER: This is Joe Ruether. We took 12 13 a bounding approach, so we brought all electrical components in and dealt with the scoping screen on a 14 15 commodity basis. 16 So it didn't make any difference what the 17 -- site lighting was basically all the components for 18 electrical and brought into scope. 19 MR. BARTON: Okay, thank you. 20 MR. ECKHOLT: The next slide is a 21 simplified drawing of our switchyard, showing in red 22 those components that were brought into scope based 23 on our CLB. In blue, is the expanded scope that was 24 25 brought in to meet the expectations of the proposed

ISG 2008-01 on SBL.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Again, the aging management reviews were done in accordance with NEI 95-10. We maximized all consistency to the extent possible. In the end, we were just a little over 89 percent consistent with GALL for the AMR line items. That's assuming notes A-D.

Some plants have gone and used E as well. We did not do that.

Aging management programs -- there were 43 aging management programs identified in the LRA. 29 are existing at the plant. 14 are new.

Program consistency with the GALL -- 31 are consistent. Of those 31, nine also include enhancements. 10 programs are consistent with exceptions. Of those, six also contain enhancements.

There are two plant-specific programs, the nickel alloy nozzles and penetrations program and the PWR vessel internals program are both plant-specific.

Of the GALL exceptions, we've tried to summarize here what we'd call typical GALL exceptions. They include the use of more recent revisions of industry standards and the revisions cited in the GALL, the use of different or additional

NEAL R. GROSS

industry standards, alternatives to performance 2 testing specified in the GALL. Those would be in cases where there wasn't instrumentation or equipment available to perform the performance testing specified in the GALL. Also, the use of alternative detection 8 techniques or more recent NRC guidance than GALL requirements in cases where we used alternates to inspection test frequencies specified in the GALL. 10 11 Time limiting aging analysis was 12 performed in accordance with NUREG-1800 guidance and 95-10. The TLA's were evaluated in accordance with 10 13 CFR 54.21(c)(1). 14 MEMBER SHACK: Question. Are you currently 15 16 using a stress-based fatigue monitoring system? 17 MR. ECKHOLT: No. 18 MEMBER SHACK: Okay, that's a will. 19 MR. ECKHOLT: The LRA was submitted with 20 stress-based, but we completed the ASME code 21 confirmatory analysis and eliminated the stress-based 22 fatigue from the LRA. 23 MEMBER SHACK: And so you can leap the environmentally enhanced fatigue? 24 25 MR. ECKHOLT: Yes.

NEAL R. GROSS

1	MEMBER SHACK: Are you strictly cycle
2	counting on all these I mean, you've got a list of
3	components here from 6260, some of which you had
4	planned to do cycle counting and some of which you
5	had planned to do
6	MR. ECKHOLT: This is Phil. Phil Lindberg,
7	our programs lead. He could maybe give more detail.
8	MR. LINDBERG: This is Phil Lindberg, Xcel
9	Energy.
10	Could you repeat the question again?
11	You're interested in our cycle counting?
12	MEMBER SHACK: I'm looking at Appendix B
13	for the fatigue monitoring and you take the 6260
14	locations and you've got essentially, there's
15	three different methods.
16	There's cycle counting. There's stress-
17	based fatigue usage monitoring, and then there's
18	cycle based fatigue usage monitoring.
19	I'm not sure what the differences between
20	the two are, but then the statement seems to be that
21	you're not going to use stress-based monitoring
22	anymore.
23	MR. LINDBERG: That is correct. We're not
24	planning to use stress-based fatigue monitoring for
25	any of those EAF locations. We have section 3 fatigue

analysis of all six new reg 6260 locations. 2 Initially, as Gene mentioned, the original submittal went in with SBF numbers for a few of those locations and given the issues with the industry with SBF, we redacted that information. We went ahead and did -- for the hot leg nozzle and the charging nozzle, we went ahead and did full ASME 8 section 3 analyses, which used design cycles. So we have standing section 3 analyses 10 with applied FEN values that we show acceptance for 11 60 years. We do intend to continue to count cycles of 12 those design cycles as part of our metal fatigue 13 program. MEMBER SHACK: And there's an update of 14 15 the Appendix B that makes that statement? 16 MR. LINDBERG: Yes. It was submitted via 17 RAI responses. 18 MEMBER SHACK: Okay. 19 MR. LINDBERG: Thank you. 20 MR. ECKHOLT: There are 36 regulatory 21 commitments that were identified that currently 22 exist, with respect to license renewal. 23 Those commitments are tracked to the Prairie Island Commitment Tracking Program. They have 24

been assigned to the station personnel responsible

for implementation prior to the period of extended operation.

At this point, I'll turn it over to Steve Skoyen who will talk about the implementation activities.

MR. SKOYEN: Well, the implementation impacts all of our plant departments. The coordination of the implementation itself is the responsibility of our engineering programs department.

Because we're going to be implementing a number of new requirements associated with 10 CFR 54, we are managing that under a changed management plan, which is a formal process at the site.

All of our aging management programs have assigned owners. Those owners have been involved in the aging management program reviews as well as the audits and inspection.

In support of the additional staff required to implement the license renewal program, we hired two additional staff earlier this year so that they can work with a project team who has been working on the project for the last three or four years.

They are currently working on planning

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

and scheduling of new requirements. MEMBER POWERS: What does it mean that the programs have planned owners? MR. SKOYEN: They are assigned program owners. Two are aging management programs. Some of those are existing. Some of those are new programs. There are individuals associated with 8 those that understand they have that responsibility going forward for coordinating associated inspections and requirements. 10 MEMBER POWERS: I guess I still don't 11 12 understand. If I'm a program owner, what is it? What 13 do I have to do? MR. SKOYEN: As program owner, you're 14 responsible for ensuring the requirements of that 15 16 program are implemented at the station, whether it's 17 performance of inspections, evaluations analyses. 18 MEMBER POWERS: If I get hit by a truck? 19 MR. SKOYEN: We have back-up program owners identified for each program. Most of those are 20 21 managed in accordance with our program health process 22 for existing programs. 23 Going forward, new programs would be incorporated into that process as well. 24

MEMBER POWERS: This is different how? It doesn't seem like an unusual management structure at all on how you would do anything.

MR. SKOYEN: Yes, I don't know that it isn't that much different.

There are new requirements that we have to ensure that we implement. That's what the additional staff will be monitoring and tracking to ensure that those new commitments we made are implemented.

MEMBER POWERS: If I'm sitting at my desk and one day you come in and you say okay, you're in charge of this program, has anything changed in my life other than that I now have another job?

MR. SKOYEN: You have additional responsibility for that program, additional responsibility for ensuring that those requirements are implemented. There may be some training associated, add a qualification.

MR. WADLEY: I think what we were trying to convey is that we're already starting to integrate the programs into the plant operation. It's not just sitting in a project group, but we're trying to bridge that gap between now and a period of extended operation to make it so it's seamless. That's really

NEAL R. GROSS

all we're trying to say. MEMBER POWERS: That's really I was looking for. You guys now have it. MR. WADLEY: Yes. MEMBER POWERS: And presumably, they're learning what it means because they haven't part of your project team. 8 MR. WADLEY: Exactly. MEMBER POWERS: I mean, if somebody came in and told them they were in charge of this and they 10 11 said what the hell is this, right? 12 MR. WADLEY: Yes, there would be a glazed look on their face and they wouldn't move forward. 13 MEMBER POWERS: Yes. 14 15 MR. WADLEY: But that's really what we're 16 trying to get is that we're starting. 17 MEMBER POWERS: That's what I was looking 18 for. 19 MR. ECKHOLT: And keeping them involved or getting them involved during the review of the LRA 20 21 input documents and the audits helps them understand 22 so that it isn't dumped on them at the last minute as 23 our project wrapped up. They've been involved all along. 24

MR. SKOYEN: Any additional questions? MR. ECKHOLT: Okay, we will move onto what we're calling specific technical items of interest. We'll talk about underground medium voltage cables of Prairie Island. We'll also talk about the three SER open items under this topic. CHAIRMAN RAY: Before you do that, I'm 8 mindful of the fact that we'll go into some areas that are currently open and have a lot of interest 10 perhaps. 11 But I wanted, if this is the right spot 12 to ask some questions about some issues that aren't 13 open, but were addressed in your RAIs and had at least triggered some questions in my mind. 14 15 MR. ECKHOLT: Sure. 16 CHAIRMAN RAY: One of them has to do with 17 coatings. There was quite a lengthy discussion of 18 your response to not having an aging management program for coatings, side containment. 19 20 I guess the essence of it is that, to 21 quote here a sentence here from the response, 22 analysis demonstrated that debris will not prevent a 23 safety-related component from performing its intended function. It assumes that all qualified coatings are 24 25 within the zone of influence. In the worst case, pipe

break will fail and all unqualified coatings and site containment fail and become debris along with other debris that could be generated by a pipe break.

I guess I'm asking myself isn't this true everywhere? I mean, why is a coatings program called for at all for anyone given -- is there something unique, I guess I'm asking, about this pant that makes it invulnerable to coatings failure as compared with other plants?

MR. ECKHOLT: We're no different than any other plant with respect to coatings. The difference is that when our LRA was initially submitted, we did not include containment coatings.

However, it was raised as a contention as part of the hearing process that it wasn't there. So in an effort to resolve the contention, we went ahead and brought containment coatings into the license renewal program. We added containment coatings program.

Well, actually, we brought the existing program into license renewal space. That was the intent of bringing it in -- was to resolve the concerns raised in the hearing process.

CHAIRMAN RAY: So it is in scope even though -- I'm still not clear. Do you have a program

NEAL R. GROSS

1	for monitoring coatings?
2	Elsewhere here, it says, for example,
3	therefore coatings inside containment do not fall
4	within the scope of 10 CFR 50.54(a)(2). Since they
5	are not components, it's fair to prevent satisfactory
6	accomplishment and so on.
7	MR. ECKHOLT: Right. We did not bring the
8	coatings into scope. We did not feel in the initial
9	application that the coatings performed an intended
10	function. But again, we brought the program in
11	CHAIRMAN RAY: What's the status now? Do
12	you have a coatings?
13	MR. ECKHOLT: Yes, we have a coatings
14	program that meets all the industry and NRC
15	expectations and standards.
16	CHAIRMAN RAY: And that's a change, is it?
17	MR. ECKHOLT: No. No, that was in place.
18	That was an existing program and basically, we
19	brought that into scope.
20	MR. WADLEY: But it's a change from our
21	original application.
22	MR. ECKHOLT: It's a change from the
23	original application.
24	CHAIRMAN RAY: That's what I was trying to
25	get at Right thank you because I was really

puzzled by having read this and then listening to what you said. MR. BARTON: Let me make sure I understand. You now have an aging management program for coatings? MR. ECKHOLT: Yes. MR. BARTON: Okay. CHAIRMAN RAY: All right. That, I think, settles that. 10 MEMBER POWERS: How do you tell when a 11 coating has aged? Is that the indicator or do you 12 have something that --? MR. ECKHOLT: Maybe Richard, you can --? 13 MR. PEARSON: Yes. This is Richard Pearson 14 15 from Xcel Energy, Prairie Island. 16 The coatings program that's in place at the plant, first of all, you have qualified coatings. 17 18 They are monitored, like on a containment vessel 19 well, by inspection, but the qualified coatings have 20 been demonstrated really not to degrade. 21 Then you have the other series of 22 coatings that total program involves inspection. It 23 involves how we put new coatings on. It involves qualification of painters, qualifications of coatings 24 25 that go into containment. It involves lockdowns that

ensure the amount of unqualified coatings we have in 2 containment is still understood and is being able to be tracked. MEMBER POWERS: Your indicator of a failed coating, qualified or not, is it falls off -blistered, delaminated -- whatever? MR. PEARSON: That's correct. MEMBER POWERS: You do not have an 8 9 instrumental indication of aging? MR. PEARSON: No. It's only a visual 10 inspection. 11 12 MEMBER POWERS: I'll tell you an amusing 13 anecdote. I got interested in coatings on aircraft in the military. They spend a huge amount of money 14 15 trying to design a device to inspect the coatings, to 16 tell them when to re-paint their airplanes. 17 So I went over to the Military Airlift Command to see if they used this and the guy says, we 18 19 never used that. We just look at it and when it looks like it's about to fall off, we re-paint it. 20 21 MR. WADLEY: Visual inspections. 22 MEMBER POWERS: Visual inspections. 23 MR. PEARSON: This is Richard Pearson again. If we find degraded coatings, there's some 24 25 standards we can use for testing them out or the

extent of degradation. We'll take measurements, characterize it as best we can.

MR. ECKHOLT: Thanks, Richard.

CHAIRMAN RAY: Okay on coatings?

Another question I had -- similarly, you have a discussion about flow-accelerated corrosion, correlation methods, and so on, ending up with use of CHEKworks. But it says Prairie Island does not experience excessive flow of accelerated corrosion that was not predicted by CHEKworks. That's good.

Could you just comment on what -- have you done much replacement of piping for flow-accelerated corrosion reasons or do you expect to, I guess?

MR. ECKHOLT: Steve?

MR. SKOYEN: We've not done a great deal of replacement. Typically, during a re-fueling outage, we'll replace a couple of typically smaller lines -- two or three inch, as well as penetrations into the condenser -- but in terms of large components, we've not experienced a great deal of replacement.

MEMBER ARMIJO: When you do these replacements, do you replace them with the same material or more resistant materials -- chrome moly

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

and things like that? MR. SKOYEN: Typically, they're replaced with the same material, but if in the determination of the engineer, replacing that with a more resistant material because of the wear rate in that particular area is higher than expected, we will replace for that in materials. 8 CHAIRMAN RAY: Enough on that. I have only 9 one or two more in this category. One of them that caught my attention was 10 11 having to do with above-ground steel tanks program. 12 The response to the RAI on this asserts that inspection is done of just one of the three storage 13 tanks because it's representative of the other two 14 and is sufficient. 15 16 Can you say a little bit more about why 17 you're so confident that you don't need to inspect 18 all three condensate storage tank bottoms? 19 MR. ECKHOLT: Phil? 20 MR. LINDBERG: This is Phil Lindberg, Xcel 21 Energy. 22 Basically, we felt we had similar 23 materials and similar environments such that our

inspection of one condensate storage tank would

reflect all three tanks.

24

Certainly, if we were to find any evidence of degradation on that one tank, we would certainly expand our inspection scope to the remaining tanks.

MR. WADLEY: Phil, could you talk a little bit about how we intend to inspect those tanks?

MR. LINDBERG: It is a visual external inspection. The tanks are insulated, so the inspection would be of the external insulation looking for insulation damage or signs of rust or discoloration coming from the insulation.

We've also stated that we would remove insulation at lower points or at points that would be expected that might indicate damage and that we would physically inspect the exterior tank, the carbon steel tank surface underneath that insulation on a periodic basis.

CHAIRMAN RAY: Well, I'm referring to the ultrasonic inspection of the tank bottom.

MR. LINDBERG: I'm sorry.

CHAIRMAN RAY: And it just says that we're just going to do one because that will tell us all we need to know. I'm just curious about why you think just one UT inspection is representative of all three tanks. I mean, that's what asserted here, but it's

NEAL R. GROSS

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

not clear why.

3

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. LINDBERG: I guess from the way we looked at it, it was similar to how the inspections for, for example, for the one time inspection program -- were done to confirm the absence of aging on a sampling approach.

CHAIRMAN RAY: Okay, but you don't have any other rationale for one is enough?

MR. LINDBERG: I don't have any plantspecific OE, no.

CHAIRMAN RAY: Okay. And then my colleagues on the committee here probably can help me with this last one that has to do with materials leaching program. It's something I'm not familiar with.

But basically, your response to the RAI indicated that a visual inspection was deemed to be sufficient and adequate. Do you have any other comment on that or I offer my esteemed colleagues to question whether that's enough selective leaching of materials.

It's elevated a status of a program, but some folks felt that it was sufficient simply to do a visual inspection, as I read this. I gather you haven't had any experience with it?

NEAL R. GROSS

1	MR. WADLEY: No, we haven't. No.
2	CHAIRMAN RAY: Can you add anything to my
3	?
4	MR. LINDBERG: This is Phil Lindberg. No,
5	actually, our selective leaching program will use
6	visual inspection in conjunction with either hardness
7	testing or a mechanical scraping. It's not strictly
8	visual.
9	MEMBER ARMIJO: What are the materials in
10	your leaching program? What materials are you
11	inspecting?
12	MR. LINDBERG: Could you repeat the
13	question?
14	MEMBER ARMIJO: Yes. What materials are
15	concerned?
16	MR. LINDBERG: This would be for cast iron
17	and for copper alloys containing greater than 15
18	percent zinc.
19	MEMBER ARMIJO: Okay, so it's basically
20	brass and cast iron?
21	MR. LINDBERG: That's correct. Like I
22	said, we would be doing visual inspection in addition
23	to either a mechanical scraping or hardness test or
24	other available detection technique.
25	We have an exception to the program that

discusses the use of alternate detection techniques beyond hardness testing. MEMBER ARMIJO: Have you had to replace any of these materials? MR. LINDBERG: We have not done any inspections to date. This is a new program. CHAIRMAN RAY: It just caught my attention 8 that it was an exception, as he indicated. I'm not familiar enough with it to know whether it's 10 exception --11 MR. LINDBERG: The GALL recommendation is 12 for a visual inspection in conjunction with hardness 13 test. CHAIRMAN RAY: Right. 14 15 MR. BARTON: Expand on Mr. Ray's question 16 on the condensate storage tank, the bottom 17 inspection. 18 How are these tanks mounted? What's the 19 foundation? Tell me how they're installed. 20 MR. PEARSON: This is Richard Pearson. The 21 condensate storage tanks sit on a concrete base and 22 then they actually have some hold-downs on them. The 23 tank is held down to the concrete base. I'm not sure what kind of coating was put 24 25 on the tank when it was installed, but when you look

at them as a concrete base, you see the joint,
basically, between the condensate storage tank, the
insulation, the concrete base.

Does that answer the question?

MR. BARTON: Yes, so my next question is

MR. BARTON: Yes, so my next question is, how can you be assured that you don't have moisture under the tank that you didn't inspect and you do have some corrosion going on in the tank bottom if you're only going to do one of three -- what do you have? Two tanks? Three tanks, okay. Suppose you pick the wrong tank.

I mean, how are you assured that there's no leakage getting underneath between the joint in the bottom of the tank and the concrete foundation?

MR. LINDBERG: This is Phil Lindberg. Part of that external visual inspection would be of that joint between the tank and the foundation. So if, again, if we were to find degradation of that joint, that would be an indication of potential intrusion, water intrusion, and we would likely end up doing some UT inspection on that.

MEMBER STETKAR: That joint is not sealed, am I correct?

MR. LINDBERG: This is a -- I'm not sure what the material is. There's some type of sealant at

NEAL R. GROSS

	35
1	the joint.
2	MEMBER STETKAR: If the tank would leak,
3	would you see traces of that leakage on the concrete
4	base and outside the tank?
5	MR. ECKHOLT: You should, yes.
6	MR. BARTON: Well, if it's sealed, how
7	would you see it?
8	MEMBER ARMIJO: That is the question.
9	MEMBER MAYNARD: Are you doing the visual
10	inspection on all three or just on one?
11	MR. LINDBERG: On all three. The visual is
12	on all three,
13	MEMBER STETKAR: Yes, you can't visually
14	inspect the bottom of them.
15	MEMBER MAYNARD: Right.
16	CHAIRMAN RAY: Okay on the tank bottoms?
17	John Stetkar had a question.
18	MEMBER STETKAR: Two quick ones. Back to
19	the selective leaching. Do you have any in-scope
20	systems that have buried cast iron piping?
21	MR. MCCALL: Hi, this is Scott McCall with
22	Xcel. Yes, fire protection piping is buried in cast
23	iron.
24	MEMBER STETKAR: That's the only one?
25	MR. MCCALL: Yes.

MEMBER STETKAR: The second question I had

-- you had a couple of exceptions on your fuel oil

chemistry program. I think I understand the

rationale.

One of the exceptions you took is you weren't going to sample for biological activity. I think, as I understand it, the argument is that you have very small filters and your normal sampling program would detect any sludge that might be generated by any type of biological attack.

Are all your samples taken directly from the bottom of each of your tanks or are your sample points elevated above the bottom of the tank so that you could have a sludge build up without actually detecting it?

MR. MCCALL: I'm not sure if I have the answer to that question. I know some of our sampling is done at top, middle, and bottom locations. The sampling is coming from some place near the bottom of the tank.

MR. ECKHOLT: We'll verify that. We can get an answer for that. We'll verify that.

MEMBER STETKAR: I think in the interest of time, let's go on to the more interesting topics.

CHAIRMAN RAY: All right, we'll reserve

NEAL R. GROSS

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

the -- return to these less interesting ones later. Go ahead. MR. ECKHOLT: All right. I'll turn it back over to Steve to talk about underground medium voltage cables. MR. SKOYEN: We did have a failure of a circulating water pump cable that resulted in a unit 8 1 trip in May of this year. That cable was replaced. It was a ground fault. We are currently in the process of continuing 10 a cause evaluation and the cable is currently at EPRI 11 12 for testing. 13 We have experienced three other cable failures. Two of those on 14.8 kilovolt lines and one 14 on a 41.16. 15 16 The two on the 14.8 volts were identified at the cable terminations. Both of them related to 17 18 water intrusion. One actually resulted in a ground 19 fault. One was taken out of service prior to failure. Those cables were subsequently replaced in 2005. 20 21 We've also had one 41.16 failures, I 22 mentioned. That was also at a termination. That one was actually identified during an outage. The cause 23

during maintenance that had weakened the insulation.

of that particular one was manipulation over time

24

Going forward, our cable insulation
testing will be part of a new program that's being
implemented called the inaccessible medium voltage
cables. That's subject to 10 CFR 50.49 Environmental
Qualification Requirements Program.
MEMBER BONACA: This is a new program?
MR. SKOYEN: Yes, this is a new program.
That's correct.
MEMBER BONACA: You did not have a program
that responds to the failures you experienced.
MR. SKOYEN: In response to generic letter
2000-701, we have a cable program currently at the
site. We had been MEGR testing cables for a number of
years.
MR. BARTON: In that letter, you said you
would have a program in place by the end of the 2007.
When the inspection team was out there in
September 2008, they said you didn't have a program
in place, although it was in the commitment tracking
system. Yet, the SER says you had a program in place
in March 2008.
What's the story? Is there a cable
maintenance program in place at the site at this
time?

MR. SKOYEN: There currently is a cable

1	program in place, as you mentioned, that we had
2	intended to implement that program by the end of
3	2007. That implementation was delayed. That program
4	has now been implemented.
5	MR. BARTON: Is that because somebody
6	missed it in the commitment tracking system or did
7	you change the date in the commitment tracking
8	system?
9	MR. ECKHOLT: That was never entered it
10	was not identified as a formal commitment.
11	MR. BARTON: It was not?
12	MR. ECKHOLT: It was not. It was not in
13	the commitment tracking system. It was basically a
14	statement of our intent to implement the program by a
15	certain date.
16	MR. BARTON: So your answer to the generic
17	letter was you intended to have it, but you didn't
18	put any commitment? You didn't cite commitment on it?
19	MR. ECKHOLT: It was not identified as a
20	formal commitment.
21	MR. BARTON: Okay.
22	MEMBER STETKAR: To what extent do you
23	have water intrusion in underground medium voltage
24	cable ductwork?

MR. SKOYEN: Joe?

2

MR. RUETHER: This is Joe Ruether. I didn't hear the question. MEMBER STETKAR: To what extent have you found water intrusion in underground medium voltage cable ductwork or other conduits and holes? MR. RUETHER: The two examples in the 13.8, we've seen water in those cables and replaced 8 that, as we referred to earlier. And then, also, in this recent May, cable -- a motor pump cable for unit one that looks like it 10 may have water involved in that as well. The root 11 12 cause is not complete, so it's --13 MEMBER STETKAR: Do you pull manholes or other types of covers to inspect? If you do, how 14 15 often do you do it? Which ones do you do? 16 MR. RUETHER: We have, as far as in scope of license renewal, medium voltage. We have one 17 manhole involved there. 18 19 When we replaced the 13.8 kV cable, we put in a whole new ditch, a whole new routing. We put 20 21 a new manhole at that time in 2005. 22 We've looked at water level -- opened up 23 the cover several times, have not seen water or any indication of water, looking on the sides to see if 24 25 any water has been in there.

	41
1	MEMBER STETKAR: Do you have a procedure
2	to periodically pull the manhole covers to inspect
3	the water?
4	MR. RUETHER: Yes, we do.
5	MEMBER STETKAR: Is that on occasion?
6	MR. RUETHER: No yes, we do. It's in
7	the PM program.
8	MEMBER STETKAR: How often?
9	MR. RUETHER: We initially looked at
10	quarterly and then it was determined that we didn't
11	see evidence. That was subsequently changed to every
12	four years.
13	Based on the experience from license
14	renewal, we'll be committed to doing that inspection
15	every two years.
16	
17	MEMBER STETKAR: That's a long time. If I
18	were to look at a site clock plan, where's the
19	manhole where you have seen water or where you
20	inspect? Is it the one out at the screenhouse? 13 kV
21	and all?
22	MR. ECKHOLT: It's actually located I
23	have a site plan. I'll pull it up.
24	MR. RUETHER: This is Joe Ruether again.
25	The 13.8 manhole is actually away from the river from

the plant. You got the river and then you have the physical plant and then going in is where the manhole is. It used to be the middle parking lot.

MR. ECKHOLT: The manhole is in this location right here. It's an old parking lot that's no longer used now.

One other thing to note with the manhole, the bottom of the manhole is sand, so should any water enter --

MEMBER STETKAR: It's an opportunity for water to come in.

 $$\operatorname{MR}.$ ECKHOLT: But it also drains out very readily both ways.

MEMBER STETKAR: If you say so.

every two years -- I'd have to see the program to know whether -- I mean, it could be getting wet deep down and if you're just looking at it at a time it may be down, but I also consider this probably more of a current operating issue as much as a license renewal issue that should get resolved as part of this. The two year cycle doesn't really excite me as far as an adequate inspection.

NEAL R. GROSS

MEMBER STETKAR: Yes, and that is sort of the reason why I brought it up because it is a current operating issue. On the other hand, there are a lot of plants out there that have water in manholes that don't have cable failures. For this purpose, I would disregard 8 termination failures because it's obviously not an environmental thing. It's a work process issue. But I think inspections every four years, 10 11 every two years are scant. I'm also surprised you 12 only have one manhole that carries medium voltage, 13 important to safety cables. I have to do a little research on that. 14 15 CHAIRMAN RAY: Okay? 16 MEMBER ABDEL-KHALIK: This program -- when 17 do you expect them to be completed? 18 MR. SKOYEN: The actual development of the 19 program? 20 MEMBER ABDEL-KHALIK: The actual testing. 21 MR. SKOYEN: Implementation of our 22 existing program -- you're referring to generic 23 letter program? MEMBER ABDEL-KHALIK: You have a cable 24 25 testing program in place.

1	MR. SKOYEN: Correct.
2	MEMBER ABDEL-KHALIK: When do you expect
3	testing to be completed of all medium voltage cables?
4	MR. SKOYEN: Of all medium voltage cables?
5	The testing that's required by the program requires
6	that we determinate the cable at both ends, so those
7	will take place over a series of outages over the
8	next few years.
9	In terms of a pardon me?
10	MEMBER BONACA: Somewhere around four
11	years?
12	MEMBER ABDEL-KHALIK: It said four
13	outages, which carries you through the period of
14	extended operation. I'm just trying to find out why
15	that is acceptable.
16	
17	MR. SKOYEN: I believe that would be two
18	outages on each unit.
19	MEMBER ABDEL-KHALIK: So when would that
20	end?
21	MR. SKOYEN: That would end approximately
22	four years or the less of four years
23	MEMBER ABDEL-KHALIK: Which is right
24	before the period of extended operation.
25	MR. SKOYEN: Right, a little bit before

then.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MEMBER ABDEL-KHALIK: Okay, thank you.

MR. ECKHOLT: The commitment for the license renewal aspect of this program is to be completed by the PEO. Anything more on --?

CHAIRMAN RAY: No thanks.

MR. ECKHOLT: Okay, moving on to the SER open items. We'll talk first about the PWR vessel internals program.

The GALL anticipates a future program. It anticipates that the program under development by EPRI and MRP will be reviewed and approved by the NRC and put in place.

Our original LRA was submitted with the associated GALL statement submitting to implement the program as approved by the NRC. As part of the hearing process, a contention was raised on the adequacy of just providing a commitment rather than a detailed discussion of an internals program.

So in order to resolve that contention, we've submitted a plant-specific vessel internals program back in mid-May that was based on the EPRI MRP-227 Rev 0 document that was submitted for NRC review.

We did retain the commitment to update

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701 the program based on whatever is finally approved by the NRC.

Subsequent to us adding that to our LRA, all the parties involved in the contention process agreed that it resolved the issue and agreed to dismiss the contention. The ASLB subsequently dismissed the contention.

And then, as Brian noted, the NRC staff review is still in progress on the submittal we made.

MEMBER SHACK: And this is basically an inspection plan?

MR. ECKHOLT: Yes. Any other questions?

The second open item relates to scoping of the waste gas decay tanks. SSCs are in-scope per part 54 in part if they prevent or mitigate the consequences of an accident which could result in off-site exposures comparable to those referred to in 10 CFR 100.

The Prairie Island waste gas decay tanks are classified as safety-related. However, we did not initially bring them into scope because the off-site exposure potential was not considered comparable. It was not what we consider -- it didn't reach a 10 percent threshold.

The NRC reviewers took issue with that interpretation and in the end, we agreed to re-

NEAL R. GROSS

classify the waste gas decay tanks as in-scope and we made a submittal that went in in early June bringing those tanks into scope. Again, the NRC staff is currently reviewing that submittal.

Then the third SER open item relates to reviewing cavity leakage. Just a little bit of background on the NRC review of this issue. The NRC was briefed on this issue during the aging management audit in the fall of 2008.

We also held a public meeting with the NRC staff to give them more detailed information on the issue and the actions we were taking. There were a number of REIs that we responded to and there was an NRC team that came on-site to do an audit of some of our documentation as well.

We have responded to all the REIs. The last response went in on June 24th of this year.

Again, the NRC review is still in progress.

We'll also provide some more detailed information. Steve Skoyen will give us a little background on the leakage, our containment configuration, the leak locations, the leak paths, our inspection results to date, the corrective actions we're taking, and what we're looking at for

NEAL R. GROSS

long term aging management as well as an evaluation we've done on potential degradation. So with that, I'll turn it over to Steve.

MR. SKOYEN: Thank you, Gene. Prairie

Island has experienced intermittent leakage

indications in both units since the late 1980's.

Approximately 1987 was the first documentation of a problem.

The cumulative leak rate that we see from the refueling cavity is approximately one to two gallons per hour. It's most commonly seen in the ECCS sump and then in the regenerative heat exchanger room.

Sources has been determined to be refueling cavity water, based upon the chemistry of the water that accumulates in those two locations, and the fact that the leakage indications typically begin two to four days after the refueling cavity has been flooded. They end approximately three days after the cavity has been drained.

We've been successful with sealing activities, either application of a strippable liner or caulking, but our success has been inconsistent.

MR. BARTON: Let me ask a question. I've seen that you've taken some corrective actions, but

NEAL R. GROSS

this subsequent -- I assume when you do a strippable coating prior to a refueling outage, do you do the same spots all the time, but yet when you fill up for that outage, do you still have leakage, which means that you've got -- that the coating either failed or you've still got leakage in other parts of the pool that you haven't found.

MR. SKOYEN: We had some success with a coating when it was applied properly and when we were able to apply it to all areas, we were successful.

We were unsuccessful when it was applied improperly. We saw the coating delaminating in the application to the location that we believe are leaking is not done properly, so we didn't -- the process wasn't applied.

MR. BARTON: Were you ever successful in an outage of sealing and not having any leakage in that outage of did you always have leakage?

MR. SKOYEN: We were successful with the application of the strippable coating approximately 50 percent of the time.

We were also successful when we caught around the base plates and underneath the support stand nuts approximately 50 percent of the time.

MR. WADLEY: Sufficiency of application is

NEAL R. GROSS

MR. BARTON: You think it's an
application, but if you had applied it properly you
think you would have stopped it?
MR. WADLEY: Yes.
MR. BARTON: So you think you know where
the leaks are?
MR. WADLEY: Correct, yes.
MR. ECKHOLT: We'll get into that here.
MR. BARTON: Okay.
MR. WADLEY: We demonstrated a correlation
during a
MR. BARTON: I just wondered whether we
were chasing a ghost here or whether we're just
having a problem fixing what's there. Okay.
MEMBER STETKAR: Well, you know if you've
been successful part of the time and unsuccessful
other parts of the time, you may want to consider
another sealing method or do additional work and make
sure the sealing method you use actually performs its
function.
MR. ECKHOLT: We'll get into
MR SKOYEN: Well get into the action we

Following the most recent refueling

NEAL R. GROSS

plan to take.

outage in which our sealing method was not successful, we determined that we needed to perform a root cause evaluation on this issue. So that was performed earlier this year.

As a result of that root cause evaluation, we determined the sources of leakage to be the embedment plates for the reactor internal stands which are in the lower cavity and then the rod control cluster change fixture supports which are in the transport.

We determined that based upon the correlation between when we are successful in mitigating a leakage and when we were not, when we could relate that back to problems during application of the coating or application of the caulking.

Some background on our containment vessel because it may be different from others you've seen - bring up the drawing.

Actually, if you turn to the last slide in your presentation -- we did include a figure so we can look at that. The containment pressure vessel itself has an inch and a half thick bottom head, an inch and a half thick shell, and the top head is 3/4 of an inch thick.

At the ECCS sump location, as well as

NEAL R. GROSS

other penetrations, the thickness of the shell is 3/4 of an inch for reinforcement.

Material is an SA 51670 low temperature carbon steel.

The lower head, as you can see in the drawing, is fully encased in concrete on both sides. The remainder of the containment pressure vessel -- and there's a five foot annular gap between the containment vessel itself and the one in the leakage -- reinforce the concrete shield building. That allows us access to the vast majority of the containment pressure vessel itself.

I'd also like to point out on this slide, because we'll be talking about this later, the regenerative heat exchanger room. That lies right below our lower cavity and we have seen evidence of leakage there.

The fuel transfer tube and canal, as well as the upper refueling cavity. This is the reactor head.

At this time, I would also like to point out our sump charley, which is below the reactor vessel. We'll also be referring to that later. At that particular point, the thickness of the concrete is approximately 16 to 18 inches.

NEAL R. GROSS

MEMBER ABDEL-KHALIK: So how would a leak make its way all the way to the sump there? MR. SKOYEN: Actually, that is not the sump where we typically see the leak. We'll get to that in the next section. MEMBER ABDEL-KHALIK: Okay. MR. SKOYEN: Okay, the top view, you'll 8 notice our ECCS sump -- that's at an elevation of 693.7. 693 and 7 inches. We didn't see that in the prior view because it was in a different plane. 10 11 That's typically where the leakage would show up, in 12 that particular location. 13 MEMBER STETKAR: So that's 693.7, so that's --14 15 MR. ECKHOLT: We've just got another --MEMBER STETKAR: Do you have another 16 elevation that shows that? 17 MR. ECKHOLT: It's down in this location. 18 19 The refueling cavity bottom is up here. 20 MR. SKOYEN: Can we go back to the cut-21 away drawing again, the elevation drawing. It may b 22 easier to see here. 23 Although it's not shown on this picture relative to the other elevations, you can get an idea 24

of approximately where that is located.

MR. ECKHOLT: That's basically down --MR. SKOYEN: 693 elevation. MEMBER MAYNARD: That's at the bottom of that thing over on the right. MEMBER ARMIJO: You have a slide 51, page 51, that's shows the ECCS sump. Is that one of those locations that where you're finding the water? MR. SKOYEN: That's correct. That's the location that we're referring to on this particular slide, in the center -- the cut-away drawing in that 10 particular location. 11 12 And you'll note that the grout between 13 the containment pressure vessel itself and the sump is relatively thin in that particular area. 14 MR. ECKHOLT: This area here. 15 16 MEMBER ARMIJO: This looks thicker there 17 also, for some reason. 18 MR. SKOYEN: Correct. That's a penetration 19 so it has some reinforcements. That's approximately three and a half inches. Next slide, Gene. 20 21 The actual leak locations themselves, the 22 typical reactor vessel internals support stand is in 23 the left and the typical RCC change fixture support stand is on the right. There are eight internal 24 25 support stands and we have three NRCC change fixture

supports.

2

8

10

11

12

13

The leakage, we believe to be flowing the threads down past the nut. Once past the nut, there's a seal weld -- this is the RCC change fixture -- seal weld that was installed when this was originally put in.

That ground flush, we believe that there's a leakage path to that location that's allowing the refueling cavity water then to pass completely through the stud and then come out underneath the embedment plate.

Similar arrangement on the internal support stands.

14

15

16

17

18

19

20

21

22

23

24

25

MR. ECKHOLT: Maybe you can describe the caulking we've done on these in the past?

MR. SKOYEN: Yes. Past actions that we've taken, most recently was caulking and we would remove the nuts from the top of the base plate, underneath those nuts to prevent the leakage from going past the threads. Then between the base plate and the embedment plate, we would try to caulk there.

If you look at this and go back to the prior slide, Gene, that orange material that you see there is the caulking. That is applied and removed

NEAL R. GROSS

each outage. MEMBER STETKAR: Is that borated water? MR. SKOYEN: That's correct. MEMBER STETKAR: What are the materials for the nuts, the studs, face plates? MR. SKOYEN: It's all like a pore stainless. MEMBER STETKAR: Okay. Have you seen corrosion of any sort that is significant that would change the strength of the structure? 10 MR. SKOYEN: In the refueling cavity 11 12 itself? 13 MEMBER STETKAR: Of these supports. MR. SKOYEN: No, we have not. No corrosion 14 and no reports of any deficiencies related to the 15 16 integrity of the supports for the studs. 17 Okay, next slide, Gene. Do you want to go 18 to the cut-away drawing? We are referring to slide 19 number 33 when we talk about the path the leakage 20 takes. 21 Once the leakage is underneath the 22 refueling cavity and liner -- or seeped through -- it 23 will travel through construction joints between the floor of the transfer pit and the wall behind the 24 25 transfer tube. Once it's behind the wall in the

transfer tube, it can travel horizontally and circumferentially around the containment, which is between that space between the concrete and the shell.

Once it gets into the lower elevation of containment, we see that come through the ECCS sump. As we mentioned earlier, grout is relatively thin in that area and that's why we believe it shows up in that particular location.

The leak rate that we see in this particular location is approximately one gallon per hour -- up to one gallon per hour. It has been the last -- depending on our success with mitigation.

We have also seen evidence of leakage in our regenerative heat exchanger room, which is directly below the lower refueling cavity. That particular leakage will travel and once it's underneath the liner. It can follow hairline cracks in the concrete and then seep through the sealing in the walls in that particular room.

MEMBER ARMIJO: Do you have some sort of a sump pump in that area, that 851 -- slide 851.

MR. SKOYEN: In the ECCS sump? Yes, there is not an existing pump in there, but during

NEAL R. GROSS

1	refueling outages, we will pump that occasionally if
2	that particular outage has some leakage.
3	MEMBER STETKAR: A portable pump?
4	MR. SKOYEN: Yes, correct.
5	MEMBER SHACK: I thought you said before
6	you didn't see leakage into sump C.
7	MR. SKOYEN: Sump Charley is underneath
8	the reactor vessel. What we're talking about here is
9	the ECCS sump.
10	MEMBER SHACK: Do you see leakage in both
11	of the sumps?
12	MR. SKOYEN: No. We see the commonly,
13	we see the leakage in the ECCS sump. Sump Charley, if
14	there's leakage in that particular area, it is more
15	than likely due to leakage through the cavity seal.
16	CHAIRMAN RAY: I was going to say how the
17	heck are you going to separate that?
18	MEMBER STETKAR: Well, you can tell just
19	be well, you have insulation on the reactor vessel
20	so you can't see.
21	MR. SKOYEN: Correct.
22	MEMBER STETKAR: The pathway is going to
23	be between the vessel.
24	MR. DOWNING: I would like just to add one
25	clarification if I may, My name is Tom Downing. I'm

2

2

at Prairie Island site.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

There is evidence of leakage in the sump under the reactor vessel only in that there's a stain in the wall that originates from a construction joint and comes down the wall. Actual leakage has never been witnessed because that sump is not accessible when the pool is flooded.

You can also see on the diagram there that the one horizontal line coming over to the sump directly under the reactor vessel is just to indicate that there is a stain on the wall there.

MR. SKOYEN: Any additional questions regarding leakage?

CHAIRMAN RAY: Well, you demonstrated or illustrated I should say a hypothetical path. It's one that I assume could exist. It's not a unique path from the site of the leakage to the sump of interest.

MR. SKOYEN: Correct. Regarding inspections that we've done related to the leakage, we have poured ultrasonic examinations and visual examinations of the containment vessel.

In particular, in the ECCS sump, we have removed the grout at that location more than once and performed inspections there.

All readings have been above nominal. All

NEAL R. GROSS

no corrosion in that particular area. The visual 2 inspection confirmed that as well. The annulus area, we have also inspected there because as we've mentioned, once the refueling cavity leakage would get past underneath the liner, once it gets to the transfer tube, it can go down 8 along the wall. So we have inspected from the annulus from external to the pressure vessel looking back in to determine if there's been any corrosion on the 10 11 interior side. We've seen none on the exterior. 12 At that location, we have not identified 13 any corrosion either. Again, all of our wall thickness measurements are above nominal in that 14 15 location and they're also consistent. 16 MEMBER STETKAR: Now, I take it every 17 place where leakage ends up is in some kind of a 18 concrete vault with the liner, metallic liner? 19 MR. SKOYEN: No, that's not correct. 20 MEMBER STETKAR: What's not correct about it? No liner? 21 22 MR. SKOYEN: No liner. 23 MEMBER STETKAR: Okay, so you're flat up against the concrete? 24 25 MR. SKOYEN: Correct.

readings have been consistent, which should indicate

1	MR. ECKHOLT: Yes. There's no steel liner
2	on the surface
3	MR. BARTON: But ECCS sump.
4	MEMBER STETKAR: Have you found any
5	deterioration of the concrete or the coating or do
6	you usually have some kind of a coating here?
7	MR. SKOYEN: No. We see the leakage
8	seeping through the coating. We have not seen that
9	the coating has deteriorated in that location and we
10	have no evidence of concrete degradation either.
11	MEMBER STETKAR: Have you inspected the
12	areas for cracks that would take you far enough into
13	it rebar?
14	MR. SKOYEN: We have looked at cracks. The
15	cracks that we have looked at as part of our
16	structures monitoring program could be characterized
16 17	
17	as hairline cracks. We have no significant cracking.
17 18	as hairline cracks. We have no significant cracking. MEMBER STETKAR: You have no way of really
17 18 19	as hairline cracks. We have no significant cracking. MEMBER STETKAR: You have no way of really determining what condition of rebars?
17 18 19 20	as hairline cracks. We have no significant cracking. MEMBER STETKAR: You have no way of really determining what condition of rebars? MR. SKOYEN: Not directly, that's correct.
17 18 19 20 21	as hairline cracks. We have no significant cracking. MEMBER STETKAR: You have no way of really determining what condition of rebars? MR. SKOYEN: Not directly, that's correct. CHAIRMAN RAY: Well, now, aren't you
17 18 19 20 21 22	as hairline cracks. We have no significant cracking. MEMBER STETKAR: You have no way of really determining what condition of rebars? MR. SKOYEN: Not directly, that's correct. CHAIRMAN RAY: Well, now, aren't you planning to excavate
17 18 19 20 21 22 23	as hairline cracks. We have no significant cracking. MEMBER STETKAR: You have no way of really determining what condition of rebars? MR. SKOYEN: Not directly, that's correct. CHAIRMAN RAY: Well, now, aren't you planning to excavate MR. SKOYEN: Yes.

MR. SKOYEN: Yes, we'll be covering that a 2 little bit later. CHAIRMAN RAY: All right. MEMBER ABDEL-KHALIK: Now, when you say the leak rate is one to two gallons per hour, this is your measured leak, right? MR. SKOYEN: That's correct. MEMBER ABDEL-KHALIK: Do you have any idea 8 what your actual leak rate is? How would you go about 10 estimating that? 11 MR. SKOYEN: That is probably the most 12 direct way to measure it. Tom, if you have something 13 to add? MR. DOWNING: Yes. My name is Tom Downing. 14 When you first -- well, I shouldn't say 15 16 when you first start experiencing -- back in `98, `99 17 time-frame when we experienced leakage, we hung 18 plastic sheeting up in the leak areas and drained it 19 into a bucket, five gallon bucket, and timed it. 20 At that time, the leakage in the region 21 room was estimated at 1.25 gallons per hour. 22 Similarly, we estimated the amount of leakage into 23 the ECCS sump at .5 gallons per hour. So the sum of total leakage and 24

NEAL R. GROSS

containment generally ranges between one and two

gallons per hour. MEMBER ABDEL-KHALIK: Well, but my question was aimed at finding out are there any other locations where water could actually be accumulating? MR. DOWNING: It's a potential that water is accumulating on the bottom head of the reactor vessel itself. There's really no way to know for sure 8 exactly where the water travels or where water resides. I would expect that the leakage either 10 comes through the construction joint or follows the 11 12 transfer tube directly, comes down the wall, comes 13 around containment, and could potentially fill the interface between the interior concrete in the inside 14 diameter of the reactor vessel bottom head. 15 16 MEMBER ABDEL-KHALIK: If that were the 17 case, what would be the consequences? MR. SKOYEN: Of the actual water at that 18 19 location? 20 MEMBER ABDEL-KHALIK: Right. 21 MR. SKOYEN: We'll also be getting into 22 that as part of the presentation a little bit later 23 when we talk about evaluation of potential degradation. 24

MEMBER ABDEL-KHALIK: Okay.

CHAIRMAN RAY: We can run a little over, 2 but we've got 20 minutes. MR. SKOYEN: All right. We plan to prepare to permanently eliminate the leakage during our next refueling outage on each unit. MR. BARTON: Let me ask you. This thing has gone on for so long. Why now do you decide you're 8 going to fix it? MR. SKOYEN: Well, we had, as I mentioned earlier, we had tried a number of sealing methods. 10 11 Given the inconsistency of performance, we determined 12 that we could no longer rely on that to eliminate 13 this leakage. We were successful during our unit 1 14 outage in the spring of 2008, the sealing on that 15 16 unit. 17 We had less success in the fall. We 18 didn't see leakage for approximately 10 days, but 19 after 10 days, we did see leakage into our ECCS. 20 MR. ECKHOLT: We had some difficulty. We 21 couldn't remove the nuts and get the caulking under 22 them for that outage so --23 MR. SKOYEN: That is a concern as well because that's a stainless to stainless interface. 24 25 There is a concern for GALLing and repeated removal

and installation in that area. What we're performing now is a permanent repair so that we don't have to do that anymore. MR. WADLEY: It's not acceptable to continue to have this leak. Too many unknowns. CHAIRMAN RAY: Mike, I must say that that was hard to figure out from a lot of the rhetoric that was submitted here -- that it wasn't acceptable. 8 I'm glad to hear you say that. 10 MR. BARTON: Yes, thank you. MR. SKOYEN: The repair method that we're 11 12 going to employ is shown on this particular slide. As 13 you can see, on the right hand side of the slide is the existing configuration with an open nut. 14 We will be installing blind nuts, as 15 16 noted on the lefthand side in the particular 17 locations where it's attainable to surface area and 18 the thread engagement. 19 Then putting a seal weld all the way around the location, that will eliminate the leak 20 21 path that could occur there. 22 We'll also be putting a seal weld between 23 the base plate and the embedment plate to eliminate that leak path. 24 25 We believe that by doing this, we will

permanently eliminate the leakage that occurs from both the internal stands and the RCC change fixture support stands. MEMBER ARMIJO: There was no seal weld there initially? MR. BARTON: There was initially. said down here, they think that --8 MEMBER ARMIJO: Yes, just around the threads. 10 11 MR. SKOYEN: Yes. Just around the threads. 12 So we believe this to be a much more 13 robust design than was the original. It also allows us to inspect these welds going forward and identify 14 15 any concerns with those in repair. 16 It also, from a dose consideration, 17 perspective, is we receive far less dose employing 18 this method of repair than going back to the original 19 drawing. 20 So for a number of reasons, we believe 21 this is the correct method for repair. 22 CHAIRMAN RAY: I take for granted that 23 there aren't any leak chases on the seams of the cavity and so on. 24

MR. SKOYEN: That's correct, right.

NEAL R. GROSS

MEMBER ABDEL-KHALIK: Have you done a simple calculation to -- if you have a certain water level in the refuelings, storage, how big a crack in terms of equivalent diameter would you have to have to have to give you water flow of one to two gallons per hour all the way from that location to that sump? MR. SKOYEN: I don't know that -- we haven't done a calculation on a crack size. We do know that it would be somewhere between 165 and 350 drips per minute. MEMBER ABDEL-KHALIK: No, I mean, size of the hole. MR. SKOYEN: I don't believe we've done that. Tom? MR. DOWNING: Yes. Again, my name is Tom Downing. We've never actually calculated what size hole would be needed to generate a one to two gallon per hour leak, but intuitively it would seem that it would be pretty small. MEMBER ABDEL-KHALIK: It has to travel a very, very long distance. MR. DOWNING: Yes, it does travel a torturous path. Again, leakage manifests itself in ECCS sump anywhere from three to ten days after the pool is flooded to a level of -- is pool at 35 feet,

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

above 35 feet of head. MEMBER ABDEL-KHALIK: But that would be a relatively simple calculation to do just to get an idea how big a hole is that. MR. WADLEY: We'll take a look at that. We'll get back to you. CHAIRMAN RAY: You guys are persuaded that 8 you know where the leakage is coming from. I would just observe the seam leakage in these liners is not 10 uncommon. MR. SKOYEN: We have inspected for seam 11 12 leakage in the past, both through vacuum box testing, POINT testing. We will be doing some additional seam 13 leakage testing this upcoming outage. 14 MEMBER SHACK: Well, I think that was the 15 16 point of Said's thing is to see whether that hole 17 size is really consistent with what you think is the 18 mechanism, a small crack in that seal weld or a 19 bigger hole which might indicate --20 MR. SKOYEN: We have other problems. Okay, 21 thank you. 22 CHAIRMAN RAY: But the fact is you do know 23 that these things are leaking? There's no doubt about that. 24

NEAL R. GROSS

MR. SKOYEN: That's correct.

MEMBER ARMIJO: And you had good success 2 when you seal them, although it's unreliable when you seal them with coatings or caulking or whatever. MR. SKOYEN: That's correct. MEMBER ARMIJO: So there may be other leaks, but these you know for sure. MR. WADLEY: We have high confidence that 8 this is the most probable location of the leak. The repairs that we'll perform then will validate whether or not those -- our assumptions and our confidence 10 11 was truly supported in this location. 12 CHAIRMAN RAY: What's your experience on 13 the spent fuel pool? MR. WADLEY: No leakage at all that I can 14 recall. Does anyone else have a --? 15 16 CHAIRMAN RAY: We may return to that if we 17 have time, but you're focused on this now so lets continue. 18 19 MR. WADLEY: Yes. 20 MR. SKOYEN: Okay, we're going to enhance 21 our monitoring of the tank pressure vessel by 22 removing concrete from our sump Charley, which we 23 referred to before. That's the sump below the reactor vessel. It's a relatively --24

NEAL R. GROSS

CHAIRMAN RAY: Jack, this is the

excavation I was talking about that he's referring to 2 here. MR. SKOYEN: We'll be removing concrete at that location because it's the lowest -- as close as we get to the lowest point in containment. With respect to the head, there was stagnant water there. That would be the most probable 8 location. Again, that's 16 to 18 inches of concrete we'll have to remove. Once that's removed, we'll be 10 11 performing both a visual examination and an 12 ultrasonic examination to assess the containment 13 pressure vessel. If there's any water observed in that 14 particular area, that will be removed. We'll be doing 15 16 this in the outages following the repair locations. MEMBER STETKAR: I take it you don't 17 18 expect to find any water in there, right? MR. SKOYEN: I don't know if I'd make that 19 statement. We'll talk about that a little bit later 20 21 as well. 22 We'll also be performing some additional 23 assessments. We will be performing a margin assessment of the containment vessel concrete and 24 25 rebar, as well as evaluating the structural

requirements potential degradation around the fuel transfer tube.

Long term aging management -- we are going to be monitoring areas that previously exhibited leakage for the next two outages after the repairs. That is in our corrective action program.

We'll continue general monitoring for new leakage using the structures monitoring program per ASME section 11 IWE program for the remainder of the plant life.

For any new issues that are identified, we will be utilizing the corrective action program for evaluation and application of additional corrective actions.

We have performed evaluations of potential degradation for the steel containment vessel, the concrete, and the rebar.

With respect to the steel containment vessel, as previously mentioned, we have not identified any corrosion, nor have we identified any wall thickness concerns. All of the readings we've taken for wall thickness have been at or above nominal. The water that would be done in that lower elevation of containment would be essentially stagnant. Oxygen would be consumed to preclude

NEAL R. GROSS

continued corrosion. The alkalinity from the concrete -- we've demonstrated that that would elevate to a pH sufficient to inhibit corrosion in those areas. The containment vessel corrosion behind the concrete in the areas wetted by the cavity leakage, we would expect to be no more than 10 mils. 8 MEMBER ABDEL-KHALIK: Based on what? MR. SKOYEN: That was based on evaluation and the different factors that the time that the 10 11 refueling cavity actually leaks. It's very limited. 12 It's only during outages for approximately 15 days -the buffering effect that you get from the concrete 13 and elevated pH. 14 MEMBER ARMIJO: This is 10 mils over the 15 16 whole life of this leakage? 17 MR. SKOYEN: That's correct. 18 MR. BARTON: How many years has this been 19 going on? 20 MR. SKOYEN: In performing our evaluation, 21 we assume the entire plant life, although there wasn't evidence of it prior to 1987. 22 23 With respect to the concrete, long term exposure to the acid can dissolve the calcium 24

hydroxide in the cement binder in the soluble

aggregate.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Dissolving the calcium hydroxide neutralizes the acid if it's not refreshed, so if it's not continually refreshed, that reaction would stop.

The refueling cavity liner -- our evaluation has concluded that there would be negligible effect on the refueling cavity walls and floor because those are all fortified feet thick with the exception of one location which is adjacent to the transfer tube. That evaluation of that area is still ongoing.

At the containment vessel inside surface, the water would essentially be stagnant so the acid would be neutralized by the alkalinity in the concrete, again having minimal effect. It's not refreshed other than during refueling outages.

Cracks in the concrete -- essentially the same situation. The water would be stagnant so the acid would be neutralized by the alkaline in the concrete there as well.

MR. BARTON: How long after refueling outage do you think that the containment vessel remains wet? That that area remains wet?

MR. SKOYEN: How long will the area remain

wet?

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. BARTON: What do you think, yes, after refueling outage and leakage stops, how long do you think that area remains wet?

MR. SKOYEN: At the lowest elevation of the containment vessel, potentially it could remain wet indefinitely.

MEMBER SHACK: Is that how you calculated your 10 mils? That indefinitely at some pH that you assume from the concrete?

MR. SKOYEN: That's correct.

MEMBER SHACK: Okay.

MR. SKOYEN: With respect to the rebar, there is some potential for the refueling cavity leakage to reach re-bar in the cracks. Corrosion of the wetted rebar would be inhibited, again, by the alkalinity in the concrete promoting a protective layer.

Qualitative assessment concluded that there had been no significant signs of corrosion. We've not seen any spalling, concrete cracking at these locations. We've only had minor rustings that have come through hairline cracks.

So the conclusion is that the corrosion of the rebar, whether wetted periodically or

continuously, would be minimal. CHAIRMAN RAY: Well, that's the rhetoric that I was referring to. We don't need to go into it, I don't think, if we're committed to stop the leakage. The main conclusion one draws from this is it's not an alarming condition. MR. SKOYEN: Right, correct. 8 CHAIRMAN RAY: But if we stop it, then we don't need to draw the ultimate conclusions that 10 11 you're presenting here. 12 This is an awkward context for us to address fundamental issues like you're dealing with 13 here. We'll talk to the staff about that later. 14 MR. SKOYEN: Right, I understand. 15 16 MEMBER ABDEL-KHALIK: But the statement 17 has been made that leakage is unacceptable. 18 MR. WADLEY: Yes, that's true. Correct. 19 MEMBER ABDEL-KHALIK: Yet this has been 20 going on for more than 20 years. Is this sort of a 21 new management attitude? MR. WADLEY: Well, we've tried a number of 22 23 different methods to solve the problem. Performing the root cause evaluation provided some additional 24 25 insights that we didn't -- we tried to do a fix,

quick fix, with caulk and strippable material. This approach is a more rigorous approach to a deeper understanding of what we're dealing with so I think we have a better solution. It's never been acceptable, but we've never spent the time and the effort to get to the details. We didn't come up with a proper solution. 8 MEMBER ARMIJO: I just had a quick question. When you excavate under that sump C, now that won't be the lowest point on your containment 10 11 vessel. Is that a concern, you know, that you're 12 going to look for evidence of water or corrosion 13 damage, but that's still -- I don't know -- maybe a foot or two higher than the bottom. I don't know. The 14 15 low point of the vessel seems to be -- you won't ever 16 see that. 17 MR. SKOYEN: Tom, do you know the difference between exact elevation? 18 19 MR. DOWNING: Yes. If I'm understanding 20 your -- again, my name is Tom Downing from Prairie 21 Island. 22 If I understand your question, you're 23 asking about the location of the excavation and it's

MEMBER ARMIJO: Yes.

not bottom, dead center.

NEAL R. GROSS

COURT REPORTERS AND TRANSCRIBERS 1323 RHODE ISLAND AVE., N.W. WASHINGTON, D.C. 20005-3701

24

MR. DOWNING: That's true and I would agree that in an ideal world, it would be nice to be able to excavate bottom, dead center because if water had pooled there, that you would expect it to be.

It's just not really physically possible in that the concrete is so thick there. It gets three to four feet thick and even trying to excavate through 16 to 18 inches of concrete with a mat of

steel at the top and then a double mat towards the bottom would be very difficult.

2

8

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MEMBER ARMIJO: No. I'm just -- I agree with that and I wouldn't expect a pool of water there. I just -- if it's spreading out and it's wetted, I just wondered how many inches difference there is between the dead center bottom and where you're excavating.

MR. DOWNING: My recollection, from looking at past drawings and trying to determine how thick that concrete is, is that it's approximately eight feet from bottom, dead center where we're going to be excavating.

MR. ECKHOLT: What's the difference in elevation, Tom?

MR. DOWNING: Yes, the difference in elevation -- again, this is just pure -- my

recollection. I think it was in the realm of about a 2 foot and a half. It's the 105 foot containment and then it comes up as an ellipse so if you assume it's a perfect ellipse, you can kind of figure that out. MEMBER ABDEL-KHALIK: And the purpose of this is to confirm that your 10 mil calculation is 8 correct? MR. SKOYEN: That's correct. To assess at 10 that particular location, ensure that our centers are 11 correct, as well as provides us an opportunity that 12 if any water has pooled there, to evacuate that 13 water. MEMBER ABDEL-KHALIK: Do you know the 14 15 thickness of the containment anywhere to within 10 16 mil accuracy? 17 MR. SKOYEN: We have performed containment 18 vessel inspections as we mentioned previously, both 19 from the annulus in the transfer tube area and at the ECCS sump. Within 10 mils of accuracy is what you're 20 21 referring to? 22 MEMBER ABDEL-KHALIK: Right. Anywhere. 23 MR. SKOYEN: We know the nominal plate thickness that was delivered so we have a fairly 24 25 strong understanding of what the thickness will be.

MR. ECKHOLT: I think the UT measurements have been pretty uniform. MR. SKOYEN: They've been fairly consistent uniform. CHAIRMAN RAY: Well, the excavation isn't intended to verify the 10 mils, I don't think. MEMBER SHACK: But you don't want to see 8 significant corrosion there because then it raises Sam's question. Exactly how much corrosion is significant may be argued but --10 MEMBER ABDEL-KHALIK: But the presentation 11 12 earlier indicated that this analysis led you to the 13 10 mil estimate was done in a very conservative way. MR. SKOYEN: That's correct. 14 15 MEMBER ABDEL-KHALIK: So in a sense, by 16 doing this, you're trying to confirm that your 17 analysis was indeed conservative, that indeed that 18 reduction and thickness, if any, does not exceed the 19 10 mil. The question is, how can you tell? 20 MR. SKOYEN: We would have a pretty good -21 - from the surface examination, we would also have an 22 idea if there had been any reduction, evidence of any 23 corrosion. MEMBER ABDEL-KHALIK: Okay. 24 25 CHAIRMAN RAY: You also had some

experiments done by your consultants, I believe, and those ideal experiments showed it was very low. I just think 10 mils is a very small number. I would have put more windage on that.

MR. WADLEY: And I appreciate the question and the comment.

MEMBER MAYNARD: I understand that the conclusion on the significance here. I'm just not sure how long that's valid. The concrete kind of neutralizing the boric acid -- you do have a chemical process going on and I don't know how long that can go on without starting to degrade the concrete or the rebar.

At some point, you lose the ability to continue to neutralize it. I don't know if that's 1000 years or if's that's five years. I don't have a feel for that, but I'm kind of curious as to how long those conclusions are good for.

MR. DOWNING: Hi. This is Tom Downing again. The 10 mils was based on 36 years of operation to date. Again, we have not see any corrosion.

We do not believe there's any corrosion, but we would expect a similar evaluation for 36 years forward so that a total over 72 years is potentially 20 mils.

NEAL R. GROSS

81
CHAIRMAN RAY: That's what I was referring
to, Otto, and I mentioned this is an awkward place to
try and deal with fundamental physics of something
like what's the threat of borated water in the wrong
place for a long time, which is not to say that we
shouldn't have some way of dealing with that.
It's just that I'm not sure that all the
work the applicant has done here, we can conclude is
persuasive. The inspection of the
containment itself by this excavation was what I felt
was most valuable and the commitment now heard to
arrest the continued leakage. Go ahead.
MR. SKOYEN: Okay. Just in conclusion, the
expected containment vessel corrosion behind the
concrete in the wetted areas, we would expect to be
minimal, as we've been discussing.
We would also expect the concrete
degradation and any associated rebar corrosion not to
have had a significant effect on the reinforced

concrete that has been wetted in a leakage.

CHAIRMAN RAY: Okay, we're almost on time. MR. ECKHOLT: Almost, just a final summary.

The LRA was developed by an experienced team. It conforms to the regulatory requirements and

NEAL R. GROSS

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	follows industry guidance.
2	Prairie Island will be prepared to manage
3	aging during the period of extended operation.
4	CHAIRMAN RAY: Would you put up your back-
5	up slide 49, please? I want to make sure that members
6	still have the list here. We've read about many of
7	the items that are accepted here.
8	I don't recall reading about the steam
9	generator tube integrity program exception. Can you
10	comment on that?
11	MR. ECKHOLT: Phil, can you touch base on
12	that?
13	MR. LINDBERG: Excuse me. This is Phil
14	Lindberg, Xcel.
15	The exception to the steam generator tube
16	integrity program falls in the category of using a
17	later revision of an industry standard then what's
18	recommended in GALL.
19	I believe it's NEI 97-06 standard. I
20	believe we used Rev 2 where GALL recommends Rev 1, so
21	that's the exception.
22	CHAIRMAN RAY: That's why I didn't read
23	about it, I guess. All right, other questions of the
24	applicant.
25	MR. BARTON: I got there's a

description in the LRA on the stem generator system.
You mentioned unit 1 steam generators have flow-
limiting devices, steam nozzle for main steam line
break limits steam flow, but on the second unit, you
don't mention anything about the flow limiting
devices in the case of a main steamline break. You do
have them?
MR. ECKHOLT: Yes, they're intervaled in
the main steam line. Richard, can you?
MR. PEARSON: This is Richard Pearson. The
flow limiting devices in the steam nozzle exist only
on the unit 1 replacement steam generators.
For unit 2, there is no flow limiting
orifice, so the break at the top of the steam
generator sees the full opening of the steam outlet
nozzle.
MR. BARTON: So limiting the flow limiting
device is somewhere in the steam line through that?
MR. PEARSON: Yes, just downstream of the
elbow at the top well, there is a flow-limiting
device. It's the flow orifice and that does limit
flow for the breaks downstream of the flow element.
MR. BARTON: Okay, I was just wondering
why you described the unit 1 was and unit 2, you

didn't --

MR. PEARSON: Because it's part of the new 2 steam generator. MR. BARTON: I got you, thank you. CHAIRMAN RAY: Speaking of steam generators, you said unit 2 replacement is planned, Mike. MR. WADLEY: 2013. CHAIRMAN RAY: 2013. Any other questions? 8 We will take a 15 minute break and return at 10:25. (Whereupon, the hearing went off the 10 record at 10:07 a.m. and resumed at 10:23 a.m.) 11 12 NRC PRESENTATION 13 CHAIRMAN RAY: Back to order, please. We will now hear the NRC staff presentation on Prairie 14 Island. Mr. Plasse? 15 16 MR. PLASSE: Yes, good morning. My name is 17 Rick Plasse. I am the project manager for Prairie 18 Island's license renewal application. 19 For today's presentation, we'll be discussing the results of the staff safety review of 20 21 the application. 22 With me, to my right is the lead 23 inspector from region 3, Dr. Stuart Sheldon. He led and conducted the regional inspection in January. 24 25 Stuart will be presenting the results of that

inspection.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

Seated in the audience are various members of the NRC staff that participated in the reviews. Results are contained in the SER with open items. They're here to assist and answer any questions that may arise.

For today's presentation, we'll start with a brief overview of the application and then a discussion on section 2, scoping and screening results.

Then I'll turn it over to Stu to address the regional inspection, followed by a review of section 3, aging management program and aging management review results, and then section 4, TLAA discussion.

The applicant discussed the open items in detail. Brian had mentioned staff is continuing to make progress on the open items. Some of it was due to timing of some of the recent information provided by the applicant.

I will provide a snapshot of the status of those items at the applicable portions and sections where we have a discussion on those items.

Next slide overview, I think the applicant pretty much touched upon this. I don't want

to go back and rehash it unless someone wants me to.

I'll go to the next slide.

Overview -- the SER with open items was issued June 4. There were the three open items as discussed in detail, which we'll touch upon.

There were 168 REIs that were issued as the staff went through its review process. There's 36 commitments to each unit. There's no unit-specific commitments. They're all pretty much applicable to both units.

As you probably noticed, I believe there's more numbers. In the actual commitment list, there was a couple of items which were updated that were in use and there were several environmental commitments that are in the record, in the commitment list. But as far as the safety review, there's 36 commitments for each unit.

This slide just gives a list of the activities that the staff and the region undertook going through the review. We have the scoping and screening methodology, which was in August of `08. We have the aging management program documents, which was September of `08. The regional inspection was in January of `09. They had a formal exit in February of `09.

NEAL R. GROSS

Then we had a follow up audit on the topic that we had and the technical discussion earlier on reactive cavity leakage -- a one day audit included one of our contractors and some of the NRC tech staff.

A couple things I just wanted to note. As the staff completed its review, had completed its audit, we had a couple issues that we still needed follow up. We had follow up REI's.

Also, we asked Stu, as part of his review, to do some reviews in the field in January and give a couple of examples of those. We talked in detail about the medium voltage cables and the manhole, the 13.8 kV safety related manhole.

When we did the audit in September, we had the applicant open that manhole for our audit team to inspect, so we inspected that in September. We did not see any evidence of any water intrusion.

Also, in January, when the region was there, they opened it again in the cold of the winter of Minnesota and I believe they didn't see any evidence also.

And one point I'd like to make, the applicant mentioned in their slide on the medium voltage cables, the recent failure they had with the

NEAL R. GROSS

circ water. That is a non-safety related circ water pump.

They are doing a root cause and there will be an LAR and any extended condition, they'll address in that LAR. It did result with a plant trip, so that LAR is not due till 60 days following the event. I believe the event was mid-May -- May 18 or so.

With that, I'll go to the next slide.

MEMBER ABDEL-KHALIK: I know it was kind of facetious, talking about the mid-winter in Minnesota, but are there any submerged cables at all on site? If they go through the winter and they go through a freezing, thawing process, is that more damaging than wetting and drying cycle?

MR. PLASSE: Anyone on the staff like to respond to that one?

MR. LI: My name is Rui Li. I'm an electrical engineer for the division of license renewal.

I went to Prairie Island for an audit.

The cables in Prairie Island are direct buried, so most of the cables are underground so you wouldn't be able to see them.

Unlike most of the other plants that we

NEAL R. GROSS

2

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

visited previously, there is only one manhole in this plant.

MEMBER ABDEL-KHALIK: But my question pertains to whether or not going through a freezing, thawing process would be more damaging than wetting and drying cycles?

MR. LI: I can get back to you on that, but the point I'm trying to make is because these cables at Prairie Island are on direct bury, it's hard to observe that phenomenon in this place -- to see if there's actually any ice underneath close to the cables.

MEMBER ABDEL-KHALIK: Okay, thank you.

MR. MCCONNELL: This is Matthew McConnell with the electrical engineering branch. I was involved with the review of the Prairie Island license renewal application.

To answer your question, the answer is I don't know. I mean, it may be, It depends on the chemical make up of the cables, the insulation and type, and how long the cables would be exposed to such condition.

My understanding is there's no evidence of that type of activity going on at Prairie Island, specifically with safety-related cables, so that

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

phenomenon really has not been addressed as far as I'm aware.

MEMBER MAYNARD: I would suspect that most of the cable would be below the freezing level there, but there may be areas where --

MEMBER STETKAR: Yes.

MEMBER ABDEL-KHALIK: I mean, if they have an inspection frequency of once every two years, it is conceivable that you can accumulate enough water in a pool box without detecting it. That water would go through the water, freeze, and you would have a cable that would undergo that kind of cycle.

MR. HOLIAN: This is Brian Holian. Just a reminder for the committee, they did start off with a quarterly inspection program and hopefully, taken that through several quarters to check that very theory.

But we were talking about the regional aspects too on how well they follow through on their commitments in that aspect and what those commitments are based on. So I'm sure Dr. Sheldon will be able to monitor. Hopefully, we've historically looked at did they do enough to base their current inspection frequency on.

I don't know if the region can talk to

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

that, but that is one time the staff will continue to 2 follow. MEMBER ABDEL-KHALIK: Thank you. MR. PLASSE: Okay, to go on to section 2 of the application. The applicant had mentioned that they have now placed the radwaste decay tank in scope. 8 By letter dated June 5, the applicant 9 included the waste gas decay tank within the scope of license renewal. I said I'd give a status of the 10 11 ongoing activities. 12 The staff has completed its review of the information provided by the applicant in the June 5 13 letter. I have been told by the staff that this item 14 can be closed and it will be documented in the final 15 16 SER. 17 With that, for section 2.1, the staff's audit and review has been concluded that the 18 19 applicant's methodology is consistent with 54.4 for 20 in scope and 54.21(a)(1) for components subject to an 21 AMR. Section 2.2, the staff found no omissions 22 23 of plant-level scoping systems and structures within the scope of license renewal. 24

NEAL R. GROSS

Section 2.3, mechanical systems -- the

staff completed a review of all systems. As documented in the LRA, there were 37 mechanical systems. 29 of the systems were a balance of plant auxiliary and steam and power conversion systems.

I've got a sampling of some of the things that were added to scope based on RAIs, plant floor drains, flex connections, fire dampers, the waste gasket K-tank. There were several stainless steel flex connections in the heating system, diesel generator and support systems.

Also, several boundary drawings were noted where in-scope components were inadvertently shown as out of scope on the drawings.

The components, however, typically were already addressed in the LRA tables and therefore, there were no LRA changes required. But the staff did do a 100 percent and those RAIs are documented in the SER where these applicable things were addressed.

Section 2.4 and 2.5, there were no omissions of components within a scope of license renewal. However, just as a note, during the acceptance review, a discussion was made with the applicant to understand the station black-out, which the applicant kind of discussed in their presentation, so there were some additional scope

NEAL R. GROSS

adds in the switchyard, which the applicant addressed with the blue coloring in his slide, slide number 13.

With that, with the one open item, which the staff has since determined should be able to be closed, there were no omissions from the scope of license renewal in chapter 2.

At this time, I will turn the presentation over to Dr. Stuart Sheldon to discuss the regional inspection.

MR. BARTON: Rick, before you do that, I have a question. What's the current staff position on fuse holders? Has there been a change to GALL or something that I missed?

Since day one, I always thought fuse holders ought to be in scope for aging management programs. I keep beating a dead horse and was told to get off of it, and now I notice that in the applications I've been reviewing in the past year, people are now starting to have aging management programs for fuse holders. I don't understand what's going on.

MR. NGUYEN: This is Duc Nguyen from license renewal. Right now, we don't intend to change the GALL. It can sit with the regulation if the fuse folder at the assembly, then this is our scope of the

NEAL R. GROSS

aging management review and depending on the plantspecific, if the fuse holder will determine that they
have no aging effect, then they are not required in
the aging management program. This is a plantspecific review.

MR. HOLIAN: This is Brian Holian. Just to add on to that, I think you've seen some, maybe a consistency over the years.

MR. BARTON: Yes.

MR. HOLIAN: Just as a reminder, that plant lighting issue was a similar item in here.

License renewal, if the applicant puts it in scope, we'll take it.

So that's a short answer. If they go ahead and add it and it's part of their program and they do it for simplicity or however they're organized on site by discipline, we'll keep it in scope. So that's what you're seeing here.

We are going through a GALL update now.

People are giving us comments. I know fuse holders is one of those areas where historically it's been thought should it be in scope, generically or not.

I think you heard from a reviewer that our initial thought is that it still would not be generically required to be in scope. We'll be able to

NEAL R. GROSS

ferret that out this year as we finish our reviews of that.

MR. BARTON: Thank you.

MR. SHELDON: Okay. I'm Stu Sheldon. I led the license renewal inspection for the region at the end of January of this year.

We had five experienced inspectors and one newly qualified inspector as an observer on this inspection.

We conduct the inspection under inspection procedures 71002. Our focus is on scoping and screening in aging management. We focus on (a)(2) non-safety affecting safety systems. Our primary means are physical walkdowns of systems to verify their proper scoping and material condition.

We didn't identify any issues within the scoping aspect of this. They're very conservative in their scoping aspects. We did identify a few minor material condition issues that they entered in their corrective action program some corrosion that they had not identified previously, some very small fuel oil leaks, that type of thing.

We reviewed 24 of the 43 aging management programs. This was conducted by reviewing their program documentation. Our focus is on implementation

NEAL R. GROSS

of the existing programs -- that they have an existing program.

We also conducted walk downs of any

We also conducted walk downs of any applicable systems -- if the program has an applicable system, we conduct walkdowns then. We also had the opportunity to accompany a unit 1 containment entry. During this inspection, one of our -- ISI inspector -- would have to go within the unit 1 containment and in the annulus area surrounding the --

MR. BARTON: What did you think of the material condition inside containment?

MR. SHELDON: My report is that it's very good. He did identify a leaking valve while he was in there. I don't remember how many drops per minute it was. It was a very small leak on a valve that -- that's what they were in there looking for.

CHAIRMAN RAY: Are you talking about a packing leak?

MR. SHELDON: Right, packing leak.

MR. BARTON: That seems to be an issue. I think you pointed out in your inspection report that there have been historically a lot of packing leaks and boric acid leaks, etcetera. Is that still an ongoing issue or have they got their hands around

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	that?
2	MR. SHELDON: I don't remember
3	MR. BARTON: That was in the audit report
4	MR. SHELDON: Okay, I don't remember
5	making that kind of statement.
6	MR. BARTON: As far as, during your
7	inspection, did you look at that? Was that an issue?
8	MR. SHELDON: The ISI programs, we did
9	look at. We didn't find any issues with what they
10	were doing on their ISI.
11	MR. BARTON: I was just wondering whether
12	it was a training issue or whether it was still
13	ongoing.
14	It was in the audit report. It wasn't
15	you guys probably you didn't point that out. Do
16	you know, Rick?
17	
18	MR. PLASSE: Maybe some of the staff can
19	help me out. There were several RAIs and also
20	subsequent follow-up RAIs on the boric acid program.
21	MR. SHELDON: We did have some questions
22	associated with it on whether they were meeting the
23	code and leaving the boric acid on the components.
24	The results of that is no, they are not.
25	They are cleaning it off not necessarily during

that containment entry, but when the problem is corrected, then the boric acid is cleaned off. There were questions concerning that.

MR. PLASSE: My recollection is -- and the applicant can, if I misrepresent something, they can correct me -- is that they don't intend to leave boric acid residue. They intend to clean it up as soon as they can.

In some cases, there may be a dose case or something where they make a decision to not get it at that point and time, but they evaluate those specific cases. Erach did those RAI's. He can probably --

MR. PATEL: Hi. I'm Erach Patel. I'm with the boric acid corrosion program.

Yes, you're right. They did have a significant temporal valve packaging -- packing their leakages on. They took a generic evaluation of that and they reviewed live load packings and they replaced a whole bunch of packings and they're trying to make sure that they're going into the source of the leakage itself to make sure that they prevent those leakages.

So the corrective action program does include a whole number of changes in the valve

NEAL R. GROSS

packings.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. BARTON: Thank you.

MR. SHELDON: As part of our review, we also interviewed plant personnel, specifically the program owners who are going to be responsible for implementing these programs to verify that they understand what the program is and are involved with the development.

Our operating experience review consisted of reviewing system health reports, program results from sampling programs, and we had access to the corrective action program and did searches on our own to look for anything that might be inconsistent with what they said in their application. We did not identify anything there.

One unique aspect of this is we had an observer from the Prairie Island Indian community. On our inspection, the tribal counsel president of the Prairie Island Indian community came and observed as we did our inspection.

Of the aging management programs that we reviewed, this is a list of those which we identified some sort of issue. Primarily, they were issues with -- the program was stated as consistent with the GALL and there were minor differences between what we read

1	as being required of the GALL and their procedures.
2	For example, with the external services
3	monitoring program, the applicant agreed to improve
4	their procedures to add specific acceptance criteria
5	for degradation and include other types of
6	degradation besides just corrosion, like blistering
7	paint, flaking paint, that sort of thing.
8	MEMBER ABDEL-KHALIK: Back to the previous
9	slide, is there a system health report for the
10	refueling cavity?
11	MR. SHELDON: I couldn't tell you that.
12	Does anybody over there can answer that?
13	MR. MCCALL: Yes. This is Scott McCall.
14	I'm the system entering manager at Prairie Island.
15	There's not a specific system health
16	report for refueling cavity. However, the spent fuel
17	pool and its associated components there is a
18	health report for that.
19	MEMBER ABDEL-KHALIK: What does the health
20	report say system health report?
21	MR. MCCALL: I has have there been
22	problems with the system.
23	MEMBER ABDEL-KHALIK: No. Specifically
24	with regard to the leakage issue.
25	MR. MCCALL: For the refueling cavity? It

101 says that there has been problems in the past regarding that. However, we have used, like we previously talked about, means to arrest the leakage. MEMBER ABDEL-KHALIK: And this problem has been documented in the system health reports for the past 20 years? MR. MCCALL: No. System health reports have really only been around the station in the last

five years, so five to six years. Don't quote me on the exact date, but we've not had system health reports since the late 80's.

MEMBER ABDEL-KHALIK: Thank you.

MR. BARTON: Stu, during the inspection on the aging management review of the closed cooling water system, your inspection team discovered that the site hadn't taken some chemistry samples for several years due to a shortage of chem techs -- this is probably a question for the applicant.

They took the samples while you were there, but my question is, if I hadn't taken a sample for three years, do I really need the samples? And have you corrected the chem tech issue, shortage of chem techs?

I guess I'm addressing that to the applicant. It was an item that you brought up in your

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

inspection report.

3

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. ECKHOLT: This is Gene Eckholt. The answer is yes, we need to take the samples. They weren't stopped because there was a lack of need or a perceived lack of need. There were some personnel losses that we responded to probably inappropriately by management, supervision at the time that suspended the inspections. That has been remedied. They are being taken again.

These are EPRI-required parameters we're monitoring, They are to monitor the long-term condition of the components, so they were never stopped because of any perception that they weren't important.

MR. BARTON: Since that's been corrected and they are important and you are taking them as scheduled. Is that what I'm hearing?

MR. ECKHOLT: That's correct.

MR. BARTON: Okay, thank you.

MR. SHELDON: Okay, any other questions about the aging management program?

So the results of our inspection, which we presented at our February 18 public exit meeting, is that our results support a conclusion that there's reasonable assurance that the effects of aging will

be adequately managed. We found scoping of the non-safety systems was acceptable and that documentation supporting the application was auditable and retrievable. I've listed the inspection report there. The next few slides deal with current licensee performance. All other performance 8 indicators are currently green. Both units are in the regulatory response column, column 2, to do some white inspection findings. 10 11 The fourth quarter 2008 finding was aux 12 feedwater pump failure because of a mispositioning of 13 a valve. The most recent white finding was a transportation issue where the package arrived and 14 the survey showed that it had existed DOT limits. 15 16 CHAIRMAN RAY: Is the aux feed pump turbine driven or motor driven? 17 18 MR. SHELDON: I don't know. I can't tell 19 you on this particular pump. 20 MR. PLASSE: I believe it's turbine 21 driven. 22 MR. SHELDON: But it was a discharge 23 pressure switch that was isolated to protect the pump so that it doesn't build up discharge pressure. 24

NEAL R. GROSS

MR. MCCALL: I can speak to that.

MR. SHELDON: Go ahead.

MR. MCCALL: Scott McCall again. It was a turbine driven aux feedpump. Was that the question?

CHAIRMAN RAY: It was. I was interested in then, but I've already found out what the misalignment was.

MR. SHELDON: That's all I have.

MR. PLASSE: Any more questions? Okay, we'll move on to section 3. This first slide shows the break down of section 3. It's pretty standard with license renewal applications.

I did not plan on covering each subsection. I will touch again on the open items and other information that may be of interest.

The first slide, that's just documents. I think the applicant had a similar slide. He might have broken them up a little differently.

This shows the breakdown of the aging management programs. 14 were identified as new programs. There's a total of 43 programs. 29 were existing programs. 22 were identified as consistent with GALL. 9 were identified as consistent with the GALL with enhancements. 4 were ere identified with exceptions to GALL. 6 were identified with exceptions and enhancements to GALL. 2 were identified as plant-

NEAL R. GROSS

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

specific programs. We have a bullet.

We mentioned earlier about the contentions. One of them was they didn't have a 10 element program, nickel alloy, which they put a plant-specific program March 27. Also, the vessel internals program, which is an open item I'll get to on a subsequent slide. With that, unless someone has question on the break down of the AMPs, I'll move to the next slide.

The vessel internals program, as Brian had mentioned in his lead-in, is a timing issue. The applicant put in on May 12 -- they voluntarily submitted an amended program with the 10 elements. The staff is in the process of reviewing that.

It also has additional AMR line items, which the staff is going to have to digest the document, so that is a task that's in place right now. That will all be documented in a final SER.

I don't have anything negative with respect to the letter at this point, other than that the staff is still continuing to review that item.

MEMBER SHACK: Just on a generic question

-- that commitment for the PWR internals has been in

all the license renewal applications and the 24 month

clock is ticking.

When is the first guy up to the plate? When are we actually going to see a plan? MR. CHERUVENKI: This is Ganesh Cheruvenki. I work with the MMR, vessel and technical branch. The first one is being reviewed. They submitted the PWR AMP, vessel internals. We are 8 currently reviewing it. We are also reviewing MRP-227, which was submitted in early January of this 10 year. 11 So we are trying to issue the SC some 12 time next year for both the reports, AMP and also MRP-227. 13 MEMBER SHACK: Okay. 14 MR. PLASSE: Next slide is relative to the 15 16 ground water in the area of the plant. What the data 17 shows is that the ground water in the area of the 18 plant is not aggressive to rebar embedded in 19 concrete. The data and the results are in a table. 20 The structure monitoring program includes 21 sampling of the ground water and river water 22 chemistries once every five years for the period of 23 extended operation. The bottom line is the ground water is 24 25 non-aggressive to rebar in concrete.

The next item -- we went through at length with the applicant on the status of this open 2 item with respect to the water seepage from the reactor cavity. I don't have anything to add at this point, unless you have a specific question that you would like to gear towards the staff on the issue. MEMBER ABDEL-KHALIK: Have you done a sort 8 of a calculation that would show how much margin there is, so if they were to do an inspection and 10 11 find that there's a quarter of an inch of wastage, 12 would they still have plenty of margin? 13 MR. SHEIKH: My name is Abdul Sheikh. I work in the license renewal branch. So far, we 14 haven't done any calculations on this issue. 15 16 MEMBER ABDEL-KHALIK: Wouldn't it be a 17 reasonable thing for the staff to do? 18 MR. SHEIKH: Are you talking about the 19 liner? 20 MEMBER ABDEL-KHALIK: Right. We're talking 21 about 10 mils. What if it was 100 mils. What 22 difference does it make? 23 MR. SHEIKH: We looked at the report, which the licensee as applicant has produced and 24 25 there's not too much margin in their calculations. So

if it is, say 100 mils or 200 mils, it won't satisfy the code requirements. This is according to the licensing department. MEMBER ABDEL-KHALIK: Let me just try to understand what you just said. By reviewing the analysis of record, you have determined that they really don't have much of a margin. Is that correct? MR. SHEIKH: I have not looked at the analysis of record. I have looked at the report produced by the applicant in which they stated that there is not too much margin. MEMBER ARMIJO: Can you put a number on that? What do you mean by not too much? MR. SHEIKH: It is just barely -- I mean, it's like 1.5 inches thick, the containment. The actual figure quoted in the report was about that number. MEMBER SHACK: Remember, if you assume uniform thinning, you can't take all that much. You can take localized thinning, sort of a la that famous New Jersey plant. MEMBER ARMIJO: But the burden is going to

MEMBER ARMIJO: But the burden is going to be on the applicant to find this. Whatever they find, they're going to have to justify acceptability of it to be reviewed by the staff.

NEAL R. GROSS

2

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

MR. HOLIAN: This is Brian Holian again.

We had wanted to put this in -- the licensee did a good job, I think, in the presentation earlier. But in safety significance perspective, it's an item that we think we're ahead of. I mean, ahead of in some ways.

They've been living with leakage for awhile, but they've been allowed to live with leakage based on regional inspectors and other folks looking over their shoulders for years and assessing the safety significance.

So in this particular plant, they thought they've had it fixed a few times and that's come back at them. On safety significance though, we do believe that there have not been instances where there's been corrosion through and isolated instances.

I think that comment on the margin was more of an overall view. We'll take a look at that again closer. I think it was, as was mentioned there, kind of uniform thinning along that line.

We don't see that and we think the licensee is getting ahead of that, but I did want to mention that from a safety significance perspective. This is minor leakage, all within containment -- no isolated instances, so we think we're ahead of it. We

NEAL R. GROSS

have seen it on other plants.

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

I think license renewal has taken a closer look at it because this plant, in particular, raised the issue of what is the flow path. It was harder for the staff to understand here.

We had presented to this committee another plant a few months ago that had much larger leakage, but had a little better idea of where it was coming down from the refueling cavity -- out of the welds and almost straight down.

So that's one reason why, in particular, we're looking at an issue like this for, is the GALL sufficient? Is there any other aging mechanisms or programs that need to be in place to increase the inspection frequency as you go over longer periods of time?

MEMBER ABDEL-KHALIK: I was just trying to put this thing in perspective. When the applicant says they've done a conservative analysis and it shows that the maximum is 10 mils, I want to compare that against what margin they have.

It would seem like a reasonable question to ask for which somebody should have an answer right off the top of their head.

MR. HOLIAN: The applicant can respond to

NEAL R. GROSS

that, if you like.

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MR. DOWNING: Hi. My name is Tom Downing.

There are a couple of things one considers on that question. One was the design code of the vessel. It was built for section 8. Under that code, we calculated minimum thickness was 1.5 inches.

Now, that's very conservative in that pressure vessels are designed with a safety factor of 4. The allowable stress is 17.5 KSI. The actual minimum potential stress is 70. So consequently, you could potentially have thinning of 3/4 of the way all the way through wall and not expect the vessel to fail.

However, once the vessel is built and installed, it moves from section 8 code to section 11 code. Under section 11, any thinning will need to be evaluated. However, thinning of 10 percent or less is acceptable without further evaluation.

So consequently, we could have up to 150 mils of thinning over a very large area and immediately evaluate it as acceptable. Any more thinning would require further evaluation, but could still be acceptable under section 11.

MEMBER ABDEL-KHALIK: Thank you.

MEMBER STETKAR: Just to clarify my

NEAL R. GROSS

understanding of the leakage. There is no place where they have actually found evidence of leakage against the liner itself. Is that correct? MR. DOWNING: That's correct. MEMBER STETKAR: The places where they have found leakage is places where the liner is embedded between two layers of concrete -- one below and one above. Is that correct? MR. DOWNING: That's also correct. MEMBER STETKAR: Okay, thank you. CHAIRMAN RAY: The discussion just given, by the way, does appear in the response to one of the RAIs in part C. What I would observe, Brian, is that we've learned through bitter experience to be very concerned about leakage of borated water on mechanical components. We're now aggressively removing deposits of boric acid. We don't have any comparable way of assessing in a context like this what would be the significance of the leakage we're talking about here for structures or, in this case, the containment pressure vessel. It does seem as if we ought to -- I mean,

NEAL R. GROSS

the applicant has done all that, I think, in the

2

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

context of a license renewal application, one would expect him to do in terms of trying to address things such as the interaction between boric acid and concrete and the likelihood that it doesn't represent a threat to the rebar and so on and so forth.

And now we've been talking about the containment, which we have other reason to be concerned about as well, just from an experience stand point.

But what's lacking is some generic conclusion about this subject. I just think it would be bad for us to wait until we, in fact, discovered something that was seriously problematic to then say, well, we need to decide whether this is a serious problem or not.

As I said, the applicant has said we're going to stop it. Although it has gone on for along period of time, it doesn't -- we don't have any reason to think that there's a problem. Nevertheless, they're going to excavate and look at a sensitive area here and tell us, at least with regard to the period of extended operation, that it's okay.

So my personal view is that we've got as much from the applicant as we can, but still, it's not very satisfying that we don't have a better

NEAL R. GROSS

generic way of assessing these kinds of things and saying is this a big deal or not a big deal? Should we worry about it or not worry about it?

I'll just leave you with that comment. You can respond as you wish.

MR. HOLIAN: No, I think that's a good comment. Prior to making our presentation, we've come here particularly to talk on the license renewal presentation and oftentimes the staff doesn't bring in at these same meetings what we might be looking at generically or generic correspondence or even with research.

I know research is pushing NRR and the license renewal staff for operating experience on these type of issues. They are themselves working with EPRI on light water reactor sustainability and cables and concrete for extended periods. So there are actions back at the staff that we're doing.

We do interface from license renewals with the reminder with the ROP, reactor oversight process, for kind of moving inspection insights.

Should we be doing more from inspection oversight over the years for a problem like this? Is it worth more samples from an inspector? That's one piece.

We interface with the individual tech

NEAL R. GROSS

branches on the containment and the cables issue. We do, and I compare this to a recent issue with submerged cables. It's both a license renewal issue. It is in GALL and it is a current operating issue.

I don't know what the answer is,

particularly today. I did want to put it in the

safety significance that the issue does not appear at

the plants we've seen to date to be a current issue

over the next one year, two years, four years, five

years at all at any of these plants.

It is something we know we need to track through the period of extended operation and we will pick it up on a generic aspect in some of our task within OR.

CHAIRMAN RAY: Well, I don't know where we'll ultimately and the full committee come out on this, but I just don't think we want to leave the impression that while we read all of this stuff, we waited, and we've come to a conclusion in this context.

MR. PLASSE: Okay, any other questions for the staff on this issue?

Well, with that, that concludes the section 3 review with the exception of the two open - the new plant-specific vessel internals 10 element

NEAL R. GROSS

program and the cavity issue. The staff concluded that the applicant has demonstrated that aging effects will be adequately managed during a period of extended operation in accordance with 10 CFR 54.21(a)(3). Moving on to chapter 4, just as a note in section 4, we do not have any open items. This is the 8 general layout of section 4. MEMBER ABDEL-KHALIK: Back to the previous slide, if you don't mind. 10 11 MR. PLASSE: Sure. 12 MEMBER ABDEL-KHALIK: Have you reviewed 13 their root cause evaluation report? MR. PLASSE: We spent -- early on, I 14 showed a slide of the activities of the staff. The 15 16 staff sent out a team of three individuals -- our contract from Oak Ridge, a branch chief, and a tech 17 staff to review the root cause. 18 19 Subsequent to that, they had an RAI, 20 which went out, that the applicant responded to on 21 June 25. I can have someone from the staff who was on 22 that one day audit could speak to that, if you would 23 like? MEMBER ABDEL-KHALIK: And you're satisfied 24

that the root cause they have identified is indeed

1	the root cause?
2	MR. PLASSE: That item is still under
3	review. As I stated, the letter just came in June 25
4	Abdul spoke. He was the tech staff individual.
5	At this point, the staff is still
6	reviewing it. I can't comment unless they would like
7	to comment.

MEMBER BONACA: That is a critical element because they now have created a monitoring problem.

Then of course, you got the knowledge you're going to monitor and why you're monitoring.

12

13

14

15

16

17

18

19

20

21

22

23

24

25

10

11

MR. HOLIAN: Yes, I think from the staff perspective, we're still reviewing the root cause.

You heard another plant talk about refueling cavity leakage right through the weld connections halfway up -- refueling cavity.

So I know there's some thought of are the bolted connections the primary aspect of the leakage, but the staff will still cover that and cover that in the SER update for the final.

MR. PLASSE: Any other comments? Okay, back to section 4.As I stated, we do not have any open items in section 4 in TLA.

We do have a few slides of some items

NEAL R. GROSS

that have been of interest in previous ACRS subcommittees and we provide some of that data for your interest.

The first area is section 4.2, reactor vessel neutron embrittlement. Review was performed to evaluate fluence and embrittlement in terms of upper shelf energy and pressurized thermal shock. That will be the first couple slides.

With respect to upper shelf energy, the limiting beltline materials are stated. Of note is the last two columns, the irradiated Charpy V notch upper shelf energy at 54 effective full power years is 59 foot-pounds for unit one, and 57 foot-pounds for unit two.

The acceptance criteria of appendix G for a period in operation is greater than 50 based on since the upper shelf energy values are projected to be greater than the acceptance criteria at 50 pounds.

The vessel will have margins of safety against fracture equivalent to those required by appendix G through the end of the period of extended operation.

The next slide is with respect to thermal shock, pressurized thermal shock values. Again, eliminating beltline materials, the RTPTS off unit 1

NEAL R. GROSS

is 157 degrees Fahrenheit. For unit 2 is 136. The acceptance criteria for 10 CFR 50.61 is less than 270.

The staff independently calculated RTPTS values and these values are below the threshold criterion specified in 50.61. Therefore, end of light RTPTS values for all beltline materials at Prairie Island are acceptable.

Any questions? The final slide, metal fatigue, we kind of got into a little bit of discussion with the applicant early on.

The original application did use

FatiguePro. The applicant, as he stated earlier,

understood some of the recent issues in the industry

and they went through a contract with Structural

Integrity in June of `08, completed calcs, which was

commitment number 36, which they docketed April 28.

Staff competed a review and basically, the results of that were the 60 year fatigue reanalysis applicable to the 6260 locations. None of the cumulative usage factors were greater than one. As the applicant stated earlier, they will continue to manage the cycle counting in accordance with 54.21(c)(1)(iii).

Any questions on that? Okay, with respect

NEAL R. GROSS

to chapter 4 -- well, with respect to the application in total, pending resolution of the three open items, the staff has determined on the basis of its review, there's reasonable assurance that the requirements of 54.29 have been met with respect to managing aging effects through the period of extended operation for the Prairie Island plant.

With that, if there's any other further questions, that's the end of my presentation.

CHAIRMAN RAY: Thank you, Rick. I have at least one. You heard our discussion of the measurement of the condensate storage tank bottom thickness and the applicant's position that measuring the bottom UT on one tank is sufficient to verify the integrity of all three. I understand the staff has accepted that.

The explanation for it, I'm still somewhat at a loss for except maybe the dialogue that said well, if either of the other two were subject to a lot of corrosion, you would see some rust stains external to the tank.

Does the staff have anything to add to that?

MR. PLASSE: Well, a lot of -- we go through a lot of the one time inspections. There is

NEAL R. GROSS

sampling done to give you data points and then if you find something then you do extended condition -- maybe increase the scope.

We had several discussions on that particular issue and I probably could have the responsible individual speak to that.

CHAIRMAN RAY: Please.

MR. YEE: This is On Yee from the division of license renewal.

As the applicant stated, they're doing it on a sampling basis of the three tanks. They are going to do the inspection of one tank and then if based on those results, they'll extend the scope and increase the frequency depending on what it is that they find. Other than that, I'm not --

MEMBER BONACA: I have a related question.

If you find expected degradation in that tank, will

you -- do you have a program that says how you will

expand your inspection or are you just simply waiting

for it to happen and then you'll go to corrective

action program and figure out what you have to do?

That's important because one could have a narrow view and say okay, we're going to fix the tank and that's it or monitor the tank, but do nothing about the other two.

NEAL R. GROSS

Or you could have a comprehensive response that says since you have found a problem in this tank, I should expand it to the other two and have additional monitoring. We haven't heard anything about the fallback. MR. YEE: This is On Yee again. It's my understanding that of the inspection that they do on that one tank, if they find anything, they'll expand the scopes to the other tanks. If I'm incorrect, correct me. MR. LINDBERG: This is Phil Lindberg. That is correct.

MEMBER ARMIJO: The assumption is that all the tanks are identical. They've operated in the identical manner and they're all going to behave identically. I just don't see why that's a sound assumption.

CHAIRMAN RAY: One out of three -- the reference to sampling just doesn't seem to fit here to me because nothing has been done to demonstrate that the three tanks would be identical if for some reason there was water intrusion in one in the area of concern because of a failure of the seal at some time in the past.

It just seems very odd to have three

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

tanks like this and to decide that just one of them 2 needs to be inspected because it will be indicative of the other two. I'll leave it at that. MR. BARTON: I have a question. What's the consequences of a failure of the bottom of one condensate storage tank? CHAIRMAN RAY: Well, we're doing about a 8 seismic event presumably. Some design basis event, which there's a need for condensate to remove decay heat following the event. 10 11 It's very hard to say if there's one tank 12 or two of the three tanks that has a weakened tank 13 bottom. I guess you've answered the question. MR. HOLIAN: This is Brian Holian. Just to 14 15 add, the staff appreciates these comments because we 16 similarly during reviews, we bring up those same 17 questions and we're not constrained by GALL. GALL is 18 written as quidance. 19 We're continuing to learn from operating 20 experience, as we expect the applicant to do so. On 21 this particular item, we'll take a closer look at 22 their justification for three tanks in a similar 23 environment. On these tanks, we do expect current tech 24

specs control, water level in the condensate storage

tanks. Those get monitored by operators on a daily basis. So there's other layers of safety here for reviews that might pick up degradation in these tanks vice this one time inspection.

But the general thought about crediting one term inspections and going from there -- the last item I'll add in is that the region will be back.

They will be back at the 71003 inspections during another period of extended operation.

We've learned a lot from the region 1 inspections that we've just done on the plants prior to going into a period of extended operation. I know the next RIC that's going to be an item of discussion with the industry is in general.

But that's a time for us to learn and kind of generic industry learn on is this sampling appropriate for what we're seeing as they go into the extended period.

CHAIRMAN RAY: That's fair enough, Brian.

I would just say we sometimes forget that what we're looking at here are, as I say, design basis events and not simply as a leak developed during the course of normal operation. So I'm not sure that ongoing satisfactory operation is always an adequate indicator that we're in compliance with our design

NEAL R. GROSS

basis.

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

MEMBER BONACA: I guess my question goes in the direction of a one time inspection concept is you do it once because you believe that there is an effect in place. You just want to verify it.

By definition, when you do that, you don't provide any information about what else you may do should you find, in fact, that there is some degradation.

The implication is that you throw it to the corrective action program and then you establish some kind of program. So it's hard for us to make a judgement about the adequacy of the thought process there because of that.

I guess I don't have an objection with one time inspections, but I'm always left with a question in my mind of what answer can you except the licensee to do and I can see a big range, depending on how they respond to a root cause of an event of that nature.

MR. PLASSE: Let me see if I can maybe shed some light from a part 50 perspective. I used to be a resident and I worked for an applicant for 13 years as a licensing engineer.

Plants, every day that they find

NEAL R. GROSS

deficiencies, over a course of a year, a single unit will write 3000 corrective action reports. The challenge for the applicant for a licensee is to review those and take the appropriate corrective actions, look at extended condition.

That's always subject to second-guessing, Monday morning quarter-backing by their own people and the NRC. So to be able to sit here and tell you for any deficiency that the plant identifies, what are they going to do, what's the right thing -- that's kind of that little bit abstract.

But in the course of business, everything that they identify, it is a challenge to them to do the right thing.

Now, they don't always do the right thing in 100 percent of the cases and they have lessons learned and they try to improve it the next time.

The NRC will do what the residents -they do reviews on a daily basis and then
periodically, they do what's called a problem
identification review inspection, P&IR, or they look
at in total from a little bit of a big picture to see
is their corrective action program effective.

I mean, that's a little bit outside of this area, but that's --

NEAL R. GROSS

MEMBER BONACA: I agree with you. I believe the corrective action program is the foundation of everything. However, this proceeding here is about license renewal --MR. PLASSE: Exactly. MEMBER BONACA: Where you put on paper problems that you intend to implement to address 8 degradation, should you find it. So I don't think it's inappropriate. Now, the question is, to what extent 10 11 should you define that future. I agree that in some 12 cases, you don't want to have a fall back program 13 behind a one time inspection. I'm only saying that given that these 14 15 events have happened, I'm uneasy to not know really 16 how it's going to be handled. 17 Anyway, that's as far as I'll go. CHAIRMAN RAY: Okay, other questions for 18 19 the staff? Hearing none, thank you, Rick. 20 MR. PLASSE: Thank you. 21 SUBCOMMITTEE DISCUSSION 22 CHAIRMAN RAY: Okay, it's now time for the 23 subcommittee to have some discussion of the license renewal application for Prairie Island. 24

NEAL R. GROSS

I would like to start with our

consultant, John Barton, and ask him to summarize 2 anything that he'd like to put on the table for us to consider. MR. BARTON: The only concern I have in looking at all the documents I reviewed is the decision finally to do something with the cavity leak that's been going on for years and years without 8 really understanding maybe what damage has been going on for all these years. I mean, when you look at the fix, the fix 10 is relatively simple. I think when you have a problem 11 12 like this, you may try initially try to find the 13 leak, seal the leak. If that doesn't correct the problem, I 14 15 think you get in. You don't wait 30-something years 16 before you decide to make the correction. The 17 correction that they're going to do is relatively 18 simple. 19 As far as overall, that's the -- I don't 20 have any other issues that impede this applicant from 21 license renewal. 22 CHAIRMAN RAY: Thank you. Jack? 23 MEMBER STETKAR: I have no comments beyond John's and those that I made during this discussion. 24 25 I didn't find serious problems with what they were

doing.

I do have curiosity about the limitation of the inspection of all three condensate storage tanks, recognizing however, that the more likely thing that will happen is not necessarily a seismic event but just general leakage and its safety function is in aux feed as opposed to normal plant operation. So it depends on the magnitude of the catastrophic effect.

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

8

9

MR. ECKHOLT: This is Gene Eckholt. We should clarify. The condensate storage tanks at Prairie Island are not safety relayed.

MEMBER STETKAR: That's right.

 $$\operatorname{MR}.$$ ECKHOLT: The safeguard supply is river water to the aux feed pumps.

MEMBER STETKAR: Okay.

CHAIRMAN RAY: Well, they are, I assume, used for decay heat removal under some emergency conditions.

MR. ECKHOLT: That's correct.

MEMBER STETKAR: That's right and that puts them in scope.

MEMBER MAYNARD: But what they're taking credit for is the river water. In normal operation,

NEAL R. GROSS

they're going to use the condensate storage tank and in an emergency, they will, if the condensate storage tanks are there, so they can use the cleaner water. But the river water is always there available for an emergency.

MEMBER STETKAR: That's a one shot deal though. Then you replace the irrigation.

CHAIRMAN RAY: Okay, Sam?

MEMBER ARMIJO: I would like to see the staff's final evaluation of the root cause analysis and make sure that the staff agrees with the applicant on the source of the leakage.

It seems to me, based on what I've heard, that they have identified the leakage because they've been capable on more than one occasion of stopping it with the caulking. But I would like to see that.

I think the inspection -- they're going as far as reasonably doable to actually excavate underneath in that sump region. I think that will tell us a lot.

I think that 10 mil number is a little bit unnecessary to even talk about -- should talk in terms of how much margin there is. The applicant's clarification of that 150 mils is the real margin makes me a lot more comfortable.

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

131 Even if they find 20 or 30 mils of general wastage there, it's not the end of the world if they fix a leak. So that's all I have. CHAIRMAN RAY: Dana? MEMBER POWERS: I think we've identified

anything that's a smoking gun here. We've identified a generic issue that we need to think about doing something.

I'd say a question, which I think is an interesting one is, is freeze/thaw more damaging than wet/dry. I suspect that nobody has looked at that and that's a generic issue that needs to be put on the board some place. I'm not sure where we put that on the board.

But, I mean, we need to preserve -- I mean, it seems like a legitimate question, especially since we're finding an awful lot of plants in this licensure renewal phase that are getting their cables very wet.

Those in Florida probably don't have to worry about freeze/thaw. But as you move north, that freeze/thaw question is a question.

I personally am not familiar with anybody looking at it. As cable insulation ages, I would assume freeze/thaw cycles break it. I don't know.

NEAL R. GROSS

2

8

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1	CHAIRMAN RAY: Well, I suppose we would
2	assume, would you not, that direct buried cable is
3	subject to moisture by definition?
4	MEMBER POWERS: By definition.
5	MEMBER ARMIJO: How deep is it buried
6	below the freeze line?
7	CHAIRMAN RAY: Well, moisture and freezing
8	are two different issues. I just assume any direct
9	buried cable is subjected to moisture. Anybody who
10	says no, it's not, I think has got a big burden to
11	carry. Bill?
12	MEMBER SHACK: No additional comments.
13	CHAIRMAN RAY: Mario?
14	MEMBER BONACA: No additional comments. I
15	mean, I made a concern about the underground cables
16	being dealt with.
17	CHAIRMAN RAY: Otto?
18	MEMBER MAYNARD: I had a clarification and
19	a couple of generic items.
20	On the condensate storage tank, I'm not
21	really overly concerned from a safety stand point. I
22	believe that the probability of a catastrophic
23	failure without identifying some leakage would
24	probably be pretty darn remote.

I'm still a little bit concerned about

just the justification for doing one. It's not so much from the internal treatment of the condensate storage tank. It's more of -- I'd like to see a justification of why there's some type of external environment to water getting around into places on one that would not be getting around on another.

That's kind of part of the discussion that I'm missing on why one is acceptable as both the other. Or what external environment may occur as opposed to internal.

But again, from a safety perspective, they're not safety related, counting on the river water, and the chance of catastrophic failure is pretty low.

From just generic, there's two things.

One is for the industry. I haven't really seen any applicant come in and give a good presentation on what they're doing relative to water in the vaults and their understanding and justification for the frequency.

Everybody seems to be picking two year, one year, quarterly or whatever without much justification as to what -- that's all right, but that's more that I'm seeing from the industry than specific to this.

NEAL R. GROSS

The others on the NRC and this is on the 2 station blackout scoping as to where we stand with that. There still some inner discussions going on. We're spending rate payer and tax payers' money going ahead and doing things that may or may not be required. I think we really do need to get it resolved, the station blackout scoping, of just what 8 really is required on that. So those are my two generic comments. 10 CHAIRMAN RAY: On the last one, though, can you apply it more directly here to Prairie 11 12 Island? 13 MEMBER MAYNARD: Again, it's a generic statement because Prairie Island decided to just go 14 15 ahead and add it to the scope. So that's an 16 additional cost. That's an additional activity. 17 There's been additional discussions going on. 18 Ultimately, they may or may not end up being 19 required. 20 Those are the types of things that we 21 need to get a resolution on whether it is or it is 22 not. 23 CHAIRMAN RAY: But you wouldn't identify it as a comment that you would make in the context of 24 25 this application?

MEMBER MAYNARD: No. My last two comments were just generic. I'm just venting. I would not put them in any letter or any contact for Prairie Island.

MEMBER ABDEL-KHALIK: I have no additional

CHAIRMAN RAY: Well, my comment is in this generic domain, but I'm not sure that it doesn't -this isn't an opportunity to raise it. It's
basically, without repeating myself, the dialogue I
had with Brian about how it seems to me to be
unsatisfactory that we don't have more clarity around
the significance of, to structures, of borated water
leakage.

It's something that is not unknown.

There's a lot of rational and plausible easing about why it should not be a matter of concern, but when you talk about a long period of time, even assuming this fuel transfer canal is fixed, as Prairie Island intends, there's a larger question about well, from whatever source it may have come, it's there and it's there for a long, long time unless you have some way to remove it or discover that it's present.

I don't know that we have a good basis for feeling comfortable about it. I guess I'll use the example of, well, we've learned certainly on

NEAL R. GROSS

comments.

ferrous components to be very concerned, particularly if they're at elevated temperatures. If there's boric acid deposits, we want to discover them and remove them right away and make sure there's no degradation taking place. Lower temperatures in concrete rebar, different environment, but should we have no concern? I wish we had a better handle on that. But I don't think it applies here, other than this is simply a place where we might, as Dana commented in his case, identify it as something which deserves attention generically. But we can -- I don't if anybody else has anything more they would like to say that or anything else. If not, we're adjourned. 11:32 a.m.)

(Whereupon, the meeting concluded at

18

2

8

10

11

12

13

14

15

16

17

19

20


21

22

23

24

Prairie Island Nuclear Generating Plant ACRS License Renewal Subcommittee Meeting





Introductions

- Mike Wadley Site Vice President
- Gene Eckholt License Renewal Project Manager
- Steve Skoyen Engineering Programs Manager
- License Renewal Project Team and Subject Matter Experts



Agenda

- Background
- Operating History
- Plant Description & Major Improvements
- License Renewal Project
- Renewed License Implementation
- Specific Technical Items of Interest
- Summary



Background

- Plant Owner and Operator
 - Northern States Power Minnesota (NSPM)
 - Subsidiary of Xcel Energy
- Location
 - SE of Minneapolis-Saint Paul, MN
 - On Mississippi River



Background

- Two 2 Loop PWR Units
 - 1650 MW_t
 - 575 MW_e (Gross) per Unit
- Westinghouse NSSS
- Pioneer Service & Engineering -Architect/Engineer
- Dual Containment Design
 - Steel Containment within Limited Leakage Concrete Shield Building (5 foot annulus)



Background

- Once-Through Cooling Supplemented with Four Forced Draft Cooling Towers (Seasonal)
- Ultimate Heat Sink is Mississippi River via Cooling Water System





Operating History

- Construction Permits Issued June 1968
- Operating Licenses Issued
 - Unit 1 August 1973
 - Unit 2 October 1974
- LRA Submitted April 2008



Operating History

- Unit 1
 - Completed Refueling Outage 25 in Spring 2008
 - Lifetime Capacity Factor 84.2%
 - Cycle to Date Capacity Factor 96.6%
 - Next Refueling Outage Fall 2009
- Unit 2
 - Completed Refueling Outage 25 in Fall 2008
 - Lifetime Capacity Factor 86.5%
 - Cycle to Date Capacity Factor 98.0%
 - Next Refueling Outage Spring 2010



Major Plant Improvements

- 1983 Constructed New Intake Screen House and Reconfigured Intake and Discharge Canals
- 1986 & 1987 Replaced Reactor Vessel Upper Internals
- 1993 Added Two New Diesel Generators to Unit 2
 - Separated Units Electrically
 - Cooling Water Pump Upgraded to Safety Related to Provide Swing Backup to Diesel Cooling Water Pumps
- 2004 Replaced Unit 1 Steam Generators
 - Unit 2 Replacement is Planned
- 2005 & 2006 Replaced Reactor Vessel Heads



License Renewal Project

- Project Team
- Scoping
- Aging Management Reviews
- Aging Management Programs
- Aging Management Program Exceptions
- Time Limited Aging Analyses
- Commitments



License Renewal Project Team

- LR Engineering Supervisors are NSP Employees
 - Extensive Plant Knowledge and Experience
 - Trained and Mentored by Other Plants with Renewed Licenses
- Contract Support Staff has Significant LR Experience
- Plant Subject Matter Experts Provided Support
 - Reviewed LRA Input Documents
 - Supported NRC LR Audits and Inspection
- LR Project Team Engaged with Industry
 - NEI LR Task Force and Working Groups
 - Observed NRC LR Audits and Participated in LRA Peer Reviews at Other Plants




Scoping

- Process Consistent with NEI 95-10 Rev 6
- Boundary Drawings Highlight Components for All Scoping Criteria
- Switchyard Scoping Boundary Includes Breakers at Transmission System Voltage



Switchyard Scoping Boundary





Aging Management Reviews

- Aging Management Reviews Consistent with Guidance in NEI 95-10
- Maximized GALL Consistency to Extent Practical
- 89.2% of AMR Line Items Consistent with GALL (Notes A-D)



Aging Management Programs

- 43 Aging Management Programs
 - 29 Existing Programs
 - 14 New Programs
- Program Consistency With GALL
 - 31 Programs Consistent with GALL (9 include Enhancements)
 - 10 Programs Consistent with Exceptions (6 also have Enhancements)
 - 2 Plant-Specific Programs



Typical AMP GALL Exceptions

- Typical AMP GALL Exceptions Include the Use of:
 - More Recent Revision of Industry Standard than Revision Cited in GALL
 - Different (or additional) Industry Standards
 - Alternatives to Performance Testing specified in GALL
 - Alternate Detection Techniques or More Recent NRC Guidance than GALL Recommends
 - Alternate to Inspection/Test Frequency Specified in GALL



Time-Limited Aging Analyses

- TLAA Identification/Disposition Consistent with NUREG-1800 and NEI 95-10
- Evaluated In Accordance with 10 CFR 54.21(c)(1)



Commitment Management

- 36 Regulatory Commitments for Future Action Resulting from LRA
- Commitments are Tracked Through PINGP Commitment Tracking Program
- Commitments have been Assigned to Station Personnel for Implementation Prior to PEO



Implementation

- Implementation of LR Program is Responsibility of Engineering Programs Department
- Implementation will be Managed under Formal Change Management Plan
- All Aging Management Programs have Plant Owners
- Engineering Staff has already been Augmented to Implement Renewed License Requirements



Specific Technical Items of Interest

- Underground Medium Voltage Cables
- SER Open Items
 - PWR Vessel Internals Program
 - Waste Gas Decay Tank Scoping
 - Refueling Cavity Leakage



Underground Medium Voltage Cables

- Failure of Circ Water Pump Cable Caused Unit 1
 Trip in May 2009
 - Root Cause Evaluation and EPRI Testing of Cable in Progress
- Plant has Experienced Three Other Cable Failures
 - 2 13.8 kV (at cable termination)
 - 1 4.16 kV (at cable termination)
- Cable Insulation Testing Being Implemented by the Inaccessible Medium Voltage Cables Not Subject to 10 CFR 50.49 Environmental Qualification Requirements Program



SER Open Item PWR Vessel Internals Program

- GALL Anticipates Future PWR Vessel Internals Program
 - Specifies Commitment to Implement Program
- As Part of Hearing Process the ASLB Admitted Contention that Commitment Alone was Insufficient
- To Resolve Contention a Plant-Specific PWR Vessel Internals Program was Submitted 5/12/09
 - Program is Based on EPRI MRP-227 Rev 0 (Dec. 2008)
- ASLB has Dismissed Contention
- NRC Staff Review in Progress



SER Open Item Waste Gas Decay Tank Scoping

- SSC are in Scope per 10 CFR 54.4.a(1) if, in part, they
 Prevent or Mitigate the Consequences of Accidents
 Which Could Result in Offsite Exposures "Comparable" to Those Referred to in 10 CFR 100.11
- PINGP Maintains WGDTs as Safety Related
- WGDTs Not Initially in Scope Because Offsite Exposure Potential not Considered "Comparable"
- WGDTs have been Reclassified as in LR Scope
- LRA Scoping Changes were Submitted 6/5/2009
- NRC Staff Review in Progress



SER Open Item Refueling Cavity Leakage

- NRC was Briefed on Refueling Cavity Leakage During Aging Management Audit
- NRC has Reviewed Issue in Public Meeting,
 RAIs and Specific Site Audit of Documentation
- NSPM has Responded to all NRC RAIs, Most Recently in Letter Dated June 24, 2009
- NRC Staff Review is in Progress



SER Open Item Refueling Cavity Leakage

- Detailed Review of Issue Follows
 - Background on Leakage
 - Containment Configuration
 - Leak Locations & Leak Paths
 - Inspection Results to Date
 - Corrective Actions
 - Long Term Aging Management
 - Evaluation of Potential Degradation



Refueling Cavity Leakage Background

- Intermittent Leakage Indications in Both Units Since Late 1980s
- Leak Rate is 1-2 Gallons per Hour Seen in ECCS Sump and Regenerative Heat Exchanger Room
- Source is Refueling Cavity Based on:
 - Leakage Indications Typically Begin 2 4 Days After Refueling Cavity Flood and End Approximately 3 days After Cavity is Drained.
 - Chemistry Indicates Refueling Water
- Sealing Methods Have Been Successful, but not Consistently



Refueling Cavity Leakage Background

- Root Cause Evaluation was Performed Following Most Recent Refueling Outage
- Sources of Leakage were Determined to be Embedment Plates for Reactor Internals Stands and Rod Control Cluster Change Fixture




Refueling Cavity Leakage Containment Design

Containment Vessel

- Steel Containment Vessel
 - 1-1/2 inch Thick Bottom Head, 1-1/2 inch Shell, 3/4 inch Top Head
 - 3-1/2 inch Thick at ECCS Sump (sump B) Penetrations
 - SA-516-70 Low Temperature Carbon Steel
- Provides Primary Containment
- Lower Head Encased in Concrete
- 5 foot Annular Gap Between Containment Vessel and Limited Leakage Reinforced Concrete Shield Building








Refueling Cavity Leakage Leak Locations

Typical Reactor Vessel Internals Stand Support




Typical RCC Change Fixture Support





Refueling Cavity Leakage Leak Locations



General Arrangement of Change Fixture Supports




Refueling Cavity Leakage Path

Path to ECCS Sump

- Under Refueling Cavity Liner Through Construction Joint Between Floor of Transfer Pit and Wall Behind Fuel Transfer Tube to Inner Wall of Containment Vessel
- Travels Down and Horizontally, Between Containment Vessel and Concrete, to Low Point of Containment Vessel Bottom Head
- Seeps Through Grout in ECCS Sump
- Path to Regenerative Heat Exchanger Room
 - Once Under Liner, Follows Cracks in the Concrete, Seeping Through the Ceiling and Walls of the Regenerative HX Room











Refueling Cavity Leakage Inspection Results to Date

- Ultrasonic and Visual Examinations of Containment Vessel
 - ECCS Sump
 - Grout Removed
 - Wall Thickness Measurements at or Above Nominal
 - No Corrosion Identified.
 - Annulus
 - Wall Thickness Measurements at or Above Nominal
 - No Corrosion Identified



Sump






Refueling Cavity Leakage Corrective Actions - Repairs

- Perform Repairs to Eliminate Leakage During Next Refueling Outage of Each Unit
 - Unit 1 September 2009
 - Unit 2 April 2010



Refueling Cavity Leakage Corrective Actions - Repair Method





Refueling Cavity Leakage Corrective Actions – Monitoring & Assessment

- Enhance Monitoring by Removing Concrete from Sump Below Reactor Vessel to Expose Containment Vessel
 - Next Outages Following Refueling Cavity Repairs
 - Inspect (VT and UT) Containment Vessel and Assess Concrete
 - Evacuate any Water Observed
- Additional Assessment
 - Margin Assessment of Containment Vessel, Concrete and Rebar
 - Evaluate Structural Requirements and Potential Degradation in Concrete Around Transfer Tube





Refueling Cavity Leakage Long Term Aging Management

- Monitor Areas Previously Exhibiting Leakage for Next Two Outages After Repairs to Confirm That Leakage has not Recurred
- Continue General Monitoring for New Leakage Using Structures Monitoring Program and ASME Section XI Subsection IWE Program for Remainder of Plant Life
- Utilize Corrective Action Program for Evaluation and Correction of New Issues



- Evaluations have been performed for potential degradation of:
 - Steel Containment Vessel
 - Concrete
 - Rebar



- Steel Containment Vessel
 - No Corrosion has been Identified
 - Water is Essentially Stagnant Oxygen Would be Consumed to Preclude Continued Corrosion
 - Alkalinity from the Concrete Would Elevate pH to Inhibit Corrosion in Wetted Areas
 - Containment Vessel Corrosion Behind Concrete in Areas Wetted by Refueling Cavity Leakage Would be no More than 10 mils



Concrete

- Long Term Exposure to Acid can Dissolve CaOH in Cement Binder and Soluble Aggregate
- Dissolving CaOH Neutralizes Acid if not Refreshed.
- At Refueling Cavity Liner
 - Evaluation Concluded Negligible Effect on Refueling Cavity Walls and Floor
 - Concrete at Transfer Tube End Still Being Evaluated Since Thickness <1 foot.



- Concrete (Cont'd)
 - At Containment Vessel Inside Surface
 - Water is Essentially Stagnant so Acid Would be Neutralized by Alkalinity in Concrete with Minimal Effect
 - At Cracks
 - Water is Essentially Stagnant so Acid Would be Neutralized by Alkalinity in Concrete with Minimal Effect



Rebar

- Some Potential for Refueling Cavity Leakage to Reach Rebar in Cracks
- Corrosion of Wetted Rebar is Inhibited by Alkalinity (CaOH) of Concrete, Which Promotes Protective Layer
- Qualitative Assessment Concludes There Have Been no Significant Signs of Rebar Corrosion
- Corrosion of Rebar, Whether Wetted Periodically or Continuously, Would be Minimal



Conclusions

- Expected Containment Vessel Corrosion Behind Concrete in Areas Wetted by Refueling Cavity Leakage is Minimal
- Concrete Degradation or Rebar Corrosion Would not have had a Significant Effect on Reinforced Concrete That Has Been Wetted by Refueling Cavity Leakage




Summary

- LRA Developed by Experienced Team
- LRA Conforms to Regulatory Requirements and Follows Industry Guidance
- PINGP Will Be Prepared to Manage Aging During the Period of Extended Operation



Questions?






Backup Slides



Plant Electrical Distribution





RESPONSIBLE BY NATURE"

Aging Management Programs

- Programs with Exceptions to GALL
 - Bolting Integrity Program
 - Closed-Cycle Cooling Water System Program
 - Compressed Air Monitoring Program
 - Electrical Cable Connections (E6) Program
 - Fire Protection Program
 - Flow-Accelerated Corrosion Program
 - Fuel Oil Chemistry Program
 - Selective Leaching of Materials Program
 - Steam Generator Tube Integrity Program
 - Water Chemistry Program



Shield Building Annulus




UT exam of containment vessel from annulus was performed. Scanned 18' long x 2' high area with all readings above 1.5 inch nominal plate thickness.





ECCS Sump Showing Grout





To 33 (Cont. 3D)

To 34 Insp.

