

January 4, 2005

Mr. G. R. Peterson
Vice Nuclear Officer and President
McGuire Nuclear Station
12700 Hagers Ferry Road
Huntersville, NC 28078-8985

SUBJECT: MCGUIRE NUCLEAR GENERATING STATION, UNITS 1 AND 2 - RESPONSE TO NUCLEAR REGULATORY COMMISSION (NRC) BULLETIN 2003-02, "LEAKAGE FROM REACTOR PRESSURE VESSEL LOWER HEAD PENETRATIONS AND REACTOR COOLANT PRESSURE BOUNDARY INTEGRITY" (TAC NOS. MC0545 AND MC0546)

Dear Mr. Peterson:

On August 21, 2003, the Nuclear Regulatory Commission (NRC) issued NRC Bulletin 2003-02, "Leakage from Reactor Pressure Vessel Lower Head Penetrations and Reactor Coolant Pressure Boundary Integrity," to the industry. This bulletin informed addressees that current methods of inspecting the reactor pressure vessel (RPV) lower heads may need to be supplemented with bare-metal visual inspections in order to detect reactor coolant pressure boundary leakage. The bulletin also requested these addressees to provide the NRC with information related to inspections that have been performed to verify the integrity of the RPV lower head penetrations.

The bulletin requested that addressees provide a description of the RPV lower head penetration inspection program that would be implemented at their respective plants during the next and subsequent refueling outages. This description was to include the extent of the inspection, the inspection methods to be used, the qualification standards for the inspection methods, the process used to resolve the source of findings of boric acid deposits or corrosion, the inspection documentation to be generated, and the basis for concluding that their plant satisfied applicable regulatory requirements related to the structural and leakage integrity of the RPV lower head penetrations.

By letter dated September 18, 2003, Duke Energy Corporation (Duke) provided its response to this request for McGuire Nuclear Station, Units 1 and 2. Duke indicated it planned to perform a bare-metal visual examination of the RPV lower head, including a 360-degree examination of all RPV lower head penetrations during the Spring 2004 and Fall 2003 refueling outages at McGuire, Units 1 and 2, respectively. Additionally, Duke stated that the information obtained from these inspection findings and industry developments on the RPV lower head penetrations will be used to determine the type of examinations that will be performed during future refueling outages, beyond the Fall 2003 and Spring 2004 refueling outages at McGuire. The NRC staff notes that there are a number of ongoing industry and NRC staff activities related to developing criteria for RPV lower head penetrations inspections. As such, the NRC staff expect that the criteria for these inspections will involve periodic bare-metal visual examinations or their equivalent.

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated December 4, 2003, Duke provided a summary of its inspection results at McGuire, Unit 2. Duke reported it had performed a bare-metal visual inspection of the RPV lower head, including 360-degree examinations around 100 percent of the RPV lower head penetrations. Duke did not observe any evidence of RPV lower head penetration leakage.

By letter dated June 9, 2004, Duke provided a summary of its inspection results at McGuire, Unit 1. Duke reported it had performed a bare-metal visual inspection of the RPV lower head, including 360-degree examinations around 100 percent of the RPV lower head penetrations. Duke did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Duke's responses to NRC Bulletin 2003-02, the NRC staff finds that McGuire has met the reporting requirements of the bulletin. Accordingly, TAC NOS. MC0545 and MC0546 are closed for McGuire, Units 1 and 2, respectively.

Sincerely,

/RA/

James Shea, Project Manager, Section 1
Project Directorate II
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. 50-369 and 50-370

cc: See next page

The bulletin also requested that addressees provide a summary of the RPV lower head penetration inspection that was performed at their plants, the extent of the inspection and the methods used, a description of the as-found condition of the lower head, any findings of relevant indications of through-wall leakage, and a summary of the disposition of any findings of boric acid deposits and any corrective actions taken as a result of indications found.

By letter dated December 4, 2003, Duke provided a summary of its inspection results at McGuire, Unit 2. Duke reported it had performed a bare-metal visual inspection of the RPV lower head, including 360-degree examinations around 100 percent of the RPV lower head penetrations. Duke did not observe any evidence of RPV lower head penetration leakage.

By letter dated June 9, 2004, Duke provided a summary of its inspection results at McGuire, Unit 1. Duke reported it had performed a bare-metal visual inspection of the RPV lower head, including 360-degree examinations around 100 percent of the RPV lower head penetrations. Duke did not observe any evidence of RPV lower head penetration leakage.

Based on its review of Duke's responses to NRC Bulletin 2003-02, the NRC staff finds that McGuire has met the reporting requirements of the bulletin. Accordingly, TAC NOS. MC0545 and MC0546 are closed for McGuire, Units 1 and 2, respectively.

Sincerely,

/RA/

James Shea, Project Manager, Section 1
Project Directorate II
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket Nos. 50-369 and 50-370

cc: See next page

Distribution:

PUBLIC	SMonarque	RGramm	SCoffin
PDII-1 RF	JShea	JNakoski	CHawes (Hard Copy)
GCherukenki	Esullivan	LMarsh	OGC

ADAMS ACCESSION NUMBER: ML043440424

NRR-106

OFFICE	PDII-1/PM	PDII-1/LA	LPM	EMCB	PDII-1/SC
NAME	JShea	CHawes	SMonarque	ESullivan	JNakoksi
DATE	12/17/04	12/17/04	12/23/04	1/4/05	1/4/05

OFFICIAL RECORD COPY

McGuire Nuclear Station, Units 1 & 2

cc:

Ms. Lisa F. Vaughn
Duke Energy Corporation
Mail Code - PB06E
422 S. Church St.
P.O. Box 1244
Charlotte, NC 28201-1244

County Manager of Mecklenburg County
720 E. Fourth St.
Charlotte, NC 28202

Mr. C. Jeffrey Thomas
Regulatory Compliance Manager
Duke Energy Corporation
McGuire Nuclear Site
12700 Hagers Ferry Road
Huntersville, NC 28078

Anne Cottingham, Esq.
Winston and Strawn
1400 L Street, NW
Washington, DC 20005

Senior Resident Inspector
c/o U.S. Nuclear Regulatory Commission
12700 Hagers Ferry Road
Huntersville, NC 28078

Dr. John M. Barry
Mecklenburg County
Department of Environmental Protection
700 N. Tryon St
Charlotte, NC 28202

Mr. Peter R. Harden, IV
VP-Customer Relations and Sales
Westinghouse Electric Company
6000 Fairview Road, 12th Floor
Charlotte, NC 28210

NCEM REP Program Manager
4713 Mail Service Center
Raleigh, NC 27699-4713

Ms. Karen E. Long
Assistant Attorney General
NC Department of Justice
P.O. Box 629
Raleigh, NC 27602

Mr. R.L. Gill, Jr., Manager
Nuclear Regulatory Issues &
Industry Affairs
Duke Energy Corporation
526 S. Church St.
Mail Stop EC05P
Charlotte, NC 28202

Mr. Richard M. Fry, Director
Division of Radiation Protection
NC Dept of Environment, Health & Natural
Resources
3825 Barrett Dr.
Raleigh, NC 27609-7721

Mr. T. Richard Puryear
Owners Group (NCEMC)
Duke Energy Corporation
4800 Concord Road
York, SC 29745

Mr. Henry Barron
Group Vice President, Nuclear Generation
& Chief Nuclear Officer
P.O. Box 1006-EC07H
Charlotte, NC 28201-1006