

TABLE OF CONTENTS

<u>Section</u>	<u>Title</u>	<u>Page</u>
CHAPTER 17	QUALITY ASSURANCE	17-1
17.1	Quality Assurance During the Design and Construction Phases	17-1
17.2	Quality Assurance During the Operations Phase	17-1
17.3	Quality Assurance During Design, Procurement, Fabrication, Inspection, and/or Testing of Nuclear Power Plant Items	17-1
17.4	Design Reliability Assurance Program	17-2
17.4.1	Introduction	17-2
17.4.2	Scope	17-2
17.4.3	Design Considerations	17-3
17.4.4	Relationship to Other Administrative Programs	17-3
17.4.5	The AP1000 Design Organization	17-3
17.4.6	Objective	17-4
17.4.7	D-RAP	17-5
17.4.7.1	SSCs Identification and Prioritization	17-5
17.4.7.2	Not Used	
17.4.7.3	Not Used	
17.4.7.4	D-RAP Implementation	17-8
17.4.8	Glossary of Terms	17-9
17.5	Combined License Information Items	17-9
17.6	References	17-11

LIST OF TABLES

<u>Table No.</u>	<u>Title</u>	<u>Page</u>
17-1	Quality Assurance Program Requirements for Systems, Structures, and Components Important to Investment Protection (Sheets 1 – 3).....	17-12
17.4-1	Risk-Significant SSCs Within the Scope of D-RAP (Sheets 1 – 8).....	17-15
17.4-2	Example of Risk-Significant Ranking of SSCs for the Automatic Depressurization System.....	17-24

LIST OF FIGURES

<u>Figure No.</u>	<u>Title</u>	<u>Page</u>
17.4-1	Design Reliability Assurance Program and Operational Phase Reliability Assurance Activities	17-25