

Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR

5Hz+10Hz, 10^{-5}




Figure 2.5.2-225 Deaggregation of 10^{-5} Rock Hazard for 5 and 10 Hz