

NRC INSPECTION MANUAL

DIRS

Change Notice 14-008

DELETED:

	<u>Number</u>	<u>Date</u>
1.	IP 37301	11/13/08
2.	IP 40100	04/05/11
3.	IP 92709	03/30/05
4.	IP 92711	03/30/05
5.	IP 92712	08/21/92

TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IP 37301	03/14/14
	IP 40100	03/14/14
	IP 92709	03/14/14
	IP 92711	03/14/14
	IP 92712	03/14/14

TRAINING: No

REMARKS: IP 37301, "Comparison of As-Built Plant to FSAR Comparison," has been revised to correct a reference error in Section 04.01b from 03.01a to 03.01b.

IP 40100, "Independent Safety Culture Assessment Follow-Up," has been revised to administratively align with the current version of IMC 0310, which was issued with Change Notice 13-029.

IP 92709, "Contingency Plans for Licensee Strikes or Lockouts," has been revised to capture lessons learned from licensee strikes in Region 1.

IP 92711, "Continued Implementation of Strike Plans During an Extended Strike," has been revised to capture lessons learned from licensee strikes in Region 1.

IP 92712, "Resumption of Normal Operations After a Strike," has been revised to capture lessons learned from licensee strikes in Region 1.

DISTRIBUTION: Standard

END