

# NRC INSPECTION MANUAL

DIRS

Change Notice 15-005

## DELETED:

## TRANSMITTED:

<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. IMC 0305	11/20/14	IMC 0305	04/09/15
2. IMC 2601	05/04/90		
3. IP 40100	03/14/14	IP 40100	04/09/15
4. IP 55150	06/20/83	IP 55150	06/20/83
5. IP 93100	08/18/11	IP 93100	04/09/15

TRAINING: No

REMARKS: IMC 0305, "Operating Reactor Assessment Program," has been revised to implement changes to the SCCI process, henceforth referred to as the CCI process, to include changes to thresholds for cross-cutting themes and guidance on opening and closing CCIs. Revised to address recommendations and suggestions from the 2014 ROP Independent Assessment Report. Incorporated feedback forms: 0305-1646, 1647, 1919, 1971, 2004, 2005, 2007A, and 2113.

IMC 2601, "Team Assessments of Fuel Cycle and Material Licensees," has been deleted. As described in this version of the IMC, team assessments are no longer applicable or in use by the Agency. This document is dated and no longer needed.

IP 40100, "Independent Safety Culture Assessment Follow-up," has been revised with editorial changes for consistency with terminology and changes to the original SCCIs.

IP 55150, "Weld Verification Checklist," has been re-issued in an "As-Is" state at the request of the Public Document Room (PDR). This IP was originally reactivated in 2007 as part of the 10 CFR Part 50 construction inspection program to support the resumption of construction activities at Watts Bar 2 only. This IP has no bearing on Part 52 construction activities. (See CN 07-034 for further details.)

IP 93100, "Safety-Conscious Work Environment Issue of Concern Follow-up," has been revised with editorial changes for consistency with terminology and changes to the original SCCIs.

DISTRIBUTION: Standard

END