




PSEG Power, LLC
PSEG Site ESPA
Part 2, Site Safety Analysis Report

2-D Image for Hispaniola Trench
Earthquake at 05 hours

FIGURE 2.4.6-24

Rev 0