

Duke Energy Florida Levy Nuclear Plant Units 1 and 2 Part 2, Final Safety Analysis Report

Nuclear Power Transient Versus Time for the High Cladding Temperature Rod Ejection Accident FIGURE 15.4-202