

# NRC INSPECTION MANUAL

IRIB

---

## CHANGE NOTICE 25-022

---

### DELETED:

	<u>Number</u>	<u>Date</u>
1.	IMC 2561	01/06/21
2.	IP 37801	09/09/20
3.		
4.	IP 60801	09/09/20
5.	IP 64704	11/05/20
6.	IP 71801	09/30/20
7.	IP 83750	11/05/20
8.	IP 84750	11/05/20
9.	IP 86750	10/27/20

### TRANSMITTED:

	<u>Number</u>	<u>Date</u>
	IMC 2561	06/27/25
	IP 37801	06/27/25
	IP 40802	06/27/25
	IP 60801	06/27/25
	IP 64704	06/27/25
	IP 71801	06/27/25
	IP 83750	06/27/25
	IP 84750	06/27/25
	IP 86750	06/27/25

TRAINING: No special training is required for any documents issued with this Change Notice.

REMARKS: IMC 2561, "Decommissioning Power Reactor Inspection Program." Complete rewrite of IMC 2561 to provide the following:

- Incorporated Very Low Safety Significance Issue Resolution Process.
- Risk-informed the inspection process – added additional flexibility to inspection procedure and program completion.
- Incorporated lessons learned since the last revision.
- Incorporated Management Directive 8.3 for event response.

IP 37801, "Decommissioning Safety Reviews, Design Changes, And Modifications." Revised the format of the procedure for better readability. Added additional guidance to better risk-inform the inspection based on OE since the last revision.

IP 40802, "Financial Assurance at Decommissioning Power Reactors." Original issuance. This procedure includes inspection requirements previously listed in IP 71801. Revised to include feedback from inspectors and updated to focus on the inspector's efforts on risk informing the inspection program.

IP 60801, "Decommissioning Spent Fuel Pool Maintenance, Surveillance, and Safety." The requirements and guidance were reorganized to add flexibility and further risk-inform reviews using lessons learned since the last inspection.

IP 64704, "Decommissioning Fire Protection Program." Major revision. The procedure was reorganized for easier readability. Revised to include inspector insights since the last revision and to further risk inform the procedure.

IP 71801, "Decommissioning Implantation and Status." Major revision for 1) to reduce duplication in inspection procedures, 2) to relocate PI&R and safety culture inspection requirements from IP 40801, 3) moved the financial assurance review to the new discretionary procedure IP 40802, and 4) to apply lessons learned and apply additional risk-informed decommissioning guidance.

IP 83750, "Decommissioning Occupational Radiation Control." Major re-write. The procedure was rewritten using lessons learned since the last revision. Greater inspection emphasis was placed on direct observation of work activities and site walkdowns.

IP 84750, "Decommissioning Radioactive Waste Treatment, and Effluent and Environmental Monitoring." Major revision. The procedural guidance was consolidated to implement lessons learned since the last revision from ongoing decommissioning activities.

IP 86750, "Decommissioning Solid Radioactive Waste Management, Demolition and Transportation of Radioactive Materials." Major revision. Updated to include inspection experience since the last revision and add an inspection requirement to review demolition of radiologically impacted structures.

#### EDITORIAL REVISIONS FROM PREVIOUS CHANGE NOTICES (As Required):

#### DISTRIBUTION:

- ☒ Standard  
☐ Official Use Only (OUO)-Security-Related Information

Please contact: \_\_\_\_\_

Email: \_\_\_\_\_

END