


Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0.0	0.0	0.8	0.7	20.6	64.3	13.6	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1125	SS-2	1.5/239.47 Ft.	1/19/2007		SAND, silty (SM)			

Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: RW Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7313		

Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0						8.2	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1125	SS-4	6.0/234.97 Ft.	1/19/2007		SAND, with silt & gravel (SP-SM)			

Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: RW Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7314		

Particle Size Distribution Report



% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
						13.5	


SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1125	SS-6	11.0/229.97 ft.	1/19/2007		SAND, silty (SM)			

Client GPC c/o SNOC
 Project Vogtle Units 3 & 4 COL Project
 Project No. 6141-06-0286 Figure 7315

**MACTEC ENGINEERING
 AND
 CONSULTING, INC.**

Tested by; RW Reviewed by; HJ

Particle Size Distribution Report

[illegible][illegible]

Client	GPC c/o SNOC
--------	--------------

Project Vogtle Units 3 & 4 COL Project


Project No. 6141-06-0286

Figure 7316

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

○ Tested by: RW Reviewed by: HJ

Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
						77.6	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1125	SS-10	28.5/212.47 Ft.	1/19/200	MH	Silt, with sand (MH)		121	58

Client GPC c/o SNOC		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: RW	Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project				
Project No. 6141-06-0286	Figure 7317			

Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0.0	0.0	0.0	0.1	4.6	72.9	22.4	


SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1127	SS-6	11.0/208.67 Ft.	11/28/2006		SAND, clayey (SC)	16.1	46	22

Client GPC c/o SNOC		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: RW Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7129		

Particle Size Distribution Report



Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0.0	0.0	0.0	0.2	41.3	39.1	19.4	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1127	SS-9	23.5/196.17 Ft.	11/29/2006		SAND, silty (SM)	15.1		

Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: RW Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7131		

Particle Size Distribution Report



% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
						16.5	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1130	UD-1	28.5/188.96	3/8/07		SAND, clayey (SC)			

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project


Project No. 6141-06-0286

Figure 7476

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

Tested by: EH Reviewed by: HJ

Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
○						6.7	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1130	UD-3	38.5/178.96	3/8/07		SAND, with clay (SP-SC)			

Client GPC c/o SNOC		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: EH Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7478		

Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0.0	0.0	0.0	0.1	22.9	37.9	39.1	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1133	UD-1	28.0/193.20	2/13/07		SAND, silty (SM)			

Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: EH Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7484		

Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
						14.4	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1133	UD-2	33.0/188.20	2/13/07		SAND, silty (SM)			

Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: EH Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7485		

Particle Size Distribution Report



% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
						66.2	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
B-1133	UD-3	38.0/183.20	2/13/07		CLAY (CL)			

Client GPC c/o SNOG

Project Vogtle Units 3 & 4 COL Project

Project No. 6141-06-0286

Figure 7486

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

Tested by: EH Reviewed by: HJ