


Particle Size Distribution Report




% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0.0	0.0	0.0	0.2	31.7	59.7	8.4	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
TP-B-1194	B1	5/197.73 Ft.	3/29/2007		SAND, with silt (SP-SM)	5.4		

Client GPC c/o SNOC		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: BM Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project			
Project No. 6141-06-0286	Figure 7352		

Particle Size Distribution Report





% COBBLES	% GRAVEL		% SAND			% FINES	
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY
0.0	0.0	0.0	0.0	19.0	52.9	28.1	

SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PL
TP-B-1194	B2	8/194.73 Ft.	3/29/200	SC	SAND, clayey (SC)	15.1	37	22

Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.	○ Tested by: BM	Reviewed by: HJ
Project Vogtle Units 3 & 4 COL Project				
Project No. 6141-06-0286	Lab no. 7353			

Particle Size Distribution Report										
U.S. Sieve Opening in Inches			U.S. Standard Sieve Numbers			Hydrometer				
% COBBLES		% GRAVEL		% SAND			% FINES			
		COARSE	FINE	COARSE	MEDIUM	FINE	SILT	CLAY		
0.0		0.0	0.0	0.0	16.6	73.3	10.1			
SOURCE		SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION		NM %	LL	PL
TP-B-1197		B1	5/240.94 Ft.	3/29/2007	SP-SM	SAND, with silt (SP-SM)		6.6	NV	NP
Client GPC c/o SNOG		MACTEC ENGINEERING AND CONSULTING, INC.			Tested by: BM		Reviewed by: HJ			
Project Vogtle Units 3 & 4 COL Project										
Project No. 6141-06-0286					Figure 7350					

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1132	UD-3	38.5/180.23	1/25/07		CLAY, sandy (CH)		85	52

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 7483

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: EH Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1136	UD-3	38.5/183.15	1/24/07		SAND, silty (SM)		107	49

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 7488

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: EH Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1155	SS-6	11.0/73.95 ft	11/29/06		CLAY, with sand (CL)	42.5	37	15

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 6825

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: R.W. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1155	SS-11	33.5/51.45 ft	11/29/06		SILT, (MH)	55.7	55	14

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 6827

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: S.P. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT




SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1155	SS-22	88.5/-3.55 ft	11/30/06		CLAY (CH)	58.1	112	73

Client GPC c/o SNOC
Project Vogtle Units 3 & 4 COL Project
Project No. 6141-06-0286
Lab no. 6831

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: S.P. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
• B-1155	SS-27	113.5/-28.55	12/4/06		SAND, (SP)	16.5	NV	NP
		ft						

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 6833

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: R.W. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT





SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1156	SS-4	6.0/79.7 Ft.	12/13/06	CH	CLAY(CH)		100	61

Client GPC c/o SNOC	
Project Vogtle Units 3 & 4 COL Project	
Project No. 6141-06-0286	Lab no. 6835

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: RW Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1156	SS-6	11.0/74.70 ft.	12/13/06		SILT (ML)	56.2	44	10



Client GPC c/o SNOC
 Project Vogtle Units 3 & 4 COL Project

Project No. 6141-06-0286 Lab no. 6836

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: S.P. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT





SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1156	SS-8	18.5/67.20 ft.	12/13/06		CLAY, sandy (CH)	32.2	61	39

Client GPC c/o SNOC
Project Vogtle Units 3 & 4 COL Project
Project No. 6141-06-0286
Lab no. 6838

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: EH Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT





SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1156	SS-12	48.5/37.20	12/14/06		CLAY, sandy (CL)	35.9	39	22

Client GPC c/o SNOG	
Project Vogtle Units 3 & 4 COL Project	
Project No. 6141-06-0286	Lab no. 6842

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: EH Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT





SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1157	SS-8	18.5/68.27 ft.	12/6/06		SILT (MH)	49.9	59	17

Client GPC c/o SNOC
Project Vogtle Units 3 & 4 COL Project
Project No. 6141-06-0286
Lab no. 6850

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: S.P. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1157	SS-11	33.5/53.27 ft.	12/6/06		CLAY (CH)	38.4	56	34

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 6851

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: R.W. Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1157	SS-26	108.5/-21.73 ft.	12/7/06		CLAY, with sand (CL)	26.7	43	23



Client GPC c/o SNOC
 Project Vogtle Units 3 & 4 COL Project

Project No. 6141-06-0286 Lab no. 6857

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: RW Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1159	SS-3	3.5/85.20 ft.	12/11/06		CLAY (CH)		58	28

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project



Project No. 6141-06-0286

Lab no. 6858

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: BM Reviewed by: HJ

LIQUID AND PLASTIC LIMITS TEST REPORT



SOURCE	SAMPLE #	DEPTH/ELEV.	DATE SAMPLED	USCS	MATERIAL DESCRIPTION	NM %	LL	PI
B-1159	SS-6	11/77.70 ft.	12/11/06		CLAY, (CH)		50	22

Client GPC c/o SNOC

Project Vogtle Units 3 & 4 COL Project

Project No. 6141-06-0286

Lab no. 6859

**MACTEC ENGINEERING
AND
CONSULTING, INC.**

• Tested by: BM Reviewed by: HJ