



Photo 13. December 9, 2007 – Dr. Stokoe directs the bulldozer that is providing vibrations required for SASW testing, at depth.



Photo 14. December 10, 2007 – Vibratory compaction of test pad fill continues.



Photo 15. December 10, 2007 – Dr. Stokoe demonstrates SASW procedure to group including NRC representatives.



Photo 16. December 10, 2007 – Fill placement and testing are observed by group including NRC representatives.



Photo 17. January 10, 2008 – Moisture conditioning of fill lift prior to compaction.



Photo 18. January 10, 2008 – compaction of fill lift with Vibromax 1105 vibratory roller.



Photo 19. January 15, 2008 – SPT hammer energy calibration during drilling of boring drilled for Cross-Hole seismic testing.




Photo 20. January 15, 2008 – SPT hammer energy data recorder.