

P-S FIELD LOG REV V1.31a



B-601 DM P-S SUSPENSION VELOCITY FIELD LOG REV 1.31a

Borehole

SITE*: Turkey Point NPP DATE*: 3/10/08
CLIENT*: MACTEC JOB*: 8083
AUTHOR*: C. Carter PAGE 1 OF * 4

CONTACT: PHONE: Off Cell

CONTACT: PHONE: Off Cell

CONTACT: PHONE: Off Cell

CONTACT: PHONE: Off Cell

DIRECTIONS TO SITE:

GENERAL SITE CONDITIONS/LOCATION:

COUNTY: Miami-Dade RANGE: TOWNSHIP: SECTION:

BOREHOLE CONSTRUCTION*: CASED UNCASD X

DIAMETERS AND DEPTH RANGES*: 6" 0 TO 25 ft; 5" 25 TO 139 ft cc 7/24/08

BOREHOLE TOTAL DEPTH AS DRILLED*: 139 ft

SURFACE CASING?: X DEPTH TO BOTTOM OF CASING 25 ft; NO

DEPTH TO BEDROCK: ~3 ft DEPTH TO WATER TABLE: 0

BOREHOLE FLUID: WATER; FRESH WATER MUD X; SALT WATER MUD;

OTHER:

DEPTH TO BOREHOLE FLUID*: 0 TIME SINCE LAST CIRCULATION: 3pm

ITEMS WITH * MUST BE COMPLETED. OTHER INFORMATION IS OPTIONAL.
GEOVision Geophysical Services - 11511 Pomona Road, Suite P, Corona, CA 92622 (951) 649-1234 Fx (951) 549-1238

P-S FIELD LOG REV V1.31a



B-601DH P-S SUSPENSION VELOCITY FIELD LOG REV 1.31a

Borehole*

SITE*: Turkey Point NPP DATE*: 3/10/08
CLIENT*: MACTEC JOB*: 8083
AUTHOR*: C. Carter PAGE 2 OF 4

LOGGING CREW*: C. Carter
MOBILIZED FROM: Florida City, FL DEPARTURE TIME: 6:30 am
ARRIVED ON SITE: 7 am
STANDBY TIME: CAUSE:
LOGGING STARTED: 4:29 pm LOGGING COMPLETED: 5:05 pm

BATTERIES CHANGED BEFORE LOGGING: YES ; NO ☒ ; STORED WITH NEW
WINCH COMPROBE ☐ GREY ☒ OYO ☐ RG ☐ OTH ☐
INSTRUMENT* OYO 12004 ☐ 15014 ☐ 19029 ☐ RG 160023 ☒ 160024 ☐
RECEIVER S/N* 12008 ☐ 20042 ☐ 26066 ☐ 11001 ☐ 23053 ☐ 30086 ☒
ISOLATION TUBE S/N* 300083 ☐ 24053 ☐ 28068 ☐ 28072 ☒ 2M
SHEAVE* COMPROBE ☐ OYO 101 ☐ 102 ☒ 103 ☐ RG ☐
MICROLOGGER* 5310 ☐ 5772 ☒ NOT APPLICABLE (OYO) ☐
PROBE OFFSET* OYO 2.0M ☐ RG 2.5M ☒
MINUS CASING STICK-UP* ~.48
DEPTH REF. OFFSET AT START* 2.02
DEPTH REF. OFFSET AT END* 2.02
AFTER SURVEY DEPTH ERROR* ϕ } REF TO GROUND SURFACE

LOG NAME*	START DEPTH*	START TIME	END DEPTH*	END TIME
B601DH SUSP DOWN 01	27.89 ft	4:29	123.03'	5:05 pm

MAINTENANCE PERFORMED ON SITE*: N/A (N/A if none)

EQUIPMENT PROBLEMS OR FAILURES*: N/A (N/A if none)

SUGGESTIONS, ADDITIONS, CHANGES:
COMMENTS:

ITEMS WITH * MUST BE COMPLETED. OTHER INFORMATION IS OPTIONAL

GEOVision Geophysical Services 1151 Pomona Road, Suite P, Corona, CA 92882 (951) 549-1234 Fx (951) 549-1236

P-S FIELD LOG REV V1.31a

B-601DH

GEOVISION SUSPENSION LOGGING FIELD NOTES

SITE*: Turkey Point NPP

DATE*: 3/10/08

CLIENT*: MACTEC

JOB*: 8083

AUTHOR*: C. Carter

PAGE* 3 OF 4

ITEMS WITH * MUST BE COMPLETED. OTHER INFORMATION IS OPTIONAL.

DEPTH METERS	DEPTH FEET	UNFILTERED FILE NO*.	FILTERED FILE NO* (if any)	COMMENTS CASING, WATER, ROCK, ETC
0.5	1.64			
1.0	3.28			
1.5	4.92			
2.0	6.56			
2.5	8.20			
3.0	9.84			
3.5	11.48			
4.0	13.12			
4.5	14.76			
5.0	16.40			
5.5	18.04			
6.0	19.69			
6.5	21.33			
7.0	22.97			
7.5	24.61			
8.0	26.25			
8.5	27.89	001		4:29
9.0	29.53	2		
9.5	31.17	3		
10.0	32.81	4		
10.5	34.45	5		
11.0	36.09	6		
11.5	37.73	7		
12.0	39.37	8		
12.5	41.01	9		
13.0	42.65	10		
13.5	44.29	11		
14.0	45.93	12		
14.5	47.57	13		
15.0	49.21	14		
15.5	50.85	15		
16.0	52.49	16		
16.5	54.13	17		
17.0	55.77	18		
17.5	57.41	19		
18.0	59.06	20		
18.5	60.70	21		
19.0	62.34	22		
19.5	63.98	23		
20.0	65.62	24		
20.5	67.26	25		

P-S FIELD LOG REV V1.31a

B-601DH

GEOVISION SUSPENSION LOGGING FIELD NOTES

SITE*: Turkey Point NPP

DATE*: 3/10/08, 3/26/08

CLIENT*: MACTEC

JOB*: 8083

AUTHOR*: C. Carter

PAGE*: 484 OF 484 *cc 3/26/08 cl 7/24/08*

ITEMS WITH * MUST BE COMPLETED. OTHER INFORMATION IS OPTIONAL *cl 7/24/08*

DEPTH METERS	DEPTH FEET	UNFILTERED FILE NO*	FILTERED FILE NO* (If any)	COMMENTS CASING, WATER, ROCK, ETC
21.0	68.90	26		
21.5	70.54	27		
22.0	72.18	28		
22.5	73.82	29		
23.0	75.46	30		
23.5	77.10	31		
24.0	78.74	32		
24.5	80.38	33		
25.0	82.02	34		
25.5	83.66	35		
26.0	85.30	36		
26.5	86.94	37		
27.0	88.58	38		
27.5	90.22	39		
28.0	91.86	40		
28.5	93.50	41		
29.0	95.14	42		
29.5	96.78	43		
30.0	98.43	44		
30.5	100.07	45		
31.0	101.71	46		
31.5	103.35	47		
32.0	104.99	48		
32.5	106.63	49		
33.0	108.27	50		
33.5	109.91	51		
34.0	111.55	52		
34.5	113.19	53		
35.0	114.83	54		
35.5	116.47	55		
36.0	118.11	56 212		5:33 3/26/08
36.5	119.75	57 213		
37.0	121.39	58 214		
37.5	123.03	59 215		5:05 (3/10/08)
38.0	124.67	216		
38.5	126.31	217		
39.0	127.95	218		
39.5	129.59	219		
40.0	131.23	220		
40.5	132.87	221		
41.0	134.51	222		

ACOUSTIC TELEVIEWER LOG COVER 1.0a.pdf



B-601DP ACOUSTIC TELEVIEWER FIELD LOG Rev 1.0a

Borehole*

SITE*: Turkey Point NPP DATE*: 3/10/08
CLIENT*: MACTEC JOB*: 8083
AUTHOR*: C. Carter PAGE 1 OF 2

CONTACT: PHONE: Off Cell

CONTACT: PHONE: Off Cell

CONTACT: PHONE: Off Cell

DRILLER PHONE: Off Cell

COMPANY:

GENERAL SITE CONDITIONS/LOCATION:

COUNTY: Miami-Dade RANGE: TOWNSHIP: SECTION:

BOREHOLE CONSTRUCTION: CASED UNCASD X

DIAMETERS AND DEPTH RANGES: 2.5" 0 TO 2.5' ; 5" 25 TO 139 ft
cc 2/10/08

BOREHOLE TOTAL DEPTH AS DRILLED*: 139 ft

SURFACE CASING?: YES X DEPTH TO BOTTOM OF CASING 25'

DEPTH TO BEDROCK: ~3 DEPTH TO WATER TABLE: 0

BOREHOLE FLUID: WATER ; FRESH WATER MUD X ; SALT WATER MUD

OTHER:

DEPTH TO BOREHOLE FLUID: 0 TIME SINCE LAST CIRCULATION: 3pm

LOGGING CREW: C. Carter

VEHICLE(S) USED AND MILEAGE:

MOBILIZED FROM: Florida City DEPARTURE TIME: 6:30am

ARRIVED ON SITE: 1am

STANDBY TIME: CAUSE:

ITEMS WITH * MUST BE COMPLETED. OTHER INFORMATION IS OPTIONAL