



MACTEC PROJECT NO.: 6468-06-1472					COUNTY Louisa, VA					GEOLOGIST J. Lachewitz					
SITE DESCRIPTION NORTH ANNA COL										GROUND WATER (ft)					
BORING NO. B-951			DRILL METHOD: Mud Rotary/Core			SAMPLE METHODS: SPT/CORE			0 HR. 9.0						
COLLAR ELEV. 249.9 ft (NAVD88)			NORTHING 3,910,548			US ft (NAD83)			EASTING 11,686,822		US ft (NAD83)		24 HR. 5.3		
TOTAL DEPTH 101.0 ft			DRILL MACHINE CME 550 ATV			DRILLER: G. Akins			HAMMER TYPE 140 lbs Auto						
DATE STARTED 8/16/06			COMPLETED 8/17/06			CORE BARREL TYPE: HQ 3 triple tube-wireline									
ELEV. (ft)	DEPTH (ft)	BLOW COUNT			BLOWS PER FOOT					SAMP. NO.	MOI	LOG	SOIL AND ROCK DESCRIPTION		
		0.5ft	0.5ft	0.5ft	0	20	40	60	80	100					
249.9					Ground Surface								249.9	0.0	
248.4	1.5									951-1			Silty SAND (SM) reddish brown (5YR 4/3) and brown (7.5YR 5/4), moist, medium dense to loose (Fill)	5.5	
246.4	3.5	5	5	8						951-2					
243.9	6.0	4	5	4						951-3					
241.4	8.5	3	3	5						951-4			SILT (ML) yellowish red (5YR 4/6), moist, stiff to very stiff, micaceous, sandy, trace gravel (Fill)		
238.9	11.0	5	6	6						951-5					
236.4	13.5	2	5	7						951-6					
		3	7	9											
230.4	19.5												Silty, fine to coarse SAND (SM) dark greenish gray (GLE Y1 4/10Y) and strong brown (7.5YR 4/6&5/8), moist, very dense (Residual Soil)	16.0	
		14	22	35						951-7					
225.4	24.5														
		28	35	38						951-8					
220.4	29.5														
		20	26	27						951-9					
215.4	34.5														
		20	42	44						951-10					
210.4	39.5												Weathered Rock: Strong brown (7.5YR 5/8), moist, very dense, severely weathered, QUARTZ GNEISS	37.0	
		50/0.3								951-11					
													Hard Rock: Light reddish brown, reddish brown, pinkish white, bluish gray, and white, moderately severe to slightly weathered, very close to close fracturing, soft to moderately hard, QUARTZ GNEISS with biotite	40.6	
													Hard Rock: White, slightly weathered to fresh, close to wide fracturing, moderately hard to very hard. QUARTZ GNEISS with biotite and trace magnetite	70.0	



MACTEC PROJECT NO.: 6468-06-1472										COUNTY Louisa, VA					GEOLOGIST J. Lachewitz				
SITE DESCRIPTION NORTH ANNA COL															GROUND WATER (ft)				
BORING NO. B-951					DRILL METHOD: Mud Rotary/Core					SAMPLE METHODS: SPT/CORE					0 HR. 9.0				
COLLAR ELEV. 249.9 ft (NAVD88)					NORTHING 3,910,548 US ft (NAD83)					EASTING 11,686,822 US ft (NAD83)					24 HR. 5.3				
TOTAL DEPTH 101.0 ft					DRILL MACHINE CME 550 ATV					DRILLER: G. Akins					HAMMER TYPE 140 lbs Auto				
DATE STARTED 8/16/06					COMPLETED 8/17/06					CORE BARREL TYPE: HQ 3 triple tube-wireline									
ELEV.	DEPTH	BLOW COUNT			BLOWS PER FOOT					SAMP.	MOI	LOG	SOIL AND ROCK DESCRIPTION						
(ft)	(ft)	0.5ft	0.5ft	0.5ft	0	20	40	60	80	100	NO.								
175.1					Continued from previous page														
													Hard Rock: White, slightly weathered to fresh, close to wide fracturing, moderately hard to very hard, QUARTZ GNEISS with biotite and trace magnetite (continued)						
													148.9 101.0						
													Boring and coring terminated at 101.0 ft in Hard Rock: Very hard, QUARTZ GNEISS with biotite						


NORTH ANNA COL CORE NORTH ANNA COL DATA REPORT REV0.GPJ NORTH ANNA COL.GDT 1/19/07




SHEET 1 OF 1

MACTEC PROJECT NO.: 6468-06-1472							COUNTY Louisa, VA			GEOLOGIST J. Lachewitz		
SITE DESCRIPTION NORTH ANNA COL										GROUND WATER (ft)		
BORING NO. B-951			DRILL METHOD: Mud Rotary/Core				SAMPLE METHODS: SPT/CORE			0 HR. 9.0		
COLLAR ELEV. 249.9 ft (NAVD88)			NORTHING 3,910,548		US ft (NAD83)		EASTING 11,686,822		US ft (NAD83)		24 HR. 5.3	
TOTAL DEPTH 101.0 ft			DRILL MACHINE CME 550 ATV				DRILLER: G. Akins			HAMMER TYPE 140 lbs Auto		
DATE STARTED 8/16/06			COMPLETED 8/17/06				CORE BARREL TYPE: HQ 3 triple tube-wireline					
CORE SIZE HQ3			TOTAL RUN 60.4 ft									
ELEV. (ft)	DEPTH (ft)	RUN (ft)	DRILL RATE (Min/ft)	REC. (ft) %	RQD (ft) %	SAMP. NO.	STRATA REC. (ft) %	RQD (ft) %	L O G	DESCRIPTION AND REMARKS		
										Begin Coring @ 40.6 ft		
209.3	40.6	5.4	1:19 1:20 1:27 1:46 1:28/1.4	(4.3) 80%	(3.4) 63%	1				209.3	Hard Rock: Light reddish brown, reddish brown, pinkish white, bluish gray, and white, moderately severe to slightly weathered, very close to close fracturing, soft to moderately hard, QUARTZ GNEISS with biotite (4 joints at 0-60° with trace clay and Fe staining)	
203.9	46.0										(4 joints at 15-35° with trace clay and Fe staining)	
		5.0	1:59 1:05 1:11 1:28 1:16	(2.5) 50%	(1.6) 32%	2						
198.9	51.0										-Multiple joints throughout with trace clay and Fe staining	
		5.0	1:07 1:10 0:44 1:07 1:21	(4.0) 79%	(1.9) 38%	3						
193.9	56.0										-Multiple joints throughout with trace clay and Fe staining	
		5.0	2:00 2:00 2:00 0:57 1:30	(2.5) 50%	(1.0) 20%	4						
188.9	61.0										-Multiple joints throughout; quartz vein from 64.7-64.9 ft	
		4.9	1:24 1:18 1:20 1:19 1:18/0.9	(3.0) 61%	(0.7) 14%	5						
184.0	65.9										(4 joints at 10-45° with Fe staining)	
		4.1	1:19 2:40 1:45 2:23	(2.6) 63%	(0.9) 22%	6						
179.9	70.0									179.9		
		5.9	1:46/0.1 3:30 2:19 2:10 2:13 1:59 3:06/0.9	(5.9) 100%	(4.0) 68%	7					Hard Rock: White, slightly weathered to fresh, close to wide fracturing, moderately hard to very hard, QUARTZ GNEISS with biotite and trace magnetite (10 joints at 5-50° with Fe staining)	
174.0	75.9										(Quartz vein at 35° at 78.6 ft with hornblende)	
		4.9	2:36 3:03 4:01 4:53 8:12/0.9	(4.9) 100%	(4.9) 100%	8						
169.1	80.8										(2 joints at 35° with slight weathering)	
		5.0	6:00 3:27 4:32 4:41 6:21	(5.0) 100%	(5.0) 100%	9						
164.1	85.8										(1 joint at 35° with very slight weathering)	
		5.1	3:09 3:10 2:38 3:33 3:48/1.1	(5.1) 100%	(5.1) 100%	10						
159.0	90.9										(2 joints at 40° with very slight weathering)	
		4.6	4:06 3:04 3:17 6:15 7:56/0.6	(4.6) 100%	(4.6) 100%	11						
154.4	95.5										(Quartz vein at 99.5-100.5 ft)	
		5.5	4:15 2:44 2:48 2:36 6:09/1.5	(5.0) 91%	(4.3) 78%	12						
148.9	101.0									148.9	Coring terminated at 101.0 ft in Hard Rock: Very hard, QUARTZ GNEISS with biotite	

NORTH ANNA COL CORE NORTH ANNA COL DATA REPORT REV0.GPJ NORTH ANNA COL GDT 1/19/07



B-951 - Box 1



B-951 - Box 2

B-951 - Box 3



B-951 - Box 4
B-951 - Box 5



MACTEC PROJECT NO.: 6468-06-1472										COUNTY Louisa, VA			GEOLOGIST M. Lear/ K. Charles-Smith		
SITE DESCRIPTION NORTH ANNA COL											GROUND WATER (ft)				
BORING NO. OW-951			DRILL METHOD: HSA/Core				SAMPLE METHODS: CORE				0 HR. ND				
COLLAR ELEV. 249.7 ft (NAVD88)			NORTHING 3,910,521		US ft (NAD83)		EASTING 11,686,786		US ft (NAD83)		24 HR. ND				
TOTAL DEPTH 67.2 ft			DRILL MACHINE CME 55LC Track				DRILLER: D. White				HAMMER TYPE NA				
DATE STARTED 11/8/06			COMPLETED 11/9/06				CORE BARREL TYPE: HQ 3 triple tube-wireline								
CORE SIZE HQ3			TOTAL RUN 33.1 ft												
ELEV. (ft)	DEPTH (ft)	RUN (ft)	DRILL RATE (Min/ft)	RUN REC. (ft) %RQD (ft) %		SAMP. NO.	STRATA REC. (ft) %RQD (ft) %		L O G	DESCRIPTION AND REMARKS					
										Begin Coring @ 34.1 ft					
215.6	34.1	3.1	4:20 1:05 1:08	(0.9) 29%	(0.0) 0%	1				214.7	Hard Rock: Tan-orange, moderately severely weathered, closely fractured, medium hard, BIOTITE-QUARTZ GNEISS (4 joints at 40-50° with clay and orange Fe stain)	35.0			
212.5	37.2	5.0	1:08/0.1 0:52 0:53 1:05 1:08 1:36	(2.2) 44%	(0.6) 12%	2				209.7	Weathered Rock: No Recovery-BIOTITE-QUARTZ GNEISS	40.0			
207.5	42.2	5.0	1:55 2:18 1:45 1:48 1:13	(2.9) 58%	(1.7) 34%	3				204.6	Hard Rock: Tan, moderately severe to moderately weathered, very closely to closely fractured, medium hard to moderately hard, BIOTITE-QUARTZ GNEISS (7 joints at 40-50° with clay and orange-brown Fe stain)	45.1			
202.5	47.2	5.0	1:06 1:33 1:47 1:44 1:24	(0.0) 0%	(0.0) 0%	4					Weathered Rock: No Recovery-BIOTITE-QUARTZ GNEISS -No Recovery				
197.5	52.2	5.0	2:15 1:34 2:02 1:58 2:16	(1.8) 36%	(0.0) 0%	5				194.3	Hard Rock: Tan-gray to gray, moderately to slightly weathered, very closely to closely fractured, moderately hard, BIOTITE-QUARTZ GNEISS -Numerous joints at 40-50° with clay and orange-brown Fe stain.	55.4			
192.5	57.2	5.0	2:05 2:07 2:00 2:05 2:14	(3.2) 64%	(0.8) 16%	6									
187.5	62.2	5.0	1:49 2:23 2:34 3:24 6:10	(3.8) 76%	(0.8) 16%	7									
182.5	67.2									182.5	Coring terminated at 67.2 ft in Hard Rock: Moderately hard, BIOTITE-QUARTZ GNEISS Note: 4.25" Hollow Stem Augers advanced to 34.1 ft without SPT's, boring then advanced with core tools.	67.2			

NORTH ANNA COL Core NORTH ANNA COL DATA REPORT REV0.GPJ NORTH ANNA COL.GDT 1/24/07



OW-951 – Box 1

OW-951 – Box 2