

May 15, 2024

L-2024-082 10 CFR 50.36b

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Re: Turkey Point Nuclear Plant, Units 3 and 4

Docket Nos. 50-250 and 50-251

2023 Annual Radiological Environmental Operating Report

Enclosed is the 2023 Annual Radiological Environmental Operating Report for Turkey Point Units 3 and 4, as required by Technical Specification 5.6.1.

If you have any questions regarding this submittal, please contact Kenneth Mack at 561-904-3635.

Sincerely,

Paul Rasmus

General Manager, Regulatory Affairs Florida Power & Light Company

Enclosure: Annual Radiological Environmental Operating Report (2023)

CC:

USNRC Regional Administrator, Region II

USNRC Project Manager, St. Lucie Nuclear Plant USNRC Resident Inspector, St. Lucie Nuclear Plant

ENCLOSURE

Annual Radiological Environmental Operating Report (2023) (55 pages follow)



Plant: Turkey Point Nuclear Units 3 & 4

Page 1 of 55

YEAR: 2023

Docket NOS Number: 50-250, 50-251

Annual Radiological Environmental Operating Report

Annual Radiological Environmental Operating Report

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY	5
	1.1 Radiological Environmental Monitoring Program	5
	1.2 Reporting Levels	6
	1.3 Sample Deviations	6
	1.4 Program Modifications	6
2.0	INTRODUCTION	7
	2.1 Radiological Environmental Monitoring Program	7
	A. Purpose	7
	2.2 Pathways Monitored	8
	2.3 Land Use Census	8
3.0	RADIOLOGICAL ENVIRONMENTAL SAMPLING PROGRAM REQUIREMENTS	9
4.0	INTERPRETATION AND TRENDS OF RESULTS	16
	4.1 Air Particulate and Radioiodine Sample Results	16
	4.2 Thermoluminescent Dosimetry (TLD) Sample Results	17
	4.3 Waterborne Sample Results	17
	4.3.1 Surface Water Results	17
	4.3.2 Shoreline Sediment Sample Results	18
	4.4 Ingestion Sample Results	18
	4.4.1 Crustacea and Fish Sample Results	18
	4.4.2 Broad Leaf Vegetation Sample Results	18
	4.5 Land Use Census Results	18
	4.6 Interlaboratory Comparison Results	25
5.0	RADIOLOGICAL ENVIRONMENTAL MONITORING PROGRAM SUMMARY	25

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 3 of 55
Annual Radiological Environme	ental Operating Report	

AΤ	TΑ	CH	lМ	ΕN	TS

Attachment 1 - Sample Deviations	29
Attachment 2 - Monitoring Results Tables	31
Attachment 3 - Interlaboratory Comparison Program Results	48
1.0 Summary	48
Attachment 4 - Industry Initiative Ground Water Protection Program, 2023	51
1.0 Description of Program	51
2.0 Discussion	51
3.0 Results	51
Attachment 5 - ERRATA Data 2023	55
1.0 List of changes from the 2022 AREOR	55
<u>TABLES</u>	
Table 1: Exposure Pathway - Airborne	9
Table 2: Exposure Pathway - Direct Radiation	10
Table 3: Exposure Pathway - Waterborne	12
Table 4: Exposure Pathway - Ingestion	13
Table 5: Land Use Census - 2023 Nearest Residence, Garden and Milk Animal Within 5 Miles	19
Table 6: Radiological Environmental Monitoring Program Summary	26
Table 7: Sample Deviations Table	29
Table 8: Air Particulate - Gross Beta	32
Table 9: Air Particulate Composite - Gamma	33
Table 10: Air Cartridges - Iodine-131	34
Table 11: Direct Radiation - Indicators	35
Table 12: Direct Radiation- Control	35
Table 13: Surface Water - Tritium and Gamma	36
Table 14: Shoreline Sediment - Gamma	37
Table 15: Crustacea - Gamma	38

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 4 of 55
Annual Radiological Environme	ental Operating Report	

	Table 16: Fish - Gamma	39
	Table 17: Broad Leaf Vegetation - Gamma	40
	Table 18: Supplemental Direct Radiation - Indicators	41
	Table 19: Supplemental Air Particulate - Gross Beta	42
	Table 20: Supplemental Air Particulate Composite - Gamma	43
	Table 21: Supplemental Air Cartridges - Iodine-131	44
	Table 22: Supplemental Surface Water - Tritium and Gamma	45
	Table 23: Supplemental Shoreline Sediment - Gamma	46
	Table 24: Supplemental Food Crops - Gamma	47
	Table 25: DOE's Mixed Analyte Performance Evaluation Program (MAPEP) 48 results	49
	Table 26: DOE's Mixed Analyte Performance Evaluation Program (MAPEP) 49 results	50
	Table 27: Ground Water - Tritium	52
<u>FIGUI</u>	<u>RES</u>	
	Figure 1: Sample Collection Sites - Near Station	14
	Figure 2: Sample Collection Sites - Distant from Station	15
	Figure 3: Turkey Point 2023 REMP Gross Beta in Air, pCi/m³	16
	Figure 4: 2023 PTN Direct Exposure TLDs: Quarterly Collection	17
	Figure 5: Onsite Tritium Monitoring Wells	54

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 5 of 55
Annual Radiological Environme	ental Operating Report	

1.0 EXECUTIVE SUMMARY

1.1 Radiological Environmental Monitoring Program

The data obtained through the Turkey Point Radiological Environmental Monitoring Program (REMP) verifies that the levels of radiation and concentrations of radioactive materials in environmental samples are not increasing. These measurements verify that the dose or dose commitment to members of the public, due to operation of Turkey Point Units 3 & 4, during the surveillance year, is well within the limits established by 10 CFR 50, Appendix I. The sampling period was from January 1, 2023 to December 31, 2023. Additionally, supplemental samples collected by the State of Florida, Department of Health (DOH), do not indicate adverse trends in the radiological environment.

All required lower limit of detection (LLD) capabilities were achieved in all sample analyses during 2023, as required by the Turkey Point Units 3 & 4 ODCM. No measurable levels of radiation above baseline levels attributable to Turkey Point Nuclear operation were detected in the vicinity of PTN. The 2023 REMP thus substantiated the adequacy of source control and effluent monitoring at Turkey Point Nuclear with no observed impact of plant operations on the environment.

Turkey Point Nuclear established the REMP prior to the station's becoming operational to provide data on background radiation and radioactivity normally present in the area. PTN has continued to monitor the environment by sampling air, water, sediment, crustacea, fish and broadleaf vegetation, as well as measuring direct radiation. PTN also samples milk if milk-producing animals used for human consumption are present within five miles (8 km) of the plant.

The REMP includes sampling indicator and control locations within an approximate 20-mile radius of the plant. The REMP utilizes indicator locations near the site to show any increases or buildup of radioactivity that might occur due to station operation and control locations farther away from the site to indicate the presence of only naturally occurring radioactivity. PTN personnel compare indicator results with control results to assess any impact PTN operation might have had on the surrounding environment.

In 2023, environmental samples were collected for radiological analysis. The results of indicator locations were compared with control locations. It was concluded that no significant relationship exists between PTN operation and effect on the area around the plant. The review of 2023 data showed radioactivity levels in the environment were undetectable in many locations and near background levels in significant pathways.

Radiological environmental monitoring for the Turkey Point Plant is conducted by the State of Florida, Department of Health DOH. The DOH personnel collect and analyze samples, with analysis taking place at the DOH Environmental Radiation Control Laboratory in Orlando, Florida. The 2023 Radiological Surveillance Quarterly Report data is provided by the State of Florida Bureau of Radiation Control and is presented in Attachment 2. The State of Florida is not involved in the (Industry Initiative) ground water monitoring program.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 6 of 55
Annual Radiological Environmental Operating Report		

1.2 Reporting Levels

No samples equaled or exceeded reporting levels.

1.3 <u>Sample Deviations</u>

During 2023, environmental sampling was performed for seven media types addressed in the ODCM and for direct radiation. A total of 802 samples of the 802 scheduled were obtained. Of the scheduled samples, 100 percent were collected and analyzed in accordance with the requirements specified in the ODCM. Attachment 1 contains the listing of sample deviations and actions taken.

1.4 **Program Modifications**

Revision 10 of procedure 0-NCAP-103, the Secondary System
Groundwater Radiochemistry was approved and issued on 03/27/23. The
revision change incorporated the new improved technical specifications into
relevant sections of the procedure.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 7 of 55
Annual Radiological Environmental Operating Report		

2.0 INTRODUCTION

This report is submitted pursuant to Specification 5.6.1 of Turkey Point Units 3 & 4 Technical Specifications. The Annual Radiological Environmental Operating Report provides information, summaries and analytical results pertaining to the REMP for the calendar year indicated. This report covers surveillance activities described in the Offsite Dose Calculation Manual (ODCM) meeting the requirements of Unit 3 and Unit 4 Technical Specifications.

2.1 Radiological Environmental Monitoring Program

The REMP for the Turkey Point Plant is conducted pursuant to Control 5.1 of Turkey Point Unit 3 & 4 ODCM.

A. Purpose

The purpose of the REMP is to provide representative measurements of radiation and of radioactive materials in those exposure pathways and for those radionuclides which lead to the highest potential radiation exposures of members of the public resulting from station operation. The REMP also supplements the radiological effluent monitoring program by verifying that the measurable concentrations of radioactive materials and levels of radiation are not higher than expected on the basis of the effluent measurements and the modeling of the environmental exposure pathways.

Sample Locations, Types and Frequencies:

- Direct radiation gamma exposure rate is monitored continuously at 23 locations by thermoluminescent dosimeters (TLDs). TLDs are collected and analyzed quarterly.
- Airborne radioiodine and particulate samplers are operated continuously at six locations. Samples are collected and analyzed weekly. Analyses include lodine-131, gross beta, and gamma isotopic measurements.
- Surface water samples are collected from three locations. Samples are collected and analyzed monthly. Analyses include gamma isotopic and tritium measurements.
- Shoreline sediment samples are collected from three locations coinciding
 with the locations for surface water samples. Samples are collected and
 analyzed semi-annually. Sediment samples are analyzed by gamma
 isotopic measurements.
- Fish and invertebrate samples are collected from two locations coinciding
 with two of the locations for surface water samples. Samples are collected
 and analyzed semi-annually. Fish and invertebrate samples are analyzed by
 gamma isotopic measurements.
- Broad leaf vegetation samples are collected from three locations. Samples are collected and analyzed monthly. Broad leaf vegetation samples are analyzed by gamma isotopic measurements.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 8 of 55
Annual Radiological Environmental Operating Report		

Table 1 through 4 provides specific information pertaining to sample locations, types, and frequencies.

Note: Ground Water Protection, NEI Initiative: The program and results are described in Attachment 4.

2.2 Pathways Monitored

The airborne, direct radiation, waterborne and ingestion pathways are monitored as required by Control 5.1 of Turkey Point Unit 3 & 4 ODCM. A description of the REMP utilized to monitor the exposure pathways is described in the attached Tables and Figures.

Section 4.0 of this report provides a discussion of 2023 sampling results with Section 5.0 providing a summary of results for the monitored exposure pathways.

2.3 Land Use Census

PTN conducts a land use census, as required by Turkey Point Units 3 & 4 ODCM. The purpose of this census is to identify changes in uses of land within five miles of PTN that would require modifications to the REMP and the Offsite Dose Calculation Manual (ODCM). Section 4.5 on the report contains a narrative on the results of the 2023 land use census.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 9 of 55
Annual Radiological Environmental Operating Report		

3.0 RADIOLOGICAL ENVIRONMENTAL SAMPLING PROGRAM REQUIREMENTS

Table 1: Exposure Pathway – Airborne

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
RADIOIODINE AND PARTICULATES 5 sample indicator locations and 1 sample control location.	 T51 (2 mi. NNW) – Entrance Area to Biscayne National Park. T57 (4 mi. NW) – Siren Pole 27, intersection of SW 112th Ave and SW 304th St. T58 (1 mi. NW) – Turkey Point Entrance Road. T72 (<1 mi. WSW) – Just before entrance to Land Utilizations access gate. T41 (1.6 mi. WNW) – Palm Dr. West of FPL Satellite School near the site boundary. T64* (22 mi. NNE) – Natoma Substation, 2475 SW 16 Ct. 	Continuous sampler operation with sample collection weekly or more frequently if required by dust loading.	 Radioiodine Canisters – I-131 analysis weekly. Air Particulate – Gross beta radioactivity analysis following filter change. Air Particulate – Gamma Isotopic analysis quarterly.

^{*}Denotes Control sample

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 10 of 55
Annual Radiological Environme		

Table 2: Exposure Pathway – Direct Radiation

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
TLDS	• N-2 (2 mi N) – Convoy Point		
22 indicator sample locations and 1 control sample location.	N-7 (7.1 mi N) – Black Point Marina parking lot on siren pole	Quarterly	mR exposure quarterly.
	N-10 (10.6 mi N) – Old Cutler Rd across from Perdue Med. Ctr. On siren pole.		
	NNW-2 (2.2 mi NNW) – East End of N. Canal Dr. on siren pole E. of 117 th Ave.		
	NNW-10 (9.2 mi NNW) – Bailes Rd. E. of US 1 on siren pole.		
	NW-1 (1.4 mi NW) – Turkey Point Entrance Rd.		
	NW-5 (3.9 mi NW) – Intersection of Mowry Dr. and 117 th Ave. on siren pole.		
	NW-10 (10 mi NW) – On Newtown Rd. N. of Coconut Palm Drive on siren pole.		
	W-5 (5.3 mi W) – Palm Drive 0.3 mi west of Tallahassee Rd.		
	WNW-10 (9.8 mi WNW) – NW 2 nd Ave. S. of Campbell Dr. at Hmstd. Middle School on siren pole.		
	W-1 (0.7 mi W) – On site north side of Discharge Canal.		

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 11 of 55
Annual Radiological Environmental Operating Report		

Table 2: Exposure Pathway – Direct Radiation

TLDS (Cont'd) 22 indicator sample locations and 1 control sample location. • W-9 (8.6 mi W) – Card Sound Rd. 0.6 mi SSE of US 1 on siren pole. • WSW-8 (7.8 mi WSW) – Card Sound Rd. 3.4 mi. SSE of US 1 on siren Pole. • SW-1 (1 mi SW) – On site near land utilization offices. • SSE-1 (1 mi SSE) – On site South East side of cooling canals at "Turtle Point". • SW-8 (8 mi SW) – Card Sound Rd. 5 mi. SSE of US 1 at entrance to Navy facility. • SSW-5 (5 mi SSW) – On site,	Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
southwest corner of cooling canals. SSW-10 (10 mi SSW) – At Card Sound Bridge on siren pole. S-5 (5 mi S) – On site, south east end of cooling canals. S-10 (10 mi S) – Card Sound Road at Steamboat Creek. SSE-10 (9 mi SSE) – Ocean Reef. NNE-22* (22.6 mi NNE) – Natoma Substation. WNW2 (1.6 mi WNW) – Palm Dr. West of FPL Satellite School, near	TLDS (Cont'd) 22 indicator sample locations and 1 control	 W-9 (8.6 mi W) – Card Sound Rd. 0.6 mi SSE of US 1 on siren pole. WSW-8 (7.8 mi WSW) – Card Sound Rd. 3.4 mi. SSE of US 1 on siren Pole. SW-1 (1 mi SW) – On site near land utilization offices. SSE-1 (1 mi SSE) – On site South East side of cooling canals at "Turtle Point". SW-8 (8 mi SW) – Card Sound Rd. 5 mi. SSE of US 1 at entrance to Navy facility. SSW-5 (5 mi SSW) – On site, southwest corner of cooling canals. SSW-10 (10 mi SSW) – At Card Sound Bridge on siren pole. S-5 (5 mi S) – On site, south east end of cooling canals. S-10 (10 mi S) – Card Sound Road at Steamboat Creek. SSE-10 (9 mi SSE) – Ocean Reef. NNE-22* (22.6 mi NNE) – Natoma Substation. WNW2 (1.6 mi WNW) – Palm Dr. 		

^{*}Denotes Control sample

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 12 of 55	
Annual Radiological Environmental Operating Report			

Table 3: Exposure Pathway – Waterborne

Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
SURFACE WATER 2 indicator sample locations and 1 control sample location.	 T42 (<1 mi. ENE) – Biscayne Bay at Turkey Point. T81 (6 mi. S) – Card Sound, near Mouth of Old Discharge Canal. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Grab samples Monthly	Gamma isotopic analysis and tritium analysis monthly.
SEDIMENT FROM SHORELINE 2 indicator sample locations and 1 control sample location. Locations coincide with the surface water sample locations.	 T42 (<1 mi ENE) – Biscayne Bay at Turkey Point. T81 (6 mi. S) – Card Sound, near Mouth of Old Discharge Canal. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Semi-annually	Gamma isotopic analysis semi-annually.

^{*}Denotes Control sample

Plant: Turkey Point Nuclear Units 3 & 4	Page 13 of 55	
Annual Radiological Environmental Operating Report		

Table 4: Exposure Pathway – Ingestion


Requirement	Sample Point Description Distance and Direction	Sampling and Collection Frequency	Type and Frequency Of Analyses
CRUSTACEA AND FISH 1 indicator sample location and 1 control sample location.	T81 (6 mi. S) – Card Sound, near Mouth of Old Discharge Canal. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park	Semi-annually	Gamma isotopic analysis semi-annually.
BROADLEAF VEGATATION 2 indicator sample locations and 1 control sample location.	 T40 (3 mi W) – South of Palm Dr. on S.W. 117th Street Extension. T41 (2 mi WNW) – Palm Dr. West of FPL Satellite School near the site boundary. T67* (13-18 mi. N, NNE) – Near Biscayne Bay, Vicinity of Cutler Plant, North to Matheson Hammock Park 	Monthly	Gamma isotopic analysis monthly.

^{*}Denotes Control sample

Figure 1: Sample Collection Sites – Near Station



Figure 2: Sample Collection Sites – Distant from Station



Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 16 of 55	
Annual Radiological Environmental Operating Report			


4.0 INTERPRETATION AND TRENDS OF RESULTS

4.1 <u>Air Particulate and Radioiodine Sample Results</u>

In 2023 there were no samples above the LLD for I-131. Indicator gross beta air particulate results for 2023 were comparable to results obtained from 2020-2022 of the operational REMP. Results are reported in picocuries per cubic meter (pCi/m³).


Monitoring Period	<u>Result</u>
2020 – 2022 (Minimum Value)	0.001
2023 Average Value	0.012
2020 – 2022 (Maximum Value)	0.029

Gross beta activity is attributed to naturally occurring radionuclides. Table 6, which include gross beta concentrations and provide a comparison of the indicator and control means and ranges emphasizes the consistent trends seen in this pathway to support the presence of naturally occurring activity. Figure 3 is a comparison of all the weekly Gross Beta results for 2023. Therefore, it can be concluded that the airborne pathway continues to be unaffected by Turkey Point Nuclear operations.



4.2 <u>Thermoluminescent Dosimetry (TLD) Sample Results</u>

Turkey Point Nuclear reports rely on comparison of the indicator locations to the control as a measure of plant impact. Turkey Point Nuclear's comparison of the indicator to the control, as seen in Table 6, identified no noticeable trend that would indicate that the ambient radiation levels are being affected by plant operations. In addition, the quarterly indicator averages shown in the TLD radiation dose comparison graph below shows the 2023 indicator results are comparable to control location results. Overall, Turkey Point Nuclear concluded that the ambient radiation levels are not being affected by plant operations.



4.3 <u>Waterborne Sample Results</u>

The results for 2023 surface water samples were below the ODCM-required LLD, in one of the indicator samples tritium was noted.

4.3.1 <u>Surface Water Results</u>

Samples were collected from two indicator and one control location and analyzed for gamma radionuclides and tritium. Tritium was detected in 1 out of 24 indicator location samples with a concentration of 91 pCi/L which is consistent with results seen in previous operational years. There were no plant related gamma radionuclides detected in any of the control or indicator location samples. Therefore, the operation of Turkey Point Nuclear had no definable impact on this waterborne pathway during 2023.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 18 of 55
Annual Radiological Environmental Operating Report		

4.3.2 Shoreline Sediment Sample Results

Sediment samples were collected from two indicators and one control location in 2023 and analyzed for gamma radionuclides. Plant related gamma radionuclides were below the LLD limits at both indicator and control locations. Turkey Point Nuclear operations had no significant impact on the environment or public by this waterborne pathway.

4.4 Ingestion Sample Results

4.4.1 <u>Crustacea and Fish Sample Results</u>

Crustacea and Fish samples were collected from one indicator and one control location and analyzed for gamma radionuclides. In 2023, plant related gamma radionuclides were below detectable limits which are consistent with the results seen in previous operational years. Therefore, based on these measurements, Turkey Point Nuclear operations had no significant radiological impact upon the environment or public by this ingestion pathway.

4.4.2 Broad Leaf Vegetation Sample Results

The REMP had detected radionuclides prior to 1990 in vegetation that are attributable to other sources. These include the radioactive plume release due to reactor core degradation at Chernobyl Nuclear Power Plant in 1986 and atmospheric weapons testing.

In 2023, Broad Leaf Vegetation samples were collected from two indicator and one control locations and analyzed for gamma radionuclides. Cs-137 was detected in samples collected from the indicator and control locations at concentrations consistent with previous years. This activity identified could be attributed to weapons fallout testing 30-40 years ago and the reactor accident at Chernobyl. Therefore, based on these measurements, Turkey Point Nuclear operations had no significant radiological impact upon the environment or public by this ingestion pathway.

4.5 Land Use Census Results

The latest land use census (performed in 2023) did not identify any new locations that yielded a calculated dose or dose commitment greater than those currently calculated (see Table 5).

The land use census identified no changes in the new resident census.

There were no changes in the milk (cows/goats) or garden census in 2023.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 19 of 55
Annual Radiological Environmental Operating Report		

<u>Table 5: Land Use Census –2023 Nearest Residence, Garden, and Milk Animal Within Five</u>
<u>Miles</u>

SECTOR	NEAREST RESIDENCE/BUSINESS	NEAREST GARDEN (A)	NEAREST MILK ANIMAL
	INESIDENCE/BOSINESS	GANDEN (A)	WIER ANIMAL
N	1.9 mi @ 349° 1.98 mi @ 349°	*	*
NNE	2.0 mi @ 354° *	*	*
		-	
NE	*	*	*
ENE	*	*	*
E	*	*	*
ESE	*	*	*
SE	*	*	*
SSE	*	*	*
S	*	*	*
SSW	*	*	*
SW	*	*	*
WSW	*	*	*
W	*	*	*
WNW	1.7 mi @ 302° 3.7 mi @ 302°	4.5 mi @ 303° 6.0 mi @ 295°	*
NW	3.6 mi @ 304° 3.7 mi @ 311° 3.8 mi @ 316° 3.9 mi @ 314°	*	*
NNW	4.4 mi @ 333° 4.7 mi @ 328°	4.4 mi @ 332° 4.7 mi @ 328°	*

⁽A) - Only gardens with an estimated total area of 500 square feet, or more, and producing green leafy vegetables are considered.

^{* -} No suitable sites were located within a five-mile range.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 20 of 55
Annual Radiological Environmental Operating Report		

TURKEY POINT RESIDENCE SURVEY RESULTS

July- October 2023

Contain	Range	Negreet Decidence/Dusiness Leasting	
Sector N (A)	Bearing 1.9 miles 349°	Nearest Residence/Business Location Homestead Bayfront Park complex. Contact is Jim Wyath. Office hours are 8:30 to 4:30, 7 days a week. Some occasional overnight recreational occupancy (up to 4 nights) on boats at the marina. Approximately 10 workers, 7 days a week, hours and numbers vary. Some summer weekends can see 1000+ visitors. There is always someone here 24 hours with more workers in the summer than the rest of the year (February thru September have the highest peak of workers). LaPlaya restaurant is open at the park weekdays from 11 am to 8:30 pm with 8 to 10 employees. Weekends open till 10 pm and may have up to 15 employees. N25° 27.683' W80° 20.200'.	
N (B)	1.98 miles 349°	South Glade Outfitters. Located on opposite side of building from office of Homestead Bayfront Park. Manager is Robert and have 2-3 employees. Weekdays 7 am to 5 pm, Fridays till 6 pm. Weekends: 7 am – 6 pm. Hours may vary depending on weather. N25° 27.767' W80° 20.206'.	
N (C)	2.0 miles 354°	Biscayne National Park at Convoy Point. Open 7 am to 5:30 pm everyday. There are 65 employees including volunteers and individuals at the institute. The one ranger and two seasonal employees are there all year. There are about 500,000 visitors (more including boaters) per year. Contacts include: Michelle Penick, Chief of Facilities, J. Ernest Jutte, Chief of Administration, 305-242-7721 (office) 202-438-6636 (mobile), and Cindy Holl (administrator) 239-695-1114. N25° 27.817' W80° 20.067'.	
NNE	No residences we	ere located within a five-mile range.	
NE	No residences we	ere located within a five-mile range.	
ENE	No residences we	ere located within a five-mile range.	
Е	No residences we	No residences were located within a five-mile range.	
ESE	No residences we	No residences were located within a five-mile range.	
SE	No residences we	No residences were located within a five-mile range.	
SSE	No residences we	ere located within a five-mile range.	
S	No residences we	No residences were located within a five-mile range.	
SSW	No residences we	No residences were located within a five-mile range.	
SW	No residences we	No residences were located within a five-mile range.	
WSW	No residences we	No residences were located within a five-mile range.	
W	No residences we	ere located within a five-mile range.	

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 21 of 55
Annual Radiological Environmental Operating Report		

TURKEY POINT RESIDENCE SURVEY RESULTS

July-October 2023 (cont.)

Sector	<u>Range</u> Bearing	Nearest Residence/Business Location
WNW (A)	1.7 miles 302°	FP&L daycare center and shooting range near the entrance to the Turkey Point Plant. There are 15 employees with ~90 children enrolled, ages 6 months to 5 yrs. Occasionally, they will have school aged children. The center is open from 6am to 6pm Monday thru Friday. The number of people and times at the shooting range varies. N25° 26.817' W80° 21.217'.
WNW (B)	3.7 miles 302°	11790 Canal Drive on the south side of Canal Drive (SW 328 St) west of SW 117 th Ave (no gardens). Next door, to the east, is a makeshift produce stand which sells coconuts, limes, mandarin oranges, flowers, garlic, mangoes, papaya, avocado, honey, melons, sugar cane, ginger, plantains and pumpkins. Is not associated with the house next door. Two employees may be working there from 8 am to 6 pm. N25° 27.767' W80° 22.867'.
NW (A)	3.6 miles 304°	The Waste Management Homestead Landfill is located north of Canal Drive (SW 328 th St) and east of SW 117 th Ave. There are 9 full time employees onsite Monday thru Friday from 7 am to 3:30 pm. N25° 27.833' W80° 22.767'.
NW (B)	<u>3.7 miles</u> 311°	11000 SW 320 th St. Per property records, this house is on land zoned agriculture and the owners live in Texas. Unable to verify if anyone lives there because the gate is locked and the residence is too far from the road to see anything. N25° 28.217' W80° 22.567'.
NW (C)	3.8 miles 316°	High Hope Nursery at 11400 SW 316 th St. Contact is George Sprinkle, Owner and General Manager. This nursery has approximately 35 employees. Hours of operations are 7am to 5pm Monday thru Friday, with some work on Saturdays until noon. A man lives onsite providing security. N25° 28.441' W80° 22.430'.
NW (D)	<u>3.9 miles</u> 314°	Snapper Creek Nursery at 11600 SW 316 th Street. 14 workers that work Monday thru Friday 7 am to 5 pm. Contact is Elmer. Security is provided by another person who lives onsite. N25° 28.444' W80° 22.560'.
NNW (A)	<u>4.4 miles</u> 333°	29800 SW 107 th Ave. Per property records, this is a small one bedroom residence on land zoned as mixed use agricultural. No information on occupants. N25° 29.450' W80° 21.817'.
NNW (B)	4.7 miles 328°	Mirtica and Sons Dragon Fruit Farm. Entrance at the end of SW 296th St. Contact is Ernesto Gonzalez Abreu. Owner lives off property in Miami N25° 29.564' W80° 22.264'.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 22 of 55
Annual Radiological Environmental Operating Report		

TURKEY POINT GARDEN SURVEY RESULTS

July-October 2023

Sector	<u>Range</u> Bearing	Nearest Garden Location (with estimated total area of 500 square feet, or more, and producing green leafy vegetables).		
N	No suitable garden	s were located within a five-mile range.		
NNE	No suitable garden	s were located within a five-mile range.		
NE	No suitable garden	s were located within a five-mile range.		
ENE	No suitable garden	s were located within a five-mile range.		
E	No suitable garden	No suitable gardens were located within a five-mile range.		
ESE	No suitable gardens were located within a five-mile range.			
SE	No suitable gardens were located within a five-mile range.			
SSE	No suitable gardens were located within a five-mile range.			
S	No suitable garden	s were located within a five-mile range.		
SSW	No suitable garden	s were located within a five-mile range.		
SW	No suitable garden	s were located within a five-mile range.		
WSW	No suitable garden	s were located within a five-mile range.		
W	No suitable garden	s were located within a five-mile range.		

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 23 of 55
Annual Radiological Environmental Operating Report		

TURKEY POINT GARDEN SURVEY RESULTS

July-October 2023 (cont.)

Sector	<u>Range</u> Bearing	Nearest Garden Location (with estimated total area of 500 square feet, or more, and producing green leafy vegetables).
WNW (A)	4.5 miles 303°	Thai Farm. South of Mowry Drive (SW 320th St) and about 0.6 miles west of Allapattah Rd (SW 117th Ave). Growing guava, dragon fruit, papaya, palm, bamboo, and more. No one present. N25° 28.217' W80° 23.467'.
WNW (B)	6.0 miles 295°	Farm Share, Inc at 14125 SW 320th St, where farmers donate locally grown produce to be given to charitable organizations. Produce donations usually start in November and run through April. About 20 workers present from 8 am to 4:30 pm Monday thru Friday. The produce donated is usually tomatoes, bananas, squash, green beans, okra, corn, potatoes, watermelon and zucchini. The contact is Nick Sanchez or Aaron Garcia, Facility Manager, 305-246-3276 (office), 305-926-9832 (cell). N25° 28.255' W80° 25.111'.
NW	No suitable gardens	were located within a five-mile range.
NNW (A)	4.4 miles 332°	Under the Vine. 11100 SW 296th St. Entrance at SW 107th Ave & SW 296th St just east of SFM Tree Farm/Mirtica Farm. Growing only dragon fruit. Open Mon-Sat 8:00-5:00. 3 employees plus the owner, Cindy, work here. Sometimes they hire extra help. The owner's brother, Pepper, sometimes spends the weekends onsite. N25° 29.464' W80° 21.828'.
NNW (B)	4.7 miles 328°	Mirtica and Sons Dragon Fruit Farm. Entrance at the end of SW 296th St. Noticed bananas, dragon fruit, plantain tress, coconuts and mangoes growing in various areas on the farm. Also noticed beehives. Owner lives off property in Miami. N25° 29.564' W80° 22.264'.

Note: At the time of our survey, many fields in the area surveyed were bare soil or cover crops. Other than the sites already described above, the only non-ornamental crops known to have been grown in the survey area were: bananas, beans, corn, guava, malanga, papaya, eggplant, sorghum, squash, sugar cane, tambis, okra, and melon.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 24 of 55
Annual Radiological Environmental Operating Report		

TURKEY POINT MILK ANIMAL SURVEY RESULTS

July-October 2023

Sector	Nearest Milk Animals (cows or goats).	
N	No potential milk animals were located within five miles.	
NNE	No potential milk animals were located within five miles.	
NE	No potential milk animals were located within five miles.	
ENE	No potential milk animals were located within five miles.	
E	No potential milk animals were located within five miles.	
ESE	No potential milk animals were located within five miles.	
SE	No potential milk animals were located within five miles.	
SSE	No potential milk animals were located within five miles.	
S	No potential milk animals were located within five miles.	
SSW	No potential milk animals were located within five miles.	
SW	No potential milk animals were located within five miles.	
WSW	No potential milk animals were located within five miles.	
W	No potential milk animals were located within five miles.	
WNW	No potential milk animals were located within five miles.	
NW	No potential milk animals were located within five miles.	
NNW	No potential milk animals were located within five miles.	

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 25 of 55			
Annual Radiological Environmental Operating Report					

4.6 <u>Interlaboratory Comparison Results</u>

Attachment 3 contains result summary for Interlaboratory Comparison Program for the Department of Energy Mixed Analyte Performance Evaluation Program (MAPEP). These satisfied the requirement of Control 5.3 of the ODCM for the Interlaboratory Comparison Program.

5.0 RADIOLOGICAL ENVIRONMENTAL MONITORING PROGRAM SUMMARY

1. Table 6, Radiological Environmental Monitoring Program Summary, summarizes data for the 2023 REMP program.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 26 of 55			
Annual Radiological Environmental Operating Report					

Table 6: Radiological Environmental Monitoring Program Summary

Sample Type (Units)	Type / Number of Analyses ⁽¹⁾	LLD (2)	Indicator Locations Mean (F) ⁽³⁾ [Range]	Location ⁽⁴⁾ [Highest Annual Mean]	Mean (F) ⁽³⁾ [Range]	Control Locations Mean (F) ⁽³⁾ [Range]	Number of Non Routine Results ⁽⁵⁾
	GB / 312	0.01	0.0122 (260 / 260) [0.001 - 0.025]	T64 (22 mi. NNE)	0.0134 (52 / 52) [0.006 - 0.024]	0.0134 (52 / 52) [0.006 - 0.024]	0
Air Particulate	GS / 24 Be-7		0.1015 (20 / 20) [0.059 - 0.146]	T58 (1 mi. NW)	0.1175 (4 / 4) [0.106 - 0.146]	0.1168 (4 / 4) [0.106 - 0.135]	0
(pCi/m³)	K-40 Cs-134 Cs-137	0.05 0.06	< LLD < LLD < LLD	N/A N/A N/A	N/A N/A N/A	< LLD < LLD < LLD	0 0 0
	Pb-210		0.0098 (4 / 20) [0.009 - 0.012]	T41 (1.6 mi. WNW)	0.0105 (2 / 4) (0.009 - 0.012]	0.0086 (1 / 4) [<lld -="" 0.009]<="" td=""><td>0</td></lld>	0
Airborne Iodine (pCi/m³)	I-131 / 312	0.07	< LLD	N/A	N/A	< LLD	0
Direct Radiation Indicator TLD (μR/hour)	Gamma / 88	(6)	3.8 (88 / 88) [2.6 - 4.9]	WNW-10 (9.8 mi. WNW)	4.3 (4 / 4) [3.9 - 4.8]	N/A	0
Direct Radiation Control TLD (μR/hour)	Gamma / 4	(6)	N/A	NNE-22 (22.6 mi. NNE)	3.3 (4 / 4) [3.0 - 3.7]	3.3 (4 / 4) [3.0 - 3.7]	0

LEGEND:

^{(1) -} GB = Gross beta; I-131 = lodine-131; H-3 = Tritium; GS = Gamma scan.
(2) - LLD = Required lower limit of detection based on Turkey Point ODCM.
(3) - Mean and range based upon detectable measurements only. Fraction of detectable measurements at specified locations is indicated in parenthesis (F).
(4) - Locations are specified (1) by name and (2) direction relative to reactor site.
(5) - Non-routine results are those which exceed ten times the control station value. If no control station value is available, the result is considered non-routine if it exceeds ten times the preoperational value for the location.

⁽⁶⁾ - LLD is not defined in Turkey Point ODCM.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 27 of 55			
Annual Radiological Environmental Operating Report					

Table 6: Radiological Environmental Monitoring Program Summary

Sample Type (Units)	Type / Number of Analyses ⁽¹⁾	LLD (2)	Indicator Locations Mean (F) ⁽³⁾ [Range]	Location ⁽⁴⁾ [Highest Annual Mean]	Mean (F) ⁽³⁾ [Range]	Control Locations Mean (F) ⁽³⁾ [Range]	Number of Non Routine Results ⁽⁵⁾
	H-3 / 36	3,000	91 (1 / 24)	T81	91 (1 / 12)	< LLD	0
Surface Water (pCi/L)	GS / 36 K-40		[<lld (24="" -="" 24)="" 291="" 420]<="" 91]="" [172="" td=""><td>(6 mi. S) T81 (6 mi. S)</td><td>[<lld -="" 91]<br="">302 (12 / 12) [232 - 416]</lld></td><td>215 (12 / 12) [153 - 287]</td><td>0</td></lld>	(6 mi. S) T81 (6 mi. S)	[<lld -="" 91]<br="">302 (12 / 12) [232 - 416]</lld>	215 (12 / 12) [153 - 287]	0
	GS / 6 Be-7		46 (1 / 4) [<lld -="" 46]<="" td=""><td>T67 (13-18 mi. N, NNE)</td><td>86 (1 / 2) [<lld -="" 86]<="" td=""><td>86 (1 / 2) [<lld -="" 86]<="" td=""><td>0</td></lld></td></lld></td></lld>	T67 (13-18 mi. N, NNE)	86 (1 / 2) [<lld -="" 86]<="" td=""><td>86 (1 / 2) [<lld -="" 86]<="" td=""><td>0</td></lld></td></lld>	86 (1 / 2) [<lld -="" 86]<="" td=""><td>0</td></lld>	0
	K-40		98 (1 / 4) [<lld -="" 98]<="" td=""><td>T67 (13-18 mi. N, NNE)</td><td>155 (2 / 2) [146 - 163]</td><td>155 (2 / 2) [146 - 163]</td><td>0</td></lld>	T67 (13-18 mi. N, NNE)	155 (2 / 2) [146 - 163]	155 (2 / 2) [146 - 163]	0
	Co-60		< LLD	N/A	N/A	< LLD	0
Sediment	Cs-137	180	< LLD	N/A	N/A	< LLD	0
(pCi/kg dry)	Pb-210		< LLD	N/A	N/A	< LLD	0
	Ra-226		378 (4 / 4) [268 - 498]	T81 (6 mi. S)	453 (2 / 2) [407 - 498]	144 (2 / 2) [134 - 153]	0
	Th-232		<lld< td=""><td>N/A</td><td>N/A</td><td>< LLD</td><td>0</td></lld<>	N/A	N/A	< LLD	0
	U-235		<lld< td=""><td>N/A</td><td>N/A</td><td>< LLD</td><td>0</td></lld<>	N/A	N/A	< LLD	0
	U-238		<lld< td=""><td>N/A</td><td>N/A</td><td>< LLD</td><td>0</td></lld<>	N/A	N/A	< LLD	0

LEGEND:

^{(1) -} GB = Gross beta; I-131 = Iodine-131; H-3 = Tritium; GS = Gamma scan.

^{(2) -} LLD = Required lower limit of detection based on Turkey Point ODCM.

⁽a) - Mean and range based upon detectable measurements only. Fraction of detectable measurements at specified locations is indicated in parenthesis (F).

(b) - Locations are specified (1) by name and (2) direction relative to reactor site.

(c) - Non-routine results are those which exceed ten times the control station value. If no control station value is available, the result is considered non-routine if it exceeds ten times the preoperational value for the location.

⁽⁶⁾ - LLD is not defined in Turkey Point ODCM.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 28 of 55			
Annual Radiological Environmental Operating Report					

Table 6: Radiological Environmental Monitoring Program Summary

Sample Type (Units)	Type / Number of Analyses ⁽¹⁾	LLD (2)	Indicator Locations Mean (F) ⁽³⁾ [Range]	Location ⁽⁴⁾ [Highest Annual Mean]	Mean (F) ⁽³⁾ [Range]	Control Locations Mean (F) ⁽³⁾ [Range]	Number of Non Routine Results ⁽⁵⁾
	GS / 4		1855 (2 / 2)	T67	1965 (2 / 2)	1965 (2 / 2)	
	K-40		[1130 - 2580]	(13-18 mi. N, NNE)	[1170 - 2760]	[1170 - 2760]	0
Crustacea (pCi/kg wet)	Ra-226		169 (1 / 2) [<lld -="" 169]<="" td=""><td>T81 (6 mi. S)</td><td>169 (1 / 2) [<lld -="" 169]<="" td=""><td><lld< td=""><td>0</td></lld<></td></lld></td></lld>	T81 (6 mi. S)	169 (1 / 2) [<lld -="" 169]<="" td=""><td><lld< td=""><td>0</td></lld<></td></lld>	<lld< td=""><td>0</td></lld<>	0
	Ra-228		< LLD	N/A	N/A	< LLD	0
Fish (pCi/kg wet)	GS / 4 K-40		3035 (2 / 2) [2580 - 3490]	T81 (6 mi. S)	3035 (2 / 2) [2580 - 3490]	2885 (2 / 2) [2760 - 3010]	0
(pointy wet)	Ra-226		< LLD	N/A	N/A	< LLD	0
	Ra-228		< LLD	N/A	N/A	< LLD	0
	GS / 36 Be-7		1910 (24 / 24) [545 - 3320]	T40 (3 mi. W)	2188 (12 / 12) [724 - 3320]	1354 (12 / 12) [663 - 3140]	0
	K-40		4893 (24 / 24) [1830 - 7580]	T67 (13-18 mi. N, NNE)	6003 (12 / 12) [1960 - 8380]	6003 (12 / 12) [1960 - 8380]	0
Broad Leaf (pCi/kg wet)	Cs-137	80	59 (15 / 24) [12 - 109]	T40 (3 mi. W)	74 (10 / 12) [12 - 109]	24 (2 / 12) [23 - 25]	0
	Pb-210		900 (4 / 24) [146 - 1590]	T41 (2 mi. WNW)	1590 (1 / 12) [<lld -="" 1590]<="" td=""><td>71 (1 / 12) [<lld -="" 71]<="" td=""><td>0</td></lld></td></lld>	71 (1 / 12) [<lld -="" 71]<="" td=""><td>0</td></lld>	0
	Pb-212		153 (2 /24) [150 - 155]	T40 (3 mi. W)	153 (2 /12) [150 - 155]	<lld< td=""><td>0</td></lld<>	0
	Ra-226		< LLD	N/A	N/A	< LLD	0

LEGEND:

^{(1) -} GB = Gross beta; I-131 = Iodine-131; H-3 = Tritium; GS = Gamma scan.

^{(2) -} LLD = Required lower limit of detection based on Turkey Point ODCM.

^{(3) -} Mean and range based upon detectable measurements only. Fraction of detectable measurements at specified locations is indicated in parenthesis (F).

^{(4) -} Locations are specified (1) by name and (2) direction relative to reactor site.

^{(5) -} Non-routine results are those which exceed ten times the control station value. If no control station value is available, the result is considered non-routine if it exceeds ten times the preoperational value for the location.

^{(6) -} LLD is not defined in Turkey Point ODCM.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 29 of 55				
Annual Radiological Environmental Operating Report						

Attachment 1 Page 1 of 1

Sample Deviations

Table 7: Sample Deviations Table

Comment No.	Sample Media Affected	Sample Location	Date	Problem	Evaluation / Actions
1	Soil	MAPEP- 23MaS49	2023	False Positive results for Mn-54	The Bureau of Radiation Control (BRC) under the State of Florida, identified a discrepancy in the reported results for MAPEP-23-MaS49 sample (see Attachment 3), for the radiological and inorganic combined soil standard Mn-54. The reported value of 1.85 Bq/Kg (50 pCi/Kg) was below the Minimum Detectable Activity (MDA) of 2.15 Bq/Kg (58.05 pCi/Kg), but it was not acceptable due to the possibly that the background subtraction method was not applied during the analysis. This issue was evaluated by the Florida lab participating in their QC program and was determined by the Florida lab not to have an impact on the results provided in this REMP report. The BRC Program Compliance officer initiated a corrective measure by requesting a blank soil sample from the next series, MAPEP-24-MaS50. A proper background subtraction technique will be used to ensure accuracy during the additional test and a report will be issued upon completion. AR# 02482781
2	Air Sample	T57	03/06/23	Pump Failure	The air sample pump was not operational upon discovery during routine weekly sampling. Due to limited air flow through the iodine cartridge, the sample pump was replaced 3 times over the course of three weeks from 03/06/23 thru 03/20/23. Estimated sampling duration was: 1) Week 1 - 4.8 hrs. out of 144 hrs.,2) Week 2 - 42.3 hrs. out of 173 hours, and 3) Week 3 - 48.8 hrs. out of 162 hrs. AR# 02440703
3	Broad Leaf Vegetation	T40	1 st , 3 rd , and 4 th Qtr.	Broad Leaf Vegetation Cs-137 Result above LLD	The presence of Cs-137 (Cesium-137) was observed in the required REMP sample T40, the broadleaf vegetation. During the first, third, and fourth quarter of State of Florida 2023 quarterly reports the sample results were 90 pCi/kg, 109 pCi/kg, and 100 pCi/kg (1st quarter), 83 pCi/kg (3rd quarter), 81 pCi/kg, and 97 pCi/kg (4th quarter). Although these values do not meet the ODCM reporting criteria thresholds, they are being documented as identified. The ODCM Lower Limit of Detection (LLD) for Cs-137 is 80 pCi/kg, and the reporting level requirement is 2000 pCi/kg. AR# 02484345

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 30 of 55				
Annual Radiological Environmental Operating Report						

Table 7: Sample Deviations Table

Comment No.	Sample Media Affected	Sample Location	Date	Problem	Evaluation / Actions
4	Milk	Т99	2023	Sample Unavailable	T99, the supplemental goat milk sample, was unavailable for 2023 because the farm had no milking goats. AR# 02482782

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 31 of 55
Annual Radiological Environme		

ATTACHMENT 2

Monitoring Results Tables

RADIOLOGICAL SURVEILLANCE OF FLORIDA POWER AND LIGHT COMPANY'S

TURKEY POINT SITE 2023

First Quarter, 2023 Second Quarter, 2023 Third Quarter, 2023 Fourth Quarter, 2023

Plant: Turkey Point Nuclear Units 3 & 4 2023 Page 32 of 55 Annual Radiological Environmental Operating Report

Attachment 2

Monitoring Results Tables Table 8: Air Particulate - Gross Beta

Page 1 of 16

Analysis: Gross Beta				Units: pCi/m³			
End Date	T41 (Indicator)	T51 (Indicator)	T57 (Indicator)	T58 (Indicator)	T64 ⁽¹⁾ (Control)	T72 (Indicator)	
LLD →	0.01	0.01	0.01	0.01	0.01	0.01	
01/02/2023	0.009	0.011	0.007	0.006	0.007	0.009	
01/02/2023	0.009	0.011	0.007	0.006	0.007	0.009	
01/16/2023	0.023	0.012	0.009	0.012	0.010	0.012	
01/23/2023	0.023	0.022	0.019	0.019	0.019	0.021	
01/30/2023	0.012	0.014	0.019	0.012	0.010	0.012	
02/07/2023	0.013	0.009	0.019	0.013	0.008	0.012	
02/15/2023	0.010	0.009	0.002	0.012	0.014	0.010	
02/21/2023	0.011	0.008	0.014	0.010	0.010	0.016	
02/28/2023	0.011	0.000	0.019	0.015	0.015	0.010	
03/06/2023	0.012	0.014	(2) 0.022	0.013	0.014	0.015	
03/13/2023	0.013	0.022	⁽²⁾ 0.006	0.018	0.014	0.019	
03/20/2023	0.016	0.018	⁽²⁾ 0.014	0.014	0.020	0.016	
03/27/2023	0.007	0.008	0.014	0.014	0.011	0.010	
04/03/2023	0.010	0.010	0.017	0.013	0.014	0.010	
04/10/2023	0.007	0.011	0.007	0.009	0.008	0.010	
04/18/2023	0.006	0.010	0.006	0.007	0.008	0.006	
04/25/2023	0.015	0.015	0.015	0.020	0.019	0.005	
05/02/2023	0.011	0.016	0.013	0.014	0.012	0.014	
05/09/2023	0.022	0.019	0.014	0.017	0.024	0.015	
05/15/2023	0.016	0.014	0.016	0.015	0.019	0.017	
05/23/2023	0.013	0.010	0.006	0.009	0.011	0.010	
05/30/2023	0.010	0.010	0.009	0.005	0.007	0.007	
06/05/2023	0.011	0.009	0.010	0.011	0.011	0.007	
06/12/2023	0.008	0.014	0.012	0.012	0.016	0.011	
06/20/2023	0.010	0.010	0.013	0.012	0.012	0.012	
06/27/2023	0.008	0.016	0.012	0.012	0.012	0.012	
07/06/2023	0.009	0.010	0.009	0.014	0.009	0.012	
07/14/2023	0.013	0.015	0.016	0.018	0.019	0.012	
07/20/2023	0.018	0.013	0.016	0.017	0.015	0.017	
07/26/2023	0.025	0.013	0.017	0.017	0.021	0.009	
08/02/2023	0.008	0.008	0.007	0.008	0.008	0.007	
08/08/2023	0.012	0.010	0.011	0.017	0.015	0.014	
08/14/2023	0.014	0.012	0.012	0.018	0.017	0.020	
08/21/2023	0.010	0.011	0.009	0.013	0.007	0.011	
08/29/2023	0.010	0.013	0.010	0.015	0.014	0.012	
09/05/2023	0.007	0.012	0.017	0.013	0.006	0.011	
09/12/2023	0.008	0.011	0.013	0.013	0.012	0.009	
09/19/2023	0.009	0.012	0.008	0.014	0.011	0.009	
09/26/2023	0.011	0.006	0.006	0.006	0.011	0.011	
10/02/2023	0.005	0.006	0.002	0.005	0.006	0.007	
10/09/2023	0.004	0.001	0.008	0.012	0.009	0.011	
10/16/2023	0.013	0.012	0.013	0.013	0.016	0.011	
10/23/2023	0.016	0.017	0.015	0.017	0.022	0.019	
11/01/2023	0.017	0.021	0.019	0.019	0.024	0.019	
11/07/2023	0.017	0.020	0.018	0.013	0.017	0.025	
11/13/2023	0.001	0.006	0.006	0.007	0.009	0.008	
11/20/2023	0.007	0.004	0.006	0.006	0.009	0.007	
11/28/2023	0.015	0.012	0.009	0.017	0.017	0.013	
12/05/2023	0.016	0.017	0.014	0.017	0.023	0.018	
12/11/2023	0.019	0.014	0.012	0.017	0.018	0.017	
12/19/2023	0.013	0.011	0.009	0.009	0.009	0.009	
12/27/2023	0.011	0.010	0.012	0.014	0.015	0.017	

⁽¹⁾ Station with highest annual mean.

⁽²⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 2

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 33 of 55				
Annual Radiological Environmental Operating Report						

Attachment 2 Page 2 of 16

Monitoring Results Tables Table 9: Air Particulate Composite - Gamma

A	Analysis: Gamma Isoto _l	oic	Units: pCi/m ³			
Location	Location Collection Date		K-40	Cs-134	Cs-137	Pb-210
	REQUIRED LLD →			<u>0.05</u>	0.06	
T41 (Indicator)	03/27/2023	0.1330	< 0.0133	< 0.0011	< 0.0008	0.0086
T51 (Indicator)	03/27/2023	0.1150	< 0.0147	< 0.0009	< 0.0008	< 0.0330
T57 (Indicator)	03/27/2023	0.1270	< 0.0146	< 0.0011	< 0.0010	< 0.0145
T58 (Indicator)	03/27/2023	0.1460	< 0.0133	< 0.0010	< 0.0010	0.0093
T64 (Control)	03/27/2023	0.1350	< 0.0143	< 0.0010	< 0.0008	< 0.0143
T72 (Indicator)	03/27/2023	0.1300	< 0.0163	< 0.0010	< 0.0008	< 0.0327
T41 (Indicator)	06/27/2023	0.0594	< 0.0187	< 0.0009	< 0.0008	0.0124
T51 (Indicator)	06/27/2023	0.0607	< 0.0115	< 0.0009	< 0.0008	< 0.0320
T57 (Indicator)	06/27/2023	0.0960	< 0.0204	< 0.0010	< 0.0009	0.0088
T58 (Indicator)	06/27/2023	0.1060	< 0.0151	< 0.0007	< 0.0008	< 0.0317
T64 (Control)	06/27/2023	0.1190	< 0.0234	< 0.0009	< 0.0009	0.0086
T72 (Indicator)	06/27/2023	0.0652	< 0.0145	< 0.0006	< 0.0007	< 0.0302
T41 (Indicator)	09/26/2023	0.0951	< 0.0157	< 0.0080	< 0.0100	< 0.0080
T51 (Indicator)	09/26/2023	0.1070	< 0.0174	< 0.0090	< 0.0120	< 0.0090
T57 (Indicator)	09/26/2023	0.0877	< 0.0152	< 0.0090	< 0.0110	< 0.0070
T58 (Indicator)	09/26/2023	0.1060	< 0.0182	< 0.0090	< 0.0120	< 0.0100
T64 (Control)	09/26/2023	0.1070	< 0.0138	< 0.0060	< 0.0070	< 0.0070
T72 (Indicator)	09/26/2023	0.0909	< 0.0193	< 0.0110	< 0.0130	< 0.0100
T41 (Indicator)	12/27/2023	0.1020	< 0.0152	< 0.0014	< 0.0017	< 0.0015
T51 (Indicator)	12/27/2023	0.0869	< 0.0139	< 0.0009	< 0.0012	< 0.0009
T57 (Indicator)	12/27/2023	0.0983	< 0.0261	< 0.0000	< 0.0000	< 0.0018
T58 (Indicator)	12/27/2023	0.1120	< 0.0148	< 0.0011	< 0.0014	< 0.0010
T64 (Control)	12/27/2023	0.1060	< 0.0231	< 0.0016	< 0.0020	< 0.0017
T72 (Indicator)	12/27/2023	0.1050	< 0.0164	< 0.0007	< 0.0009	< 0.0007

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2023 Page 34 of 55 Annual Radiological Environmental Operating Report

Attachment 2

Page 3 of 16

Monitoring Results Tables Table 10: Air Cartridges - Iodine-131

Analysis: Iodine-131				Units: pCi/m³			
	T41 T51 T57			T58 T64 T72			
End Date	(Indicator)	(Indicator)	(Indicator)	(Indicator)	(Control)	(Indicator)	
112		0.07	0.07	0.07	†	0.07	
<u>LLD →</u>	0.07				0.07		
01/02/2023	< 0.030	< 0.030	< 0.030	< 0.030	< 0.030 < 0.030	< 0.040	
	< 0.030	< 0.030	< 0.030	< 0.030		< 0.030	
01/16/2023	< 0.020 < 0.020	< 0.020 < 0.020	< 0.030 < 0.020	< 0.020	< 0.020	< 0.020	
01/23/2023 01/30/2023	< 0.020	< 0.020	< 0.020	< 0.020 < 0.020	< 0.020 < 0.020	< 0.020 < 0.020	
02/07/2023	< 0.020	< 0.020	< 0.010	< 0.020	< 0.020	< 0.020	
02/15/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
02/21/2023	< 0.020	< 0.020	< 0.030	< 0.020	< 0.020	< 0.020	
02/28/2023	< 0.020	< 0.020	< 0.050	< 0.020	< 0.020	< 0.020	
03/06/2023	< 0.020	< 0.020	⁽¹⁾ < 0.100	< 0.020	< 0.020	< 0.020	
03/13/2023	< 0.020	< 0.020	⁽¹⁾ < 0.080	< 0.020	< 0.020	< 0.020	
03/20/2023	< 0.020	< 0.020	⁽¹⁾ < 0.080	< 0.020	< 0.020	< 0.020	
03/27/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
04/03/2023	< 0.040	< 0.040	< 0.040	< 0.040	< 0.040	< 0.040	
04/10/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
04/18/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
04/25/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
05/02/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
05/09/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
05/15/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.030	< 0.020	
05/23/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
05/30/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
06/05/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
06/12/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
06/20/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
06/27/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
07/06/2023	< 0.020	< 0.010	< 0.010	< 0.020	< 0.020	< 0.020	
07/14/2023	< 0.010	< 0.010	< 0.020	< 0.010	< 0.020	< 0.010	
07/20/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
07/26/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
08/02/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
08/08/2023 08/14/2023	< 0.010 < 0.020	< 0.010 < 0.020	< 0.010 < 0.020	< 0.020 < 0.030	< 0.010 < 0.030	< 0.010 < 0.020	
08/21/2023	< 0.020	< 0.020	< 0.020	< 0.030	< 0.030	< 0.020	
08/29/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
09/05/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
09/12/2023	< 0.020	< 0.010	< 0.020	< 0.010	< 0.020	< 0.010	
09/19/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
09/26/2023	< 0.030	< 0.030	< 0.030	< 0.030	< 0.040	< 0.030	
10/02/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
10/09/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
10/16/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
10/23/2023	< 0.070	< 0.070	< 0.070	< 0.070	< 0.070	< 0.070	
11/01/2023	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	
11/07/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
11/13/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
11/20/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	
11/28/2023	< 0.020	< 0.010	< 0.020	< 0.020	< 0.020	< 0.020	
12/05/2023	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	
12/11/2023	< 0.010	< 0.010	< 0.010	< 0.020	< 0.010	< 0.010	
12/19/2023	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	
12/27/2023	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	< 0.020	

⁽¹⁾ See Attachment 1, Table 7, Samples Deviations Table, Comment 2

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 35 of 55
Annual Radiological Envir		

Attachment 2 Page 4 of 16

Monitoring Results Tables

Table 11: Direct Radiation-Indicators

Ana	alysis: Gamma D	ose	Units: μR/hr			
Station	1st Qtr 2023	2nd Qtr 2023	3rd Qtr 2023	4th Qtr 2023	Annual Mean 2023	
N-2	3.8	4.3	3.8	4.1	4.0	
N-7	3.1	3.6	4.3	4.8	3.9	
N-10	3.4	4.0	3.6	3.7	3.7	
NNW-2	3.3	3.8	4.0	4.1	3.8	
NNW-10	3.5	3.9	3.8	3.8	3.7	
NW-1	3.8	4.1	3.9	3.7	3.9	
NW-5	3.2	4.2	4.1	4.1	3.9	
NW-10	4.1	3.6	4.2	4.3	4.1	
WNW-2	3.3	4.4	3.6	3.8	3.8	
WNW-10 ⁽¹⁾	3.9	4.8	4.4	4.0	4.3	
W-1	3.7	3.8	4.8	4.6	4.2	
W-5	3.3	3.8	3.8	4.9	4.0	
W-9	3.0	4.0	3.8	4.0	3.7	
WSW-8	3.3	4.5	4.0	3.8	3.9	
SW-1	3.5	4.2	4.5	4.1	4.1	
SW-8	2.6	3.9	4.2	4.5	3.8	
SSW-5	2.8	3.9	3.9	4.3	3.7	
SSW-10	3.0	3.6	3.9	3.8	3.6	
S-5	2.7	4.0	3.6	4.2	3.6	
S-10	3.2	4.0	4.0	3.6	3.7	
SSE-1	2.7	3.0	4.0	3.4	3.3	
SSE-10	2.9	3.0	3.0	3.9	3.2	

⁽¹⁾ Indicator station with highest annual mean.

Table 12: Direct Radiation - Control

Analysis: Gamma Dose				Units: μR/hr	
Station	1st Qtr 2023	2nd Qtr 2023	3rd Qtr 2023	4th Qtr 2023	Annual Mean 2023
NNE-22	3.7	3.4	3.0	3.1	3.3

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2023 Page 36 of 55 Annual Radiological Environmental Operating Report

Attachment 2 Page 5 of 16

Monitoring Results Tables

Table 13: Surface Water - Tritium and Gamma

	Analysis: Gamma Isotopic					
Location	End Date	H-3	K-40			
REQUIRE	D LLD →	<u>3,000</u>	-			
T42 (Indicator)	01/17/2023	< 137	205			
T42 (Indicator)	02/13/2023	< 138	272			
T42 (Indicator)	03/07/2023	< 135	364			
T42 (Indicator)	04/03/2023	< 151	403			
T42 (Indicator)	05/01/2023	< 136	312			
T42 (Indicator)	06/05/2023	< 150	229			
T42 (Indicator)	07/21/2023	< 141	420			
T42 (Indicator)	08/15/2023	< 139	320			
T42 (Indicator)	09/06/2023	< 138	221			
T42 (Indicator)	10/10/2023	< 142	238			
T42 (Indicator)	11/02/2023	< 137	198			
T42 (Indicator)	12/06/2023	< 137	172			

Location	End Date	H-3	K-40
REQUIR	ED LLD →	3,000	
T67 (Control)	01/17/2023	< 137	287
T67 (Control)	02/13/2023	< 138	153
T67 (Control)	03/06/2023	< 135	246
T67 (Control)	04/03/2023	< 151	237
T67 (Control)	05/01/2023	< 136	280
T67 (Control)	06/05/2023	< 150	217
T67 (Control)	07/21/2023	< 141	195
T67 (Control)	08/15/2023	< 139	250
T67 (Control)	09/06/2023	< 138	184
T67 (Control)	10/09/2023	< 139	157
T67 (Control)	11/01/2023	< 137	187
T67 (Control)	12/05/2023	< 134	184

ι	Units: pCi/L						
	Location	End Date	H-3	K-40			
	REQUIR	ED LLD →	<u>3,000</u>	-			
	T81 (Indicator)	01/17/2023	< 137	266			
	T81 (Indicator)	02/13/2023	< 140	320			
	T81 (Indicator)	03/06/2023	< 135	264			
	T81 (Indicator)	04/03/2023	< 148	302			
	T81 (Indicator)	05/01/2023	91	364			
	T81 (Indicator)	06/05/2023	< 150	416			
	T81 (Indicator)	07/21/2023	< 141	321			
	T81 (Indicator)	08/15/2023	< 139	252			
	T81 (Indicator)	09/06/2023	< 138	311			
	T81 (Indicator)	10/10/2023	< 142	323			
	T81 (Indicator)	11/02/2023	< 137	255			
	T81 (Indicator)	12/06/2023	< 137	232			

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 37 of 55			
Annual Radiological Environmental Operating Report					

Attachment 2 Page 6 of 16

Monitoring Results Tables

Table 14: Shoreline Sediment - Gamma

	Analysis: Gamma Isotopic					Un	its: pCi/kg (d	iry)		
Location	Collection Date	Be-7	K-40	Co-60	Cs-137	Pb-210	Ra-226	Th-232	U-235	U-238
	REQUIRED LLD →				<u>180</u>					
T42 (Indicator)	01/18/2023	46	98	< 8	< 8	< 365	268	< 36	< 16	< 148
T67 (Control)	01/18/2023	< 84	146	< 6	< 8	< 244	153	< 32	< 16	< 139
T81 (Indicator)	01/18/2023	< 133	< 179	< 13	< 11	< 1050	407	< 53	< 27	< 276
T42 (Indicator)	08/15/2023	< 134	< 128	< 9	< 10	< 1180	339	< 48	< 45	< 8
T67 (Control)	08/15/2023	86	163	< 9	< 8	< 427	134	< 38	< 21	< 4
T81 (Indicator)	08/15/2023	< 226	< 160	< 14	< 13	< 1650	498	< 71	< 79	< 11

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 38 of 55			
Annual Radiological Environmental Operating Report					

Attachment 2

Page 7 of 16

Monitoring Results Tables

Table 15: Crustacea - Gamma

Analysis: Gamma Isotopic			Units: pCi/kg (wet)		
Location	Collection Date	Sample Type	K-40	Ra-226	Ra-228
REQUIRED LLD →					
T67 (Control)	01/19/2023	Blue Crabs	1170	< 269	< 47
T81 (Indicator)	01/19/2023	Blue Crabs	1130	169	< 44
T67 (Control)	08/15/2023	Blue Crabs	2760	< 624	< 111
T81 (Indicator)	08/15/2023	Blue Crabs	2580	< 517	< 93

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 39 of 55			
Annual Radiological Environmental Operating Report					

Attachment 2

Page 8 of 16

Monitoring Results Tables

Table 16: Fish - Gamma

Analysis:	Units: pCi/kg (wet)				
Location	Collection Date	Sample Type	K-40	Ra-226	Ra-228
RE					
T67 (Control)	01/12/2023	Mixed Species	3010	< 408	< 72
T81 (Indicator)	01/19/2023	Mixed Species	3490	< 371	< 83
T67 (Control)	08/15/2023	Mixed Species	2760	< 624	< 111
T81 (Indicator)	08/15/2023	Mixed Species	2580	< 517	< 93

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2023 Page 40 of 55 Annual Radiological Environmental Operating Report

Attachment 2 Page 9 of 16

Monitoring Results Tables

Table 17: Broad Leaf Vegetation - Gamma

	Analysis: Gamma Isotopic			Units: pCi/kg (wet)				
Location	Collection	Sample Type	Be-7	K-40	Cs-137 Pb-210 Pb-212 Ra-2			Ra-226
	Date	REQUIRED LLD →			80			
T40 (Indicator)	01/17/2023	Brazilian Pepper	2150	4740	⁽¹⁾ 90	712	< 25	< 280
T40 (Indicator)	02/13/2023	Brazilian Pepper	2470	5670	⁽¹⁾ 109	1150	< 39	< 539
T40 (Indicator)	03/06/2023	Brazilian Pepper	2140	4770	⁽¹⁾ 100	146	< 23	< 294
T40 (Indicator)	04/03/2023	Brazilian Pepper	724	6400	12	< 728	< 29	< 305
T40 (Indicator)	05/01/2023	Brazilian Pepper	818	7580	< 16	< 108	< 28	< 318
T40 (Indicator)	06/05/2023	Brazilian Pepper	2150	6600	21	< 1220	< 40	< 487
T40 (Indicator)	07/21/2023	Brazilian Pepper	3130	5700	⁽¹⁾ 83	< 18	< 1060	< 38
T40 (Indicator)	08/15/2023	Brazilian Pepper	3290	4050	78	< 9	150	< 22
T40 (Indicator)	09/06/2023	Brazilian Pepper	3320	4770	73	< 10	155	< 26
T40 (Indicator)	10/10/2023	Brazilian Pepper	1880	4050	⁽¹⁾ 81	< 795	< 29	< 308
T40 (Indicator)	11/02/2023	Brazilian Pepper	2330	3840	⁽¹⁾ 97	< 851	< 27	< 329
T40 (Indicator)	12/06/2023	Brazilian Pepper	1850	6040	< 25	< 1230	< 37	< 510
140 (Indicator)	12/00/2023	Brazilian i eppei	1000	00+0	\ 20	1200	\ 01	\ 010
T41(Indicator)	01/17/2023	Brazilian Pepper	545	1830	< 6	< 252	< 9	< 106
T41(Indicator)	02/13/2023	Brazilian Pepper	1680	4020	< 15	< 690	< 24	< 283
T41(Indicator)	03/06/2023	Brazilian Pepper	1170	4090	< 22	< 1010	< 33	< 417
T41(Indicator)	04/03/2023	Brazilian Pepper	1640	4890	< 19	< 1220	< 38	< 525
T41(Indicator)	05/01/2023	Brazilian Pepper	1990	5530	< 21	1590	< 47	< 568
T41(Indicator)	06/05/2023	Brazilian Pepper	1800	4370	17	< 896	< 32	< 363
T41(Indicator)	07/21/2023	Brazilian Pepper	2070	4270	26	< 18	< 1030	< 32
T41(Indicator)	08/15/2023	Brazilian Pepper	2780	6230	< 19	< 19	< 138	< 33
T41(Indicator)	09/06/2023	Brazilian Pepper	1320	5050	27	< 15	< 877	< 34
T41(Indicator)	10/10/2023	Brazilian Pepper	1580	5240	< 12	< 57	< 22	< 245
T41(Indicator)	11/02/2023	Brazilian Pepper	894	2430	19	< 902	< 30	< 344
T41(Indicator)	12/06/2023	Brazilian Pepper	2130	5260	55	< 1430	< 34	< 447
T67 (Control)	01/17/2023	Brazilian Pepper	1200	6840	< 14	< 109	< 25	< 290
T67 (Control)	02/13/2023	Brazilian Pepper	980	6180	< 19	< 967	< 32	< 450
T67 (Control)	03/06/2023	Brazilian Pepper	819	6100	< 11	< 87	< 20	< 229
T67 (Control)	04/03/2023	Brazilian Pepper	633	8380	< 13	< 112	< 26	< 310
T67 (Control)	05/02/2023	Brazilian Pepper	1020	8060	< 20	< 1260	< 42	< 525
T67 (Control)	06/05/2023	Brazilian Pepper	894	7670	< 14	< 102	< 25	< 284
T67 (Control)	07/21/2023	Brazilian Pepper	1670	3520	23	< 12	< 776	< 25
T67 (Control)	08/15/2023	Brazilian Pepper	1340	6580	< 18	< 18	< 1250	< 33
T67 (Control)	09/06/2023	Brazilian Pepper	1910	7160	< 23	< 23	< 1160	< 44
T67 (Control)	10/09/2023	Brazilian Pepper	3140	6210	25	71	< 23	< 284
T67 (Control)	11/01/2023	Brazilian Pepper	1490	1960	< 14	< 788	< 28	< 302
, ,	12/05/2023	Brazilian Pepper	1150					
T67 (Control)	12/03/2023	ы аzıнан Реррег	1150	3370	< 15	< 721	< 25	< 276

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 41 of 55
Annual Radiological Envir		

Attachment 2 Page 10 of 16

Monitoring Results Tables

Table 18: Supplemental Direct Radiation- Indicators

Ana	ılysis: Gamma D)ose		Units: μR/hr	
Station	1st Qtr 2023	2nd Qtr 2023	3rd Qtr 2023	4th Qtr 2023	Annual Mean 2023
NNW-6	3.3	3.9	3.8	3.4	3.6
NW-7	3.6	3.6	3.0	3.4	3.4
NW-8	3.4	4.0	4.0	3.0	3.6
WNW-3	3.3	4.0	4.0	3.7	3.8
WNW-6	3.7	3.0	3.4	3.1	3.3
W-8	3.5	3.0	3.0	3.6	3.3
ENE-1	2.8	3.4	3.4	3.1	3.2
T72	3.3	3.0	3.1	4.4	3.4
PTN-1 ⁽¹⁾	3.5	3.8	3.8	4.1	3.8

⁽¹⁾ Indicator station with highest annual mean.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 42 of 55		
Annual Radiological Environmental Operating Report				
Attachment 2		Page 11 of 16		

Monitoring Results Tables

Table 19: Supplemental Air Particulate - Gross Beta

	ible 19: Supplemental Air Partic lysis: Gross Beta	Units: pCi/m³
End Date	T52 (Indicator)	T56 (Indicator)
	'	· · · · · · · · · · · · · · · · · · ·
<u>LLD</u> →	0.01	0.01
01/02/2023	0.008	0.011
01/09/2023	0.011	0.008
01/16/2023	0.016	0.018
01/23/2023	0.004	0.010
01/30/2023	0.015	0.018
02/07/2023	0.008	0.010
02/15/2023	0.008	0.010
02/21/2023	0.008	0.012
02/28/2023	0.009	0.012
03/06/2023	0.011	0.014
03/13/2023	0.013	0.019
03/20/2023	0.016	0.017
03/27/2023	0.007	0.014
04/03/2023	0.011	0.011
04/10/2023	0.006	0.011
04/18/2023	0.005	0.006
04/25/2023	0.016 0.013	0.016
05/02/2023		0.013
05/09/2023	0.016	0.013
05/15/2023	0.020	0.013
05/23/2023 05/30/2023	0.014 0.009	0.011 0.008
06/05/2023 06/12/2023	0.012 0.009	0.009 0.013
06/20/2023 06/27/2023	0.009 0.011	0.011 0.007
07/06/2023	0.011	0.007
07/14/2023	0.011	0.009
07/20/2023	0.012	0.017
07/26/2023	0.012	0.025
08/02/2023	0.007	0.004
08/08/2023	0.015	0.004
08/14/2023	0.009	0.017
08/21/2023	0.010	0.010
08/29/2023	0.012	0.016
09/05/2023	0.012	0.010
09/12/2023	0.011	0.012
09/12/2023	0.009	0.015
09/26/2023	0.008	0.009
10/02/2023	0.004	0.006
10/09/2023	0.007	0.010
10/16/2023	0.014	0.014
10/23/2023	0.018	0.015
11/01/2023	0.018	0.017
11/07/2023	0.019	0.010
11/13/2023	0.006	0.005
11/20/2023	0.006	0.006
11/28/2023	0.012	0.010
12/05/2023	0.018	0.017
12/11/2023	0.019	0.022
12/19/2023	0.006	0.011
12/27/2023	0.012	0.014

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 43 of 55
Annual Radiological Environmental (Operating Report	

Attachment 2 Page 12 of 16

Monitoring Results Tables

Table 20: Supplemental Air Particulate Composite - Gamma

Analysis: Gamma Isotopic				Un	its: pCi/m³	
Location	Collection Date	Be-7	K-40	Cs-134	Cs-137	Pb-210
	REQUIRED LLD →			<u>0.05</u>	<u>0.06</u>	
T52 (Indicator)	03/27/2023	0.1030	< 0.0146	< 0.0010	< 0.0007	< 0.0283
T56 (Indicator)	03/27/2023	0.1380	< 0.0200	< 0.0011	< 0.0010	< 0.0085
T52 (Indicator)	06/27/2023	0.1280	< 0.0237	< 0.0012	< 0.0009	0.0094
T56 (Indicator)	06/27/2023	0.0857	< 0.0111	< 0.0009	< 0.0006	< 0.0294
T52 (Indicator)	09/26/2023	0.0972	< 0.0128	< 0.0011	< 0.0009	< 0.0339
T56 (Indicator)	09/26/2023	0.0888	< 0.0217	< 0.0010	< 0.0011	< 0.0085
T52 (Indicator)	12/27/2023	0.1140	< 0.0263	< 0.0022	< 0.0016	< 0.1240
T56 (Indicator)	12/27/2023	0.0837	< 0.0161	< 0.0010	< 0.0010	< 0.0064

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 44 of 55
Annual Radiological Environmental	Operating Rep	port

Attachment 2 Page 13 of 16

Monitoring Results Tables
Table 21: Supplemental Air Cartridges - Iodine-131

Table 21: Supplemental Air Cartridges - Iodine-131				
	nalysis: lodine-131	Units: pCi/m ³		
End Date	T52 (Indicator)	T56 (Indicator)		
LLD →	<u>0.07</u>	<u>0.07</u>		
01/02/2023	<0.03	<0.03		
01/09/2023	<0.03	<0.03		
01/16/2023	<0.02	<0.02		
01/23/2023	<0.02	<0.02		
01/30/2023	<0.02	<0.02		
02/07/2023	<0.02	<0.02		
02/15/2023	<0.02	<0.02		
02/21/2023	<0.02	<0.02		
02/28/2023	<0.02	<0.02		
03/06/2023	<0.02	<0.02		
03/13/2023	<0.02	<0.02		
03/20/2023	<0.03	<0.02		
03/27/2023	<0.03	<0.02		
04/03/2023	<0.04	<0.04		
04/10/2023	<0.02	<0.02		
04/18/2023	<0.02	<0.02		
04/25/2023	<0.02	<0.02		
05/02/2023	<0.02	<0.02		
05/09/2023	<0.02	<0.02		
05/15/2023	<0.02	<0.02		
05/23/2023	<0.02	<0.02		
05/30/2023	<0.02	<0.02		
06/05/2023	<0.02	<0.02		
06/12/2023	<0.02	<0.02		
06/20/2023	<0.02	<0.02		
06/27/2023	<0.02	<0.02		
07/06/2023	<0.02	<0.02		
07/14/2023	<0.02	<0.01		
07/20/2023	<0.02	<0.02		
07/26/2023	<0.02	<0.02		
08/02/2023	<0.02	<0.02		
08/08/2023	<0.02	<0.01		
08/14/2023	<0.03	<0.02		
08/21/2023	<0.03	<0.02		
08/29/2023	<0.02	<0.02		
09/05/2023	<0.01	<0.01		
09/12/2023	<0.02	<0.02		
09/19/2023	<0.04	<0.03		
09/26/2023	<0.03	<0.03		
10/02/2023	<0.02	<0.02		
10/09/2023	<0.02	<0.02		
10/16/2023	<0.02	<0.02		
10/23/2023	<0.07	<0.07		
11/01/2023	<0.01	<0.01		
11/07/2023	<0.02	<0.02		
11/13/2023	<0.02	<0.02		
11/20/2023	<0.02	<0.02		
11/28/2023	<0.02	<0.02		
12/05/2023	<0.01	<0.01		
12/11/2023	<0.01	<0.01		
12/19/2023	<0.01	<0.01		
12/27/2023	<0.02	<0.02		

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2023 Page 45 of 55 Annual Radiological Environmental Operating Report

Attachment 2 Page 14 of 16

Monitoring Results Tables

Table 22: Supplemental Surface Water - Tritium and Gamma

	Analysis:			
Location	End Date	H-3	K-40	
REQUIRE	D LLD →	3,000	-	
T08 (Indicator)	01/17/2023	3960	372	
T08 (Indicator)	02/13/2023	3197	278	
T08 (Indicator)	03/06/2023	5712	345	
T08 (Indicator)	04/03/2023	15084	288	
T08 (Indicator)	05/01/2023	24149	374	
T08 (Indicator)	06/05/2023	18215	481	
T08 (Indicator)	07/21/2023	8525	355	
T08 (Indicator)	08/15/2023	7961	354	
T08 (Indicator)	09/06/2023	8956	357	
T08 (Indicator)	10/10/2023	12904	281	
T08 (Indicator)	11/02/2023	14775	392	
T08 (Indicator)	12/06/2023	9074	349	

: Gar	nma Isotop	ic			_
	Location	End Date	H-3	K-40	
	REQUIRE	D LLD →	3,000	-	
	T75 (Indicator)	01/17/2023	< 137	< 68	
	T75 (Indicator)	02/13/2023	< 140	< 71	
	T75 (Indicator)	03/06/2023	< 135	< 41	
	T75 (Indicator)	04/03/2023	< 148	< 75	
	T75 (Indicator)	05/01/2023	< 136	< 40	
	T75 (Indicator)	06/05/2023	< 150	< 59	
	T75 (Indicator)	07/21/2023	< 141	< 76	
	T75 (Indicator)	08/15/2023	< 139	< 38	
	T75 (Indicator)	09/06/2023	< 138	< 66	
	T75 (Indicator)	10/10/2023	< 142	< 39	
	T75 (Indicator)	11/02/2023	< 137	< 64	
	T75 (Indicator)	12/06/2023	< 134	< 68	

Location	End Date	H-3	K-40
REQUIRE	3,000		
T84 (Indicator)	01/17/2023	3849	349
T84 (Indicator)	02/13/2023	4001	390
T84 (Indicator)	03/06/2023	5812	293
T84 (Indicator)	04/03/2023	14432	261
T84 (Indicator)	05/01/2023	24111	364
T84 (Indicator)	06/05/2023	18697	307
T84 (Indicator)	07/21/2023	8138	270
T84 (Indicator)	08/15/2023	10053	327
T84 (Indicator)	09/06/2023	8578	280
T84 (Indicator)	10/10/2023	13221	325
T84 (Indicator)	11/02/2023	13658	318
T84 (Indicator)	12/06/2023	9901	270

Units: pCi/L

Location	End Date	H-3	K-40
REQUIRE	D LLD →	3,000	
T97 (Indicator)	01/17/2023	3960	383
T97 (Indicator)	02/13/2023	4241	286
T97 (Indicator)	03/06/2023	5764	246
T97 (Indicator)	04/03/2023	14146	282
T97 (Indicator)	05/01/2023	24350	326
T97 (Indicator)	06/05/2023	18044	355
T97 (Indicator)	07/21/2023	8409	341
T97 (Indicator)	08/15/2023	10245	329
T97 (Indicator)	09/06/2023	8356	311
T97 (Indicator)	10/10/2023	10268	370
T97 (Indicator)	11/02/2023	13398	279
T97 (Indicator)	12/06/2023	10113	258

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 46 of 55
Annual Radiological Environmental Operating Rep	oort	

Attachment 2 Page 15 of 16

Monitoring Results Tables

Table 23: Supplemental Shoreline Sediment - Gamma

	Analysis: Gamma Isotopic				Un	its: pCi/kg (c	iry)			
Location	Collection Date	Be-7	K-40	Co-60	Cs-137	Pb-210	Ra-226	Th-232	U-235	U-238
	REQUIRED LLD →				<u>180</u>					
T01 (Indicator)	01/18/2023	< 62	< 153	< 10	< 9	343	634	< 43	40	207
T02 (Indicator)	01/18/2023	< 123	554	< 14	< 13	329	1150	< 83	73	182
T03 (Indicator)	01/18/2023	< 88	442	< 8	< 11	378	1050	< 41	< 17	< 171
T04 (Indicator)	01/18/2023	248	406	< 14	< 14	355	1120	< 67	71	273
T07 (Indicator)	01/18/2023	< 139	183	< 15	< 18	< 542	< 391	< 69	< 25	< 167
T08 (Indicator)	01/18/2023	< 119	< 162	< 11	< 12	375	1170	< 43	< 24	< 207
T10 (Indicator)	01/18/2023	< 182	596	< 16	< 19	< 1300	< 628	< 73	< 40	< 339
T84* (Indicator)	01/18/2023	< 139	471	< 15	< 16	< 647	244	< 67	< 26	< 266
T85* (Indicator)	01/18/2023	< 154	578	< 14	< 14	< 1210	939	< 69	111	457
T84* (Indicator)	08/15/2023	< 146	121	< 12	< 11	489	557	< 46	59	304
T85* (Indicator)	08/15/2023	< 196	391	< 13	< 14	< 1410	827	< 64	101	400

^{*} Note that site T84 is the same location as site T05, and site T85 is the same location as site T06.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 47 of 55	
Annual Radiological Environmental Operating Report			

Attachment 2 Page 16 of 16

Monitoring Results Tables

Table 24: Supplemental Food Crops - Gamma

Analysis: Gamma Isotopic				Uni	its: pCi/kg (wet)
Location	Collection Date	Sample Type Be-7		K-40	Cs-137	Ra-226
		REQUIRED LLD →		-	<u>80</u>	
T43 (Indicator)	01/19/2023	Corn & Green Beans	< 67	2420	< 9	< 165
T44 (Indicator)	01/19/2023	Corn & Green Beans	< 75	3280	< 6	< 231
T45 (Indicator)	02/13/2023	Corn & Green Beans	< 64	3430	< 8	< 168

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 48 of 55	
Annual Radiological Environmental Operating Report			

Attachment 3 Page 1 of 3

Interlaboratory Comparison Program Results

1.0 Summary

The Interlaboratory Comparison Program consists of participating in the DOE Mixed Analyte Performance Evaluation Program (MAPEP).

This program provides similar testing (matrices, nuclides, and levels) as the former EPA Interlaboratory Comparison Program and is referred to as the Mixed Analyte Performance Evaluation Program (MAPEP).

The samples are analyzed using the methods applicable to the REMP (gamma spectroscopy, Gross Beta, and Tritium for water).

From the MAPEP handbook:

Acceptance criteria were developed from a review of precision and accuracy data compiled by other performance evaluation programs (PEPs), the analytical methods literature, from several MAPEP pilot studies, and from what is considered reasonable, acceptable, and achievable for routine analyses among the more experienced laboratories.

The State laboratory participated in MAPEP 48 and 49. These satisfied the requirement of Control 5.3 of the ODCM for the Interlaboratory Comparison Program.

Attachment 3 Page 2 of 3 Interlaboratory Comparison Program Results

Table 25: DOE's Mixed Analyte Performance Evaluation Program (MAPEP) 48 RESULTS

Program	OE S MIIXEU AII	-	Ref.	Flag	Acceptance
status	Radionuclide	Result	Value	(Evaluation)	Range
Matrix: Ro	dF Air Filter Bq/fi	lter		,	
Required	MN54	2.133	2.14	Α	1.50 - 2.78
Required	CO57	0.618	0.661	Α	0.463 - 0.859
Required	CO60	1.003	1.05	Α	0.74 - 1.37
	ZN65	2.402	2.25	Α	1.58 - 2.93
Required	CS134	1.336	1.52	Α	1.06 - 1.98
Required	CS137	0.608	0.630	Α	0.441 - 0.819
Matrix: Grl	F Air Filter Bq/filt	ter			
Required	Gross Beta	1.361	1.49	Α	0.75 - 2.24
Required	Gross Alpha	0.984	0.97	Α	0.29 - 1.65
Matrix: Ma	aS Soil Bq/kg				
Required	K40	519	574	Α	402 - 746
	MN54	1171.67	1230	Α	861 - 1599
	CO57	562	698	Α	489 - 907
	CO60	721.17	795	Α	557 - 1034
	ZN65	962.33	990	Α	693 - 1287
	CS134	-0.54		Α	False Positive Test
Required	CS137	1.02		Α	False Positive Test
	aW Water Bq/L				
Required	H3	581.13	573	Α	401 - 745
	MN54	10.447	11.3	Α	7.9 - 14.7
	CO57	0.021		Α	False Positive Test
Required	CO60	6.531	7.24	Α	5.07 - 9.41
	ZN65	14.75	15.3	Α	10.7 - 19.9
Required	CS134	8.738	9.6	Α	6.7 - 12.5
Required	CS137	8.502	8.7	Α	6.1 - 11.3
	SR90	0.02		Α	False Positive Test
Matrix: Rd	V Vegetation, Bo	q/sample			
	MN54	8.417	8.03	Α	5.62 - 10.44
	CO57	8.031	6.93	Α	4.85 - 9.01
Required	CO60	6.604	6.51	Α	4.56 - 8.46
	ZN65	7.865	7.43	Α	5.20 - 9.66
	CS134	7.55	7.60	Α	5.32 - 9.88
Required	CS137	0.018		Α	False Positive Test

Evaluation: A = Acceptable, W = Acceptable with Warning, N = Not Acceptable, NR = Not Reported

Attachment 3 Page 3 of 3 Interlaboratory Comparison Program Results

Table 26: DOE's Mixed Analyte Performance Evaluation Program (MAPEP) 49 RESULTS

Program		Result	Ref.	Flag	Acceptance
status	Radionuclide		Value	(Evaluation)	Range
	dF Air Filter Bq/f		4 57		4.40 0.04
Required	MN54	1.577	1.57	Α	1.10 - 2.04
Required	CO57	1.582	1.63	Α	1.14 - 2.12
Required	CO60	0.025		Α	False Positive Test
	ZN65	2.027	1.89	Α	1.32 - 2.46
Required	CS134	1.549	1.60	Α	1.12 - 2.08
Required	CS137	0.046		Α	False Positive Test
	F Air Filter Bq/fil				
Required	Gross Beta	0.962	0.927	Α	0.464 - 1.391
Required	Gross Alpha	0.284	0255	Α	0.077 - 0.434
	aS Soil Bq/kg				
Required	K40	530.33	574	Α	402 - 746
	MN54	1.85		N ⁽¹⁾	False Positive Test
	CO57	927.5	1060	Α	742 - 1378
	CO60	843	898	Α	629 -1167
	ZN65	1180	1160	Α	812 - 1508
	CS134	698.04	693	Α	485 - 901
Required	CS137	1757.5	1810	Α	1267 - 2353
Matrix: M	aW Water Bq/L				
Required	H3	0.7		Α	False Positive Test
	MN54	12.1	12.7	Α	8.9 - 16.5
	CO57	17.8	19.3	Α	13.5 - 25.1
Required	CO60	0.053		Α	False Positive Test
	ZN65	19	19.1	Α	13.4 - 24.8
Required	CS134	11.074	11.3	Α	7.9 - 14.7
Required	CS137	8.62	8.7	Α	6.1 - 11.3
	SR90	7.5	7.31	Α	5.12 - 9.50
Matrix: Ro	IV Vegetation, B	q/sample:			
	MN54	2.54	2.56	Α	1.79 - 3.33
	CO57	4.463	4.24	Α	2.97 - 5.51
Required	CO60	2.627	2.79	Α	1.95 - 3.63
	ZN65	0.134		Α	False Positive Test
	CS134	4.599	4.98	Α	3.49 - 6.47
Required	CS137	-0.014		Α	False Positive Test

Evaluation: A = Acceptable, W = Acceptable with Warning, N = Not Acceptable, NR = Not Reported

A false positive test with an "A" designation flag identifies the result as less than the detectable activity, since MAPEP does not report zero values. Sensitivity Evaluation has no acceptance range but an identified value at low activity.

(1) See Attachment 1, Table 7, Samples Deviations Table, Comment 2

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 51 of 55	
Annual Radiological Environmental Operating Report			

Attachment 4 Page 1 of 4

Industry Initiative Ground Water Protection Program 2023

1.0 Description of Program

Turkey Point Nuclear maintains a sampling and analysis program to meet procedural requirements. The procedures that govern the performance are EV-AA-100-1001, *Fleet Ground Water Protection Program Implementing Guideline* and 0-ADM-654, *Ground Water Protection Program*.

The sampling frequency is quarterly; more often if conditions warrant.

Sample assay is performed by a private contractor GEL labs.

2.0 Discussion

The Turkey Point Nuclear site is surrounded on three sides by the closed cooling canal system. This canal system, in addition to being the source of tertiary cooling, is the body of water receiving permitted liquid radiological waste the canal system tritium level average was 11,498 pCi/L in 2023 with a max concentration of 24,350 pCi/L. This supports the expectation to see tritium in subsurface water collected either on-site or off-site close to the (within the Owner Controlled Area) cooling canal system. Twenty-eight (28) wells were involved in the 2023 monitoring program; some locations have multiple (two or three) depths.

Samples are analyzed for Tritium & Gamma emitters. As conditions warrant, analysis included Fe-55, Ni-63, Sr-89/90 and alpha (all were < LLD).

3.0 Results

The tritium results for the groundwater wells were from <MDA to 4,330 pCi/L. All results were less than the limits of the Offsite Dose Calculation Manual, Table 5.1-2, Reporting Levels for Radioactivity Concentrations in Environmental Samples. Storm drain outfalls occasionally are below the tidal mark of the canal and will have ingress of canal water into the storm drain. The higher levels of tritium in the storm drain section are due to the canal water ingress into the storm drain.

Tabular results follow:

Plant: Turkey Point Nuclear Units 3 & 4 Year: 2023 Page 52 of 55 Annual Radiological Environmental Operating Report

Attachment 4 Page 2 of 4

Monitoring Results Tables Table 27: Ground Water – Tritium

Analysis: Tr	itium		Units: pCi/L	
Location	First Quarter 2023 H-3	Second Quarter 2023 H-3	Third Quarter 2023 H-3	Fourth Quarter 2023 H-3
REQUIRED LLD →	<u>3,000</u>	<u>3,000</u>	<u>3,000</u>	<u>3,000</u>
PTPED-1	170	113	195	454
CD-1	365	383	216	635
P-94-2	242		283	
P-94-4	957	902	493	1030
STP-1	22		125	
PTN-MW-1s	<mdc< td=""><td></td><td><mdc< td=""><td></td></mdc<></td></mdc<>		<mdc< td=""><td></td></mdc<>	
PTN-MW-1i	344		<mdc< td=""><td></td></mdc<>	
PTN-MW-1d	795		422	
PTN-MW-2s	9		<mdc< td=""><td></td></mdc<>	
PTN-MW-3s	4		19.3	
PTN-MW-4s	<mdc< td=""><td>150</td><td><mdc< td=""><td>299</td></mdc<></td></mdc<>	150	<mdc< td=""><td>299</td></mdc<>	299
PTN-MW-4i	3540	<mdc< td=""><td>3470</td><td>462</td></mdc<>	3470	462
PTN-MW-4d	59	<mdc< td=""><td><mdc< td=""><td>119</td></mdc<></td></mdc<>	<mdc< td=""><td>119</td></mdc<>	119
PTN-MW-5s	91	19.7	<mdc< td=""><td>205</td></mdc<>	205
PTN-MW-5i	16	402	1150	566
PTN-MW-5d	934	767	1180	1300
PTN-MW-6SR	36.3		322	
PTN-MW-6DR	439		2.13	
PTN-MW-7s	1340	1400	926	2930
PTN-MW-7i	1530	1230	95.3	159
PTN-MW-7d	109	156	31.7	114
PTN-MW-8s	928	3200	4330	2510
PTN-MW-9s	1070	803	390	1280
PTN-MW-10s	14		<mdc< td=""><td></td></mdc<>	
PTN-MW-10i	59		44.6	
PTN-MW-10d	<mdc< td=""><td></td><td><mdc< td=""><td></td></mdc<></td></mdc<>		<mdc< td=""><td></td></mdc<>	
PTN-MW-11s	609	374	155	823
PTN-MW-12s	1050	656	1150	1530
NE StrmDrain	884		377	400
SE StrmDrain	3870	3160		
W StrmDrain	(1)	1290		
CRF StrmDrain	Dry	Dry	Dry	Dry

⁽¹⁾ Storm Drain submerged underwater at time of collection.

MDCs are calculated a-posteriori values. Target isotope was analyzed for but not detected above the MDC and LLD.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 53 of 55		
Annual Radiological Environmental Operating Report				

Attachment 4 Page 3 of 4 Industry Initiative Ground Water Protection Program 2023

D. List of wells and their locations


Well Name	Location
PTN-MW-1s PTN-MW-1i PTN-MW-1d	Northeast of Switch Yard, South of entrance road to Fossil Plant
PTN-MW-2s	South Switch Yard by parking lot
PTN-MW-3s	Northeast of new Issues Warehouse
PTN-MW-4s PTN-MW-4i PTN-MW-4d	SW corner of parking lot South of Training Bldg.
PTN-MW-5s PTN-MW-5i PTN-MW-5d	SW of CRF, by canal
PTN-MW-6SR PTN-MW-6DR	NE of site in the berm for fossil oil tanks
PTN-MW-7s PTN-MW-7i PTN-MW-7d	NE of RCA, by Neutralization Tank
PTN-MW-8s	Near U3 RWST
PTN-MW-9s	Near U4 RWST
PTN-MW-10s PTN-MW-10i PTN-MW-10d	SE of Radwaste Bldg. by S/G Bldg.
PTN-MW-11s	South of truck entrance to Rad Waste Bldg.
PTN-MW-12s	West of Condenser Polisher road
STP-1	West of Maintenance Bldg. on corner or road into parking lot
P-94-4	East of Dressout Building, under delay fence
P-94-2	By Neutralization Basin, East of the RCA
CD-1	By Neutralization Basin, East of the RCA
PTPED-1	By Neutralization Basin, East of the RCA

Note: s, i and d refer to well depth: shallow - 20 ft., intermediate - 40 ft. and deep - 60 ft Maps depicting the well locations follow.

Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 54 of 55
Annual Radiological Environmental Operating Report		

Attachment 4 Page 4 of 4 Industry Initiative Ground Water Protection Program 2023

Figure 5: Onsite Tritium Monitoring Wells



Plant: Turkey Point Nuclear Units 3 & 4	Year: 2023	Page 55 of 55	
Annual Radiological Environmental Operating Report			

Attachment 5 Page 1 of 1

ERRATA Data 2023

Significant errors should be corrected within one year of discovery, and the correction may be submitted with the next (normally scheduled) submittal of the AREOR as follows. A brief narrative explanation of the errors should be included in, "Errata/Corrections to Previous AREORs," "Supplemental Information." The narrative should include a statement that the affected pages, in their entirety, are included as attachments to the AREOR. Additionally, the affected, corrected pages, in their entirety, should be submitted as an attachment to the AREOR. The corrected pages should reference the affected calendar year and should contain revision bars in the margins of the page to indicate the locations of the changes. If submitting corrections to multiple AREORs, make a separate attachment for each of the affected years. Other methods of correcting previous AREORs may be used provided the corrections are clearly and completely described.

Significant errors include:

- Inaccurate reporting of samples collected and analyzed.
- Inaccurate reporting of sample results.
- Omissions that impede the NRC's ability to adequately assess the information supplied by the licensee, or other errors that alter the intent of the report.

1.0 List of changes from the 2022 AREOR

There were no corrections to previous reports found in 2023.